

AD-A063 124

GAI CONSULTANTS INC MONROEVILLE PA

F/G 13/2

NATIONAL DAM INSPECTION PROGRAM. LATROBE RESERVOIR NDI NUMBER P--ETC(U)


JUN 78 B M MIHALCIN


DACW31-78-C-0052

NL

UNCLASSIFIED

1 OF 1  
AD  
A063 124





LEVEL IV

1  
NW

ADA063124

OHIO RIVER BASIN  
TROUT RUN, WESTMORELAND COUNTY  
PENNSYLVANIA

LATROBE RESERVOIR  
NDI Pa - 479  
*Number*  
Ohio River Basin. Trout Run, Westermoreland  
County, Pennsylvania.

DDC FILE COPY

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

*Bernard M. Michalski*



DEPARTMENT OF THE ARMY  
Approved for public release  
Distribution unlimited

DEPARTMENT OF THE ARMY  
Baltimore District, Corps of Engineers  
Baltimore, Maryland 21242

⑤ DACW 41-13-C-1052

PREPARED BY

CAI CONSULTANTS, INC.  
20 HENRY ROAD  
MONROEVILLE, PENNSYLVANIA 15146

DDC  
RECEIVED  
JAN 1973  
OFFICE

# LEVEL II



## PHASE I REPORT National Dam Inspection Program

Latrobe Reservoir

Pennsylvania

Westmoreland County

Trout Run

16 May 1978 (visual inspection)

Inspection Team - GAI Consultants, Inc.  
570 Beatty Road  
Monroeville, Pennsylvania 15146

Based on a visual inspection, past performance, and available engineering data, the dam and its appurtenances appear to be in very good condition. The structure was rebuilt in 1958 when the embankment was modified to increase the available storage. The initial embankment, which was constructed in 1920 now forms part of the upstream portion of the dam.

The project is capable of passing the PMF (recommended spillway design flood) without overtopping.

Runoff had become impounded on a bench at the midpoint of the structure because of poor drainage. It is recommended that the owner be required to provide positive drainage from all points on the bench so as to prevent the ponding of water on the downstream face.

It is also recommended that a formal warning system be developed in order to provide for the safe evacuation of downstream inhabitants, should the need arise.

The dam should also be inspected on a yearly basis by qualified personnel to ensure that conditions at the facility do not deteriorate.

ACCESSION for	
DTIS	White Section <input checked="" type="checkbox"/>
DDC	Buff Section <input type="checkbox"/>
UNANNOUNCED	<input type="checkbox"/>
JUSTIFICATION	
Per DDC Form 50	
or on file	
DISTRIBUTION/AVAILABILITY CODES	
Dist.	AVAIL. and/or SPECIAL
A	

Contract DACW31-78-C-0052

DDC  
RECEIVED  
JAN 11 1979  
D

DISTRIBUTION STATEMENT A  
Approved for public release;  
Distribution Unlimited

i  
79 01 10 044




GAI Consultants, Inc.

Approved:

Bernard M. Mihalcin  
Bernard M. Mihalcin

G. K. Withers  
G. K. WITHERS  
Colonel. Corps of Engineers  
District Engineer



Date: July 7, 1978

Date: 20 J 1 78

*RECEIVED*  
JAN 12 1978  
D D C  
REGISTERED

Approved by  
District Engineer

NO. 100	
NO. 200	
NO. 300	
NO. 400	
NO. 500	
NO. 600	
NO. 700	
NO. 800	
NO. 900	
NO. 1000	
NO. 1100	
NO. 1200	
NO. 1300	
NO. 1400	
NO. 1500	



Overview Photograph of Latrobe Reservoir Taken from the Right Abutment.

## TABLE OF CONTENTS

	<u>Page</u>
SYNOPSIS . . . . .	i
OVERVIEW PHOTOGRAPH. . . . .	iii
TABLE OF CONTENTS. . . . .	iv
SECTION 1 - GENERAL INFORMATION. . . . .	1
1.0 Authority. . . . .	1
1.1 Purpose. . . . .	1
1.2 Description of Project . . . . .	1
1.3 Pertinent Data . . . . .	3
SECTION 2 - ENGINEERING DATA . . . . .	6
2.1 Design . . . . .	6
2.2 Construction Records . . . . .	7
2.3 Operation. . . . .	7
2.4 Other Investigations . . . . .	7
2.5 Evaluation . . . . .	7
SECTION 3 - VISUAL INSPECTION. . . . .	8
3.1 Observations . . . . .	8
3.2 Evaluation . . . . .	9
SECTION 4 - OPERATIONAL PROCEDURES . . . . .	10
4.1 Normal Operating Procedure . . . . .	10
4.2 Maintenance of Dam . . . . .	10
4.3 Maintenance of Operating Facilities. . . . .	10
4.4 Warning Systems in Effect. . . . .	10
4.5 Evaluation . . . . .	10
SECTION 5 - HYDROLOGIC/HYDRAULIC EVALUATION. . . . .	11
5.1 Design Data. . . . .	11
5.2 Experience Data. . . . .	11
5.3 Visual Observations. . . . .	11
5.4 Overtopping Potential. . . . .	11
SECTION 6 - EVALUATION OF STRUCTURAL INTEGRITY . . . . .	13
6.1 Visual Observations. . . . .	13
6.2 Design and Construction Techniques . . . . .	13
6.3 Past Performance . . . . .	13
6.4 Seismic Stability. . . . .	13
SECTION 7 - ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES. . . . .	14
7.1 Dam Assessment . . . . .	14
7.2 Recommendations/Remedial Measures. . . . .	14

**TABLE OF CONTENTS**

**APPENDIX A - CHECK LIST - ENGINEERING DATA**

**APPENDIX B - CHECK LIST - VISUAL INSPECTION**

**APPENDIX C - HYDRAULICS AND HYDROLOGY CALCULATIONS**

**APPENDIX D - PHOTOGRAPHS**

**APPENDIX E - GEOLOGY**

**APPENDIX F - FIGURES**

**APPENDIX G - REGIONAL VICINITY MAP**



PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM  
LATROBE RESERVOIR  
NDI# PA-479, PENNDR# 65-66

SECTION 1  
GENERAL INFORMATION

*ABSTRACT*  
1.0 Authority.

The Dam Inspection Act, Public Law 92-367 authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.

1.1 Purpose.

The purpose is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project. *ABSTRACT*

a. Dam and Appurtenances. Latrobe Reservoir Dam (Trout Run Dam, as it is locally known), is an earthen embankment approximately 775 feet in length with a maximum height of 86 feet. A concrete chute spillway is located along the left end of the embankment. The spillway is a gravity type structure with an ogee-shaped crest and channel length of approximately 400 feet. A single 24-inch cast iron supply line constitutes the outlet works. It originates and is gated at the reservoir tower and runs under the embankment exiting to the right of the downstream channel. At a point approximately 250 feet downstream a 24-inch blow-off is connected to the supply line. No walkway has been provided, thus the reservoir tower and equipment therein are accessible only by boat.

b. Location. Latrobe Reservoir is located approximately 4 miles southeast of Latrobe, Westmoreland County, Pennsylvania. The reservoir dam is situated at the southern end of the reservoir approximately 5,000 feet from the confluence of Trout Run and Coalpit Run, near the intersection of U. S. Routes 30 and 259. The dam, reservoir, and watershed are contained within the Derry and Wilpen 7.5 minute quadrangles. The coordinates of the dam are N40° 16' 28", W79°, 16' 17".

c. Size Classification. Intermediate (86 feet high, 3,650 acre-feet storage capacity at spillway crest).

d. Hazard Classification. High (see Section 3.1.c).



e. Ownership. Municipal Authority of the Borough of Latrobe.

f. Purpose of Dam. The dam serves as a storage reservoir for the water supply system of the Borough of Latrobe. Recreational use is prohibited.

g. Historical Data. The original facility was designed and constructed by J. G. White Engineering Corporation of New York, New York, and completed in 1920. Designed to serve as a storage reservoir for the water supply system of the Borough of Latrobe, it has been owned and operated since construction by the Municipal Authority of the Borough of Latrobe. The original dam was an earth embankment 51 feet high, 580 feet long, with a reservoir capacity of 360 million gallons and it was equipped with a concrete spillway having a capacity of 2,900 cfs.

Inspection reports compiled every two years by the Pennsylvania Water Commission indicated a plethora of minor problems at the original facility between 1920 and 1958.

As early as May 1920, seepage was detected at several locations along the downstream slope confirming the fears of inspecting engineers and causing much concern to the local citizenry. Although the Pennsylvania Water Commission was convinced at this time that the structure was unsafe, there was disagreement as to the nature of the leakage.

Nevertheless, in December 1920, it was recommended that the structure be strengthened by superimposing a drained earthfill upon the downstream part of the dam. Repairs were instituted the following year. Additional repairs to the spillway were made during the following years.

The firm of Gannett, Fleming, Corddry, and Carpenter, Inc., of Harrisburg, Pennsylvania, was retained in 1958 to prepare plans for upgrading the facility. Included in their design were an extensive grouting program; a plan to increase the dam height by 35 feet to elevation 1256; demolishing, removing, and replacing the old spillway; and modifying the control tower. Construction ensued and the old Latrobe Reservoir Dam currently forms the upstream toe of the "new" structure (see Figure 3 in Appendix E).

PennDER inspection reports compiled for the present facility in 1966 and again in 1971 indicate that the structure was in a good condition.

1.3 Pertinent Data.

a. Drainage Area. 5.66 square miles.

b. Discharge at Dam Site. According to Ed McClellam, Trout Run Dam superintendent for the past 30 years, discharge records are not kept at this facility. However, he recalls that the highest level, achieved during his years as superintendent, was approximately 3 feet at the spillway crest in June 1972.

The capacity of the outlet works at maximum pool level (elevation 1256) are as follows:

24-inch cast iron outlet pipe - 75 cfs.

Spillway - 8,400 cfs.

c. Elevation (feet above mean sea level).

Top of Dam - 1256.

Maximum Pool Design Surcharge - Not known.

Maximum Pool of Record - 1243 (verbal).

Normal Pool (spillway crest) - 1240.

Upstream Portal Invert Outlet Conduit - 1169.

Downstream Portal Invert Outlet Conduit - 1168.

Streambed at Center Line of Dam - 1168.

Maximum Tailwater - Not known.

d. Reservoir.

Length of Maximum Pool  $\approx$  1.3 miles (elevation 1256).

Length of Normal Pool - 1.2 miles (elevation 1240).

e. Storage (acre-feet).

Spillway Crest - 3650.

Top of Dam - 6250.

Design Surcharge - Not known.

f. Reservoir Surface (acres).

Top of Dam  $\approx$  160.

Maximum Pool - Maximum design pool not known.

Spillway Crest  $\approx$  125.

g. Dam.

Type - Rolled earthfill.

Length - 600 feet.

Height - 86 feet maximum.

Top Width - 20 feet.

Side Slopes - Lower Downstream 3H:1V  
Upper Downstream 2.5H:1V  
Upstream 2.5H:1V

Zoning - Compacted impervious selected mixture of clay, sand, and gravel increasing in permeability toward outer slopes, with riprap on upstream face, and rock toe downstream. A sand and gravel filter blanket is provided within and beneath the embankment (see Figure 3).

Impervious Core - Not applicable.

Cutoff - A cutoff trench located at the downstream toe of the original embankment was carried an average depth of 15 feet below the toe for the entire length of the dam and into both abutments.

Grout Curtain - A grouting program was carried out as part of the latest construction in 1958. Grout holes (approximately 60 feet deep) were drilled along the embankment centerline and extend approximately 60 feet beyond the embankment--abutment contacts. The best record available on the grout program is contained in the construction progress reports that were compiled every two weeks during construction in 1959 by Gannett, Fleming, Corddry, and Carpenter, Inc.

h. Outlet Conduit.

Type - 24-inch cast iron supply pipe serving the Borough of Latrobe has its inlet at reservoir intake tower. Approximately 250 feet downstream, the pipe is connected to a valved 24-inch cast iron blow-off.



Closure - Sluice gates are controlled in the gate house.

Access - Intake tower accessible only by boat; inlet submerged.

Regulating Facilities - Can be regulated in the gate house and at gate valve 250 feet downstream.

i. Spillway.

Type - Concrete channel with ogee-crested weir.

Weir Length - 35 feet.

Channel Length  $\approx$  400 feet.

Crest Elevation - 1240.

Upstream Channel - Curved natural rockbed channel approximately 100 feet in length.

Downstream Channel - Approximate 15 percent slope at top that steepens as it reaches a stilling basin which is 42 feet wide, 60 feet long, and 6.5 feet deep.

j. Regulating Outlets. None in spillway. Low flow can be controlled through blow-off line.

SECTION 2  
ENGINEERING DATA

2.1 Design.

a. Design Data Availability and Sources.

1. Hydrology and Hydraulics. No design reports are available.

2. Embankment. A copy of the specifications used during the 1958 reconstruction of the structure and the design drawings are available from both the owner and PennDER files.

3. Appurtenant Structures. Same as 2 (above).

b. Design Features.

1. Embankment. Available contract documents and historical data indicate that the present Latrobe Reservoir Embankment was constructed of rolled earthfill. The original embankment which was constructed in 1920 was incorporated into the current structure and currently functions as a part of the upstream portion of the dam (see Figure 3). Contract documents indicate that a cutoff trench was excavated to rock and that a concrete cutoff wall and grout curtain were constructed beneath the present structure.

The upstream face of the dam is at a slope of 2.5H to 1V and is faced with 9 inches of gravel covered by a well graded durable sandstone riprap. The downstream face of the structure lies at a slope of 3H to 1V and is mantled with crown vetch. Near the midpoint of the downstream face, a 10-foot wide berm was constructed to direct flow into lined diversion ditches on the embankment-natural slope interface. The dam is provided with a rock toe which drains a sand and gravel filter blanket contained within and beneath the embankment.

2. Appurtenant Structures.

a) Spillway. The primary discharge is a reinforced concrete ogee spillway located adjacent to the left abutment (see Photographs 2 and 6).

The ogee spillway foundation is keyed into rock on the left abutment and is shown on the attached Figure 4.



b) 24-Inch Supply Pipe. A 24-inch cast iron supply pipe, encased in concrete within the new structure, passes beneath the dam to a point a few hundred feet downstream. A valve box is located at this point which serves to utilize the supply line as a blow-off pipe enabling the water authority to discharge water into the downstream drainage system (see Photograph 5).

c) Gate House. The original gate house was modified in 1958 in order to raise the structure and permit the drawing of water through four gates located at different elevations within the reservoir. The gates discharge water directly into the 24-inch supply line. Details of the modifications of the gate house are shown on Figure 5.

## 2.2 Construction Records.

Progress reports are available for both the original and the modified embankments. The latter reports were issued to PennDER and document the progress made on a monthly basis. These data are available in PennDER files.

## 2.3 Operational Records.

No operational records are available.

## 2.4 Other Investigations.

Several State inspection reports are available from PennDER files, however, the majority document problems and conditions at the original structure. Two post construction reports concerning the new structure are available from PennDER files and are dated 1964 and 1971.

## 2.5 Evaluation.

The information available is considered sufficient to make an accurate assessment of the structure.

SECTION 3  
VISUAL INSPECTION

3.1 Observations.

a. General. The general appearance of the structure and the related appurtenances suggests that the dam was well engineered, is well maintained, and is in satisfactory condition.

b. Embankment. The upstream slope of the dam is mantled with a well graded, durable, sandstone which was apparently dumped in place. The downstream dam slope is thickly vegetated (crown vetch) and is provided with a system of concrete and/or stone-lined diversion ditches which discharge at the rock toe. No indications of seepage through the embankment slope were observed during the field investigation. There were no indications of lush vegetation on the downstream face nor did we note any flora which is selective for damp or swampy environs. Some water was noted seeping through the rock outcrop just above the bench level on the right abutment which discharges some flow into the diversion ditch. It is possible that the flow is not related to impoundment levels as other springs were noted through similar rock strata above the impoundment level on the left abutment.

c. Appurtenant Structures.

1. Spillway. The spillway, spillway abutments, discharge channel, and plunge pool all appeared to be in excellent condition, except for some minor temperature and/or shrinkage cracking.

2. Gate House, Valves, and Supply Line. Access to the gate house is by boat, which was not available during our inspection, consequently, we were not able to assess condition of the mechanical systems within the gate house. According to a representative of the Water Authority the system is in good working order. The downstream gate valve which regulates flow from the supply line to a 24-inch blow-off line was observed (see Photograph 5). The valve is located in a concrete pit approximately 250 feet downstream of the dam. The valve was greased and appeared in good order.

3. Reservoir Area. The slopes adjoining the reservoir were moderate to steep and densely wooded. No signs of slope distress were observed with the exception of a portion of a road fill on the northeast side of the reservoir (see Photograph 7). A portion of the raised

and/or relocated county road in this area has slumped into the reservoir. However, since the total slumped volume of fill at this point is small, this condition is not considered to be serious.

4. Downstream Channel. The area immediately downstream of the dam is characterized as a broad (~600 feet wide) thinly vegetated valley containing Trout Run. The stream passes beneath a two-lane bridge approximately 4,000 feet downstream of the dam before emptying into Coalpit Run a first order tributary of Loyalhanna Creek.

### 3.2 Evaluation.

As shown on the Regional Vicinity Map (Appendix G) approximately six (6) homes located along Trout Run just downstream of the dam would be inundated if the dam were to fail. Consequently, the hazard classification is high.



SECTION 4  
OPERATIONAL PROCEDURES

4.1 Normal Operational Procedure.

According to water company personnel, there are no established operational procedures at the facility. Excess inflow passes over the spillway and discharges into the Trout Run channel. The only other outlet serving the structure is a 24-inch supply line which is used to convey water to the Borough of Latrobe. This outlet can be readily regulated to pass water through a 24-inch blow-off pipe directly into the Trout Run channel.

4.2 Maintenance of Dam.

The dam crest is periodically mowed by water company personnel. The downstream slope is covered with crown vetch and is reportedly cleared of brush yearly.

4.3 Maintenance of Operating Facilities.

The water company superintendent stated that the valves are lubricated yearly and that the blow-off is opened every few years to insure that it is operating properly.

4.4 Warning Systems.

There are no formal warning systems in effect.

4.5 Evaluation.

The overall appearance of the structure suggests that it is well maintained.

SECTION 5  
HYDROLOGIC/HYDRAULIC EVALUATION

5.1 Design Data.

No hydrologic or hydraulic design data was available. This information was reportedly destroyed while in storage at Harrisburg, Pennsylvania, during the flood of June 1972.

5.2 Experience Data.

No data pertinent to spillway evaluation are available from past performance.

5.3 Visual Observations

The dam and its appurtenances appeared to be in very satisfactory condition.

5.4 Overtopping Potential and Spillway Adequacy.

The ratio "PMF Peak Flow/Drainage Area" was determined from an empirical curve supplied by the Corps of Engineers, Baltimore District. The curve used was the Ohio River Basin Curve (see calculations in Appendix C). Based on this curve and a drainage area of 5.66 square miles, Peak PMF  $Q/A = 1,680$  cfs/sq. mi., and Peak PMF  $Q = 9,509$  cfs. The size category is "intermediate" and the hazard rating "high". Consequently, the SDF is the PMF ("Recommended Guidelines for the Inspection of Dam").

Calculations were performed to evaluate the overtopping potential using spillway and blow-off line capacities during the PMF.

Based on this curve, the inflow volume calculated for the design storm is equal to 16,112 acre-feet. This corresponds to an overconservative estimate of runoff and, as a consequence, an inflow volume based on 26 inches of runoff, that is 7,849 acre-feet, was used in subsequent calculations.

The spillway has a maximum discharge capacity equivalent to 8,400 cfs. This coupled with the maximum discharge capacity of the outlet works ( $\approx 75$  cfs) yields a total maximum discharge capacity approximately equal to 8,475 cfs. A comparison of peak inflow to the maximum discharge shows that some storage volume is required.



Based on normal pool elevation 1240 and top of dam elevation 1256, the available storage is found to be 2,240 acre-feet which is greater than the volume of storage required of 863 acre-feet. Consequently, the embankment would not be overtopped during the PMF and the spillway capacity is considered adequate (see Appendix C).

SECTION 6  
EVALUATION OF STRUCTURAL INTEGRITY

6.1 Visual Observations.

a. Embankment. Based on visual observations, the embankment appeared to be in excellent condition. Aside from a small amount of runoff, which was ponded on a bench at the downstream embankment midpoint, the drainage system seemed to be in good order.

b. Appurtenant Structures. Based on the visual inspection, the spillway structure appeared to be in excellent condition.

6.2 Design and Construction Techniques.

a. Embankment. Specifications and construction drawings indicate the the embankment is well engineered. Favorable embankment slopes, a substantial grouting program, a layered blanket drain, rock toe, and lined diversion ditches suggest adequate stability and safety features.

b. Appurtenant Structures. Specifications and construction drawings also indicate well designed outlet and discharge facilities. The spillway is keyed into rock, anchored, drained and of adequate capacity. The outlet pipe is encased in concrete through the new embankment and can be controlled from the upstream end.

6.3 Past Performance.

No formal records of past performance were available. The Agnes flood of 1972 which was reportedly passed with a 3-foot spillway level did no apparent damage.

6.4 Seismic Stability.

The dam is located in Seismic Zone No. 1 and is thus subject to minor earthquake induced forces. Since the embankment is broad-based, well drained, and constructed of residual soils it is believed that the static stability is sufficient to withstand minor earthquake induced dynamic forces. However, no calculations or investigations, etc., were performed to confirm this belief.

SECTION 7  
ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES

7.1 Dam Assessment.

a. Safety. The visual inspection and operational history of the dam since its reconstruction in 1958 indicate that the structure is in very good condition. Review of available engineering data indicate that the structure and its appurtenances were designed and constructed in accordance with accepted engineering practice. The only deficiency noted at the time of inspection was that runoff had become impounded on the downstream face of the dam because of poor drainage on the bench located about midway between the toe and dam crest. A design deficiency (in retrospect) is the lack of instrumentation (settlement monitors, piezometers, etc.) that would have been prudent during the time of initial fillup.

The hydraulic and hydrologic procedures adopted for our analysis indicate that the spillway will pass and/or contain the PMF.

b. Adequacy of Information. Although most of the files pertaining to the design of this dam were lost during the flood of June 1972, contract specifications and drawings were available for review. These are considered sufficient to make a reasonable assessment of the adequacy of the facility.

c. Urgency. It is suggested that the remedial measures listed below be implemented as soon as practical.

d. Necessity for Additional Investigations. Because of the good overall appearance of the structure, additional investigations are not deemed necessary at this time.

7.2 Recommendations/Remedial Measures.

a. It is recommended that remedial measures be implemented to provide positive drainage on the bench so as to prevent runoff from accumulating on the downstream dam face.

b. It is recommended that a formal warning system be implemented to protect the inhabitants residing on the floodplain immediately downstream of the dam.

c. It is recommended that the dam be inspected on a yearly basis to check for changed conditions.

APPENDIX A  
CHECK LIST - ENGINEERING DATA



CHECK LIST  
 ENGINEERING DATA  
 DESIGN, CONSTRUCTION, OPERATION  
 PHASE I

NAME OF DAM Latrobe Reservoir - Locally  
 known as "Trout Run Reservoir"

ID # PA-479

ITEM REMARKS SHEET 1

**AS-BUILT DRAWINGS**

Available from owner as well as PennDER files - These drawings only cover the reconstruction which took place in 1958.

**REGIONAL VICINITY MAP**

See Section F of the report.

**CONSTRUCTION HISTORY**

A partial history is available from PennDER - photographs were supplied by both the owner and PennDER.

**TYPICAL SECTIONS OF DAM**

Drawing 6 - General Plan  
 Drawing 7 - Typical Sections and Details

**OUTLETS - PLAN** Drawing 11 - Tower and Conduit Details, Supply Line Blow-off.

- DETAILS Drawing 11 - Conduit Location Profile; 24-inch Blow-off detail; Miscellaneous Details.
- DISCHARGE RATINGS None

**RAINFALL/RESERVOIR RECORDS**

Rainfall records from 1956 to present along with reservoir levels from 1909 to present are available at Latrobe Reservoir pump house.



ITEM

REMARKS

ID # 479

SHEET 2

DESIGN REPORTS

Not available.

Note: Many of the reports and much of the data for this project were destroyed by the flood of June 1972, while in storage at Harrisburg, Pennsylvania, according to Gannett, Fleming, GEOLOGY REPORTS Corddry, and Carpenter, Inc.

Not available.

DESIGN COMPUTATIONS  
HYDROLOGY & HYDRAULICS  
DAM STABILITY  
SEEPAGE STUDIES

Not available.

MATERIALS INVESTIGATIONS  
BORING RECORDS  
LABORATORY  
FIELD

Drawings 3, 4, and 5 - Foundation Exploration Logs I, II, III.

POST-CONSTRUCTION SURVEYS OF DAM

None.

BORROW SOURCES

Drawing 2 - Location Plan.

**MONITORING SYSTEMS**

No formal system, manager inspects yearly.

**MODIFICATIONS**

Not since 1958.

**HIGH POOL RECORDS**

Daily records available, but maximum not known.

**POST CONSTRUCTION ENGINEERING  
STUDIES AND REPORTS**

None.

**PRIOR ACCIDENTS OR FAILURE OF DAM  
DESCRIPTION  
REPORTS**

None according to available records.

**MAINTENANCE  
OPERATION  
RECORDS**

Formal records not available. Periodic maintenance is carried out. Scuba investigation 5 years ago revealed no siltation against screen intakes. Yearly clearing and grubbing of vegetation on the embankment is maintained.

ITEM

REMARKS

ID # 479

SHEET 4

SPILLWAY PLAN Drawing 6 - General Plan

SECTIONS Drawing 12 - Spillway Chute, Stilling Basin.

DETAILS  
Drawing 13 - Approach and Wall Details.  
Drawing 14 - Stilling Basin Details.  
Drawing 15 - Wall Details.  
Drawing 16 - Wall Details.

OPERATING EQUIPMENT  
PLANS & DETAILS

Drawings 9, 10, and 11 - Tower and Conduit Details.  
Manufacturer's Shop Drawings - Not available.

NDI# PA-479  
ID # PennDER# 65-66

CHECK LIST  
HYDROLOGIC AND HYDRAULIC  
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 5.66 square miles.

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 1240.

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): 1256.

ELEVATION MAXIMUM DESIGN POOL: Not known.

ELEVATION TOP DAM: 1256.

SPILLWAY DATA:

- a. Crest Elevation 1240.
- b. Type Concrete ogee.
- c. Weir Length 35
- d. Channel Length ~400 feet.
- e. Location Spillover Left abutment.
- f. Number and Type of Gates NONE.

OUTLET WORKS:

- a. Type One 24-inch supply pipe with 24-inch blow-off.
- b. Location see below.
- c. Entrance Inverts elevation 1169 - Located beneath tower.
- d. Exit Inverts elevation 1168 - Located approx. 250 feet downstream.
- e. Emergency Draindown Facilities 24-inch blow-off.

HYDROMETEOROLOGICAL GAGES:

- a. Type Raingage, staff gage.
- b. Location Latrobe Pump Station, Latrobe Reservoir Tower.
- c. Records Rainfall post 1956; water level post 1090; located at pump house.

MAXIMUM NON-DAMAGING DISCHARGE: Not known.



APPENDIX B

CHECK LIST - VISUAL INSPECTION

CHECK LIST  
VISUAL INSPECTION  
PHASE 1

DAM NAME Latrobe Reservoir COUNTY Westmoreland STATE Pa. ID # Pa-479

TYPE OF DAM Earthfill w/Rock Toe HAZARD CATEGORY High

DATE(S) INSPECTION 16 May 78 WEATHER Overcast TEMPERATURE 50°-60°

POOL ELEVATION AT TIME OF INSPECTION 1240.5 M.S.L. TAILWATER AT TIME OF INSPECTION 1167.5 M.S.L.

INSPECTION PERSONNEL:

GAI

B. Mihalcin

J. P. Nairn

K. H. Khilji

D. Bonk

Owner's Representatives

Ed. McCallen - entire visit

J. Durco (Mgr.) - brief visit

D. Johnson (operations) - "

K. H. Khilji

RECORDER

Tom Gray (chemist) - brief  
vis:

EMBANKMENT

ID# Pa-479

Sheet 1

REMARKS OR RECOMMENDATIONS

VISUAL EXAMINATION OF

SURFACE CRACKS

None observed.

UNUSUAL MOVEMENT OR  
CRACKING AT OR BEYOND  
THE TOE

None observed.

SLOUGHING OR EROSION OF  
EMBANKMENT AND ABUTMENT  
SLOPES

Minor rockfall at downstream right abutment - no problem.

VERTICAL AND HORIZONTAL  
ALIGNMENT OF THE CREST

Smooth -- No unusual settlement.

RIPRAP FAILURES

None observed.

Well-graded, durable riprap; 2 to 3 ft. maximum particle size.

EMBANKMENT

ID # Pa-479

SHEET 2

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

JUNCTION OF EMBANKMENT  
AND ABUTMENT, SPILLWAY  
AND DAM

Minor rockfall on downstream slope of right abutment. Otherwise, in excellent condition

ANY NOTICEABLE SEEPAGE

Seepage visible through natural slope at right abutment below bench level.  
5 to 10 gpm flow -- could be from existing spring.

STAFF GAGE AND RECORDER

Staff gage on gate house tower leg. Not legible.

DRAINS

Minor accumulation of water on bench -- bench too flat.  
Paved slope drains - OK.  
Toe drain (Rock toe) - functioning OK.



REMARKS OR RECOMMENDATIONS

OBSERVATIONS

VISUAL EXAMINATION OF

CRACKING AND SPALLING OF  
CONCRETE SURFACES IN  
OUTLET CONDUIT

Not applicable - outlet through cast iron blow-off pipe.

INTAKE STRUCTURE

Gate House (Control Tower) visible but not accessible by foot.  
Needs minor maintenance, possibly bridge for quick access.

OUTLET STRUCTURE

24-inch blow-off line, valve box, and outlet end in good condition.  
Owner operated valve in 1977 to verify operability.

OUTLET CHANNEL

Blow-off valve discharges into stream. No problem.

EMERGENCY GATE

Inaccessible to inspection crew.

UNGATED SPILLWAY

ID # Pa-479

SHEET 4

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

CONCRETE WEIR

Excellent condition. Minor spalling at 2 construction joints along base.  
Owner to patch this year.

APPROACH CHANNEL

No problems.

DISCHARGE CHANNEL

Stilling basin & downstream area in good to excellent condition.

BRIDGE AND PIERS

None.

VISUAL EXAMINATION OBSERVATIONS REMARKS OR RECOMMENDATIONS

MONUMENTATION/SURVEYS  
None observed.

OBSERVATION WELLS  
None.

WEIRS  
No weirs on discharge or drainage facilities.

PIEZOMETERS  
None.

OTHERS

RESERVOIR

ID # Pa-479

SHEET 6

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

SLOPES

Gentle to moderate. Mostly wooded around reservoir. Steep (1:1) slope on relocated road embankment (probably rockfill from adjacent cut). Small slide on road embankment.

SEDIMENTATION

Minor.



DOWNSTREAM CHANNEL

ID # Pa-479

SHEET 7

VISUAL EXAMINATION OF OBSERVATIONS REMARKS OR RECOMMENDATIONS

CONDITION

(OBSTRUCTIONS,  
DEBRIS, ETC.)

Natural channel with thick vegetation.

SLOPES

Gentle downstream slope. With moderate to steep side slopes.

APPROXIMATE NO.  
OF HOMES AND  
POPULATION

Few homes - all indicated on U.S.G.S. 7.5 minute map; Derry and Wilpen quadrangles.  
Photo revised 1973.

APPENDIX C  
HYDRAULICS AND HYDROLOGY

SUBJECT DAM SAFETY INSPECTION - LATROBE RESERVOIR.



Engineers • Geologists • Planners  
Environmental Specialists

KHK DATE 5/17/78 PROJ. NO. 78-501-479  
CHKD. BY DLB DATE 5-22-78 SHEET NO. 1 OF 11

LATROBE RESERVOIR NDS & PA 479

DERRY QUADRANGLE }  
WILPEN QUADRANGLE } 7.5 MINUTE USGS MAP

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

DAM STATISTICS

MAXIMUM HEIGHT OF DAM = 86 FT.

DRAINAGE AREA (PLANIMETERED) = 5.50 SQ. MILES U.S.G.S MAP.

DRAINAGE AREA (FROM REF 2) = 5.66 SQ. MILES

STORAGE CAPACITY = 3650 ACRE- FEET  
@ NORMAL POOL (REF 2:)

SIZE CLASSIFICATION.

DAM SIZE = INTERMEDIATE. (SEE TABLE 1)  
REF. 1  
≥ 40 < 100 FT

SPILLWAY DESIGN FLOW (SDF)

HAZARD RATING = HIGH

POSSIBLE LOSS OF LIFE IS GREATER THAN 3

REFERENCES:

- 1: "RECOMMENDED GUIDELINES FOR SAFETY INSPECTION OF DAMS" BY DEPT. OF ARMY - OFFICE OF CHIEF ENGINEER - APPENDIX D.
- 2: LOCATION & DRAINAGE AREA, RESERVOIR MAP DRAWING No 2788 SHEET 2 BY GANNETT FLEMING CORDRY & CARPENTER INC 6/12/1958

SUBJECT DAM SAFETY INSPECTION - LATROBE RESERVOIR



KHK DATE 5/17/78 PROJ. NO. 78-501-479  
CHKD. BY DLB DATE 5-22-78 SHEET NO. 2 OF 11

Engineers • Geologists • Planners  
Environmental Specialists

REQUIRED SDF = PMF

(SEE TABLE 3, REF 1)

USE PMF FOR SDF

DRAINAGE AREA = 5.66 SQ. MILES (SHEET 1)

PMF (PEAK FLOW)/AREA = 1680 (SHEET 10 OF 11)

PMF =  $1680 \times 5.66 = 9509$  CFS.


SDF = 9509 CFS.

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDG

DEVELOP INFLOW HYDROGRAPH

MAXIMUM INFLOW = 9509 C.F.S

TOTAL TIME OF FLOW = 41 HRS. (FROM SHEET 11 OF 11)





THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

SUBJECT DAM SAFETY INSPECTION  
LATROBE RESERVOIR  
BY DLB DATE 7-5-78 PROJ. NO. 78-501-479  
CHKD. BY JPN DATE 7-6-78 SHEET NO. 3 OF 11

**gai**  
CONSULTANTS, INC.  
Engineers • Geologists • Planners  
Environmental Specialists

VOLUME OF INFLOW HYDROGRAPH

$$\begin{aligned}V &= \frac{1}{2} (\phi_{I_{MAX}}) (TIME) \\ &= \frac{1}{2} (9509 \text{ CFS}) (41 \text{ HRS}) (3600 \text{ SEC/HR}) (1 \text{ ACRE} / 43,560 \text{ FT}^2) \\ &= 16,110 \text{ ACRE-FEET}\end{aligned}$$

DETERMINE THE AVERAGE RAINFALL IN INCHES REQUIRED TO PRODUCE  
THE VOLUME ABOVE

$$\frac{(16,110 \text{ AC-FT}) (1 \text{ SQ. MI.} / 640 \text{ ACRES}) (12 \text{ IN/FT})}{(5.66 \text{ SQ. MI.})} = 53.4 \text{ INCHES}$$

VOLUMES PRODUCED BY RAINFALLS IN EXCESS OF 26 INCHES ARE  
TO BE RECALCULATED USING 26 INCHES AS AN UPPER BOUND

$$(26 \text{ INCHES}) (5.66 \text{ SQ. MI.}) (640 \text{ ACRES/SQ. MI.}) (1 \text{ FT} / 12 \text{ IN}) = 7849 \text{ AC-FT}$$

$$\text{VOLUME OF INFLOW (RECALCULATED)} = 7849 \text{ AC-FT}$$

NOTE:  $\phi_{I_{MAX}}$  REMAINS CONSTANT  
STORM DURATION DECREASES IN ACCORDANCE WITH THE  
DECREASE IN INFLOW VOLUME

$$\begin{aligned}\text{STORM DURATION} &= (7849 \text{ AC-FT}) (2) (43,560 \text{ FT}^2/\text{AC}) / (3600 \text{ SEC/HR}) (9509 \text{ CFS}) = \\ &= 20 \text{ HRS}\end{aligned}$$

SUBJECT DAM SAFETY INSPECTION - LATROBE RESERVOIR

BY KHK DATE 5/17/78 PROJ. NO. 78-501-479



CHKD. BY DLB DATE 5-22-78 SHEET NO. 4 OF 11



Engineers • Geologists • Planners  
Environmental Specialists

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDG

## SPILLWAY CAPACITY



SPILLWAY CREST ELEVATION = 1240 FT. SEE SHEET 12 OF REF 2

HEAD ABOVE SPILLWAY CREST = 16 FT " " "

$$Q = CL H_t^{3/2} \quad \text{--- (EQ. 21-121, REF 3)}$$

$$H_t = 16 \text{ FT. (NEGLECTING VELOCITY HEAD)} = H_d$$

$$L = 35 \text{ FT.}$$

REF. 3: "STANDARD HANDBOOK FOR CIVIL ENGINEERS" By MERRITT.

SUBJECT DAM SAFETY INSPECTION LATROBE RESERVOIR



KHK DATE 5/17/78 PROJ. NO. 78-501-479  
CHKD. BY DLB DATE 5-22-78 SHEET NO. 5 OF 11

FROM FIG. 21-67 REF. 3


$$P/H_D = \frac{5}{16} = .3125$$

$$\therefore C = 3.75$$

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDG

$$Q = 3.75 \times 35 \times (16)^{3/2} = 8400 \text{ CFS}$$

CONSIDER DISCHARGE THROUGH 2.4" BLOW OFF PIPE



INVERT ELEVATION 1167.0 (DRAWING H-4499-1 By J.G. WHITE ENGINEERING CORPORATION)

LENGTH OF PIPE = 765 FT (DRAWING 2788 SHEET II REF 2)

HEAD OVER INVERT = 1240 - 1167 = 73 FT.

USE BERNOULLI'S EQUATION.

$$Z_1 + \frac{P_1}{w} + \frac{V_1^2}{2g} = Z_2 + \frac{P_2}{w} + \frac{V_2^2}{2g} + h_f \quad \text{--- EQ 21-12 REF 3}$$

Where

$Z_1$  = HEIGHT OF INLET ABOVE DATUM = 0

$Z_2$  = HEIGHT OF OUTLET " " = 0

$P_1/w$  = PRESSURE HEAD AT INLET. = 72.0 FT.

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

SUBJECT DAM SAFETY INSPECTION - LATROBE RESERVOIR



KHK DATE 5/18/78 PROJ. NO. 78-501-479

CHKD. BY DLP DATE 5-22-78 SHEET NO. 6 OF 11

Engineers • Geologists • Planners  
Environmental Specialists

$$P_2/W = \text{PRESSURE HEAD AT OUTLET} = 0$$

$$V_1 = \text{VELOCITY AT INLET} = 0$$

$$V_2 = \text{VELOCITY AT OUTLET} = ? \text{ SOLVE FOR.}$$

$$h_f = \text{HEAD LOSSES DUE TO FRICTION}$$

$$h_f = \frac{LV^2}{2gD} \quad \text{DARCY - WEISBACH FORMULA} \quad \text{EQ-21-30} \\ \text{REF 3}$$

WHERE  $L = \text{LENGTH OF PIPE} = 765 \text{ FT (SHEET 5)}$

$V = \text{VELOCITY} = \text{SOLVE FOR}$

$D = \text{DIAMETER OF PIPE} = 2.0 \text{ FT}$

$g = 32.2 \text{ FT/SEC}^2$

$f = .017 \quad \text{FOR } f = .00085 \text{ (CAST IRON PIPE) :}$

TABLE 21-3

REF 3

$$f/D = .00042$$

$$\text{RAYNOLDS NUMBER} = 3.5 \times 10^7$$

$$\text{ENTRANCE LOSSES} = h_e = K_E \frac{V^2}{2g} \quad \text{EQ. (21-42) REF 3}$$

$K_E = \text{COEFFICIENT OF ENTRANCE LOSSES}$

$$= .50 \quad \text{TABLE 21-7 REF 3}$$

SOLVE BERNOULLI'S EQUATION.

$$0 + 72 + 0 = 0 + 0 + \frac{V_2^2}{2(32.2)} + \frac{.017(765)V_2^2}{2(32.2)(2)} + \frac{.50 V_2^2}{2(32.2)}$$



SUBJECT DAM SAFETY INSPECTION - LATROBE RESERVOIR

BY KHK DATE 5/18/78 PROJ. NO. 78-501-479

CHKD. BY DLB DATE 5-22-78 SHEET NO. 7 OF 11



$$72 = 0.016 V_2^2 + 0.101 V_2^2 + .008 V_2^2$$

$$V = 24.0 \text{ FT / SEC.}$$

$$Q = \frac{\pi (D^2)}{4} \times V = 75.40 \text{ CFS.}$$

MAXIMUM DISCHARGE THROUGH SPILLWAY = 8400 CFS

MAXIMUM DISCHARGE " PIPE = 75. CFS.

TOTAL OUTFLOW = 8475 CFS

NOTE: IT IS ASSUMED THE BLOW-OFF WILL BE OPENED PRIOR TO WHEN MAXIMUM SPILLWAY DISCHARGE OCCURS AND WILL REMAIN OPENED DURING THE ENTIRE DISCHARGE PERIOD

MAXIMUM INFLOW (9509 CFS) > MAXIMUM OUTFLOW (8475 CFS)

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

SUBJECT DAM SAFETY INSPECTION  
LATROGE RESERVOIR  
DLB DATE 5-26-78 PROJ. NO. 78-501-479  
CHKD. BY JFD DATE 5-26-78 SHEET NO. 8 OF 11



CONSIDER INFLOW RELATIVE TO BOTH OUTFLOW AND STORAGE  
USING SHORT CUT METHOD AS RECOMMENDED BY NAD

$$P = \frac{\text{MAXIMUM TOTAL DISCHARGE}}{\text{PMF PEAK INFLOW}} = \frac{8475}{9509} \quad \begin{matrix} \text{(SHEET 7)} \\ \text{(SHEET 2)} \end{matrix}$$

$$P = 0.89$$

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDG

$$(1-P) = \frac{\text{REQUIRED RESERVOIR STORAGE}}{\text{VOLUME OF INFLOW HYDROGRAPH}} = 0.11$$

$$\text{VOLUME OF INFLOW HYDROGRAPH} = 7849 \text{ AC-FT} \quad \text{(SHEET 3)}$$

$$\therefore (16112 \text{ AC-FT})(0.11) = 863 \text{ ACRE-FT}$$

$$\text{REQUIRED RESERVOIR STORAGE} = 863 \text{ ACRE-FT}$$

COMPUTE STORAGE AVAILABLE

- \* RESERVOIR SURFACE AREA AT EL 1240  $\approx$  120 ACRES
- \* RESERVOIR SURFACE AREA AT EL 1252  $\approx$  160 ACRES

\* NOTES: AREAS HAVE BEEN PLANIMETERED FROM DRWG #2 BY  
GIANNETT, FLEMING, CORDORY & CARPENTER

SUBJECT DAM SAFETY INSPECTION  
LATROBE RESERVOIR  
BY DLB DATE 5-26-78 PROJ. NO. 78-501-479  
CHKD. BY JW DATE 5-26-78 SHEET NO. 9 OF 11



AVAILABLE FREEBOARD (1256 - 1240) = 16 FT

STORAGE AVAILABLE  $\approx \left[ \frac{(160 + 120) \text{ ACRES}}{2} \right] (16 \text{ FT}) = 2240 \text{ AC-FT}$

STORAGE AVAILABLE > STORAGE REQUIRED

2240 AC-FT > 863 AC-FT


CONCLUSION: LATROBE RESERVOIR WILL BE ABLE TO  
CONTAIN AND OR PASS THE PMF PEAK  
INFLOW WITHOUT OVERTOPPING

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDG



CFS/MI<sup>2</sup>

PMF PEAK FLOW/AREA




PMF PEAK FLOW/AREA (CFS/MI<sup>2</sup>)  
VS.  
DRAINAGE AREA (MI<sup>2</sup>)

DRAINAGE AREA (SQ. MI.)



TOTAL TIME IN HOURS



THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDC

TOTAL TIME (HRS)  
VS  
DRAINAGE AREA (MI<sup>2</sup>)

DRAINAGE AREA  
(SQ. MI.)

APPENDIX D  
PHOTOGRAPHS

PHOTOGRAPH 1 View looking across the crest of the Latrobe Reservoir embankment taken from the right abutment. The spillway is located in the background. A field team member is shown near the center of the embankment as scale.

PHOTOGRAPH 2 View taken from a few hundred feet downstream of the Latrobe Reservoir embankment showing the spillway on the right and the rock toe near the center of the photograph.


PHOTOGRAPH 3 View looking downstream from the crest of the Latrobe Reservoir embankment.

PHOTOGRAPH 4 View of the upstream face of the Latrobe Reservoir embankment. The gate house can be seen near the right center of the photograph.





2



4



1



3




PHOTOGRAPH 5 View of the valve on the 24-inch blow-off pipe located approximately 250 feet downstream of the center of the embankment.

PHOTOGRAPH 6 View of the spillway at the Latrobe Reservoir. Note the riprap in the channel just downstream of the spillway.

PHOTOGRAPH 7 View of the upstream portion of the Latrobe Reservoir near the northeast end. A portion of a road passing around the reservoir has slumped into the reservoir as shown on the photograph. Roadway is not pictured.

PHOTOGRAPH 8 View of a two-lane bridge located approximately one-half mile downstream of the embankment. It represents the first restriction downstream.



6



8



5



7

APPENDIX E

GEOLOGY

The Latrobe Reservoir Dam is located approximately midway between the Chestnut Ridge Anticline and Ligonier Syncline in the Pennsylvanian age sedimentary rocks of the Conemaugh Formation. The unit is best characterized as a cyclic sequence of shales, siltstones, and sandstones containing a few limestone beds and coal seams. These strata dip to the southwest at about  $5^{\circ}$  in the area of the Latrobe Reservoir.




APPENDIX F

FIGURES


APPENDIX F - FIGURES

<u>Figure</u>	<u>Description/Title</u>
1	Location, Drainage Area, Reservoir Maps
2	General Plan of Embankment
3	Embankment Section and Details
4	Grouting and Drainage Details
5	Extension of Existing Tower I
6	Tower and Conduit Details, Supply Line Blow-off



LOCATION MAP  
SCALE IN MILES



**THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC**




RESERVOIR MAP  
SCALE 1:500



THIS PAGE IS BEST QUALITY PRACTICE CABLE FROM COPY FURNISHED TO DDC



PRACTICABLE



RESERVOIR CAPACITY CURVE

**LEGEND**  
 RAB - BORROW POINTS OR BORROW AREAS  
 RTP - TEST PIT OR BORROW POINT  
 NOTE FOR A BENCH MARK & TEST PIT  
 LOCUS, SEE SHEET 2788  
 NOTE THE EXACT LOCATION, LIMITS, DEPTH AND  
 FURNISHED QUANTITIES FOR BORROW AREAS  
 SHALL BE DIRECTED BY THE RESIDENT  
 ENGINEER IN THE FIELD.



DESIGNED BY	MUNICIPAL AUTHORITY OF THE	DATE
DRAWN BY	BOROUGH OF LATROBE	2
CHECKED BY	TROUT RUN DAM	2788
APPROVED BY	LOCATION, DRAINAGE AREA	
	& RESERVOIR MAPS	
	CAPACITY CURVE	

NO.	REVISIONS	DATE	BY

GANNETT FLEMING GURNEY & COMPANY, INC.  
 4140 N. 15th ST.  
 PHILADELPHIA, PA.


2

FIGURE 1




THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

THIS PAGE IS BEST COPY  
FROM COPY FURNISHED



THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDG

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDG



**LEGEND**

- SEA (100) START OF STATIONING ALONG AXIS OF DAM
- SEA (100) STATION ALONG CUT-OFF THROUGH
- SEA (100) START OF STATIONING ALONG SPILLWAY
- - 3" INDICATES TEST PIT
- - 6" INDICATES DRILL HOLE

**GENERAL NOTES**

- SECTION (A-B) INDICATES THAT SECTION B WAS TAKEN ON SHEET NO. 6 AND IS SHOWN ON SHEET NO. 7.
- ALL DIMENSIONS AND EXISTING CONDITIONS SHALL BE CHECKED AND VERIFIED BY THE CONTRACTOR AT THE SITE. NUMBERS IN CIRCLES INDICATE ITEM UNDER WHICH PAY LINE WILL BE MADE.
- PAY LINE FOR EXCAVATION AND WALLS BEHIND WALLS SHALL BE ON A VERTICAL LINE TWO FEET BEHIND EDGE OF FOOTING.
- ALL EXPOSED EDGES OF CONCRETE SHALL BE CHAMFERED ONE HALF INCH UNLESS OTHERWISE INDICATED.

SCALE 1" = 30'



REVISIONS	
NO.	DESCRIPTION




DESIGNED BY MJC	MUNICIPAL AUTHORITY OF THE BOROUGH OF LATROBE TROUT RUN DAM	SHEET NO. 6
DRAWN BY HJD		TOTAL SHEETS 2706
CHECKED BY ER		DATE JANUARY 1938
APPROVED BY VFB		
GANNETT FLEMING CORDERY & CARPENTER, INC. ENGINEERS		

FIGURE 2




THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDG


THIS PAGE IS BE  
FROM COPY FURNI



DETAIL  
INTERCEPTING GUTTER  
SCALE 1/2" = 1'-0"




SECTION 63  
SCALE 1/20




TYPICAL SAND & GRAVEL FILTER 7  
SCALE 1/2" = 1'-0"

NOTE: SAND SHALL CONSIST OF EQUAL  
SIZES OF TYPE 20 & TYPE 4  
COARSE. AGGREGATES IN SPECIFICATIONS  
OF THE PENNA. DEPT. OF HIGHWAYS  
SHALL MEET ALL REQUIREMENTS  
OF TYPE 20 FINE AGGREGATE IN  
SPECIFICATION OF PENNA. DEPT. OF  
HIGHWAYS.




DETAIL  
TOP OF DAM  
SCALE 1/8



DETAIL  
PERVIOUS SECTION B FILTER  
SCALE 1/8" = 1'-0"

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC



NOTE FOR GENERAL NOTES PERTAINING TO THIS SHEET,  
SEE SHEET 4



OWNER	MUNICIPAL AUTHORITY OF THE BOROUGH OF LATROBE	PROJECT NO.	2788
DESIGNED BY	TRIBUTARY ENGINEER	DATE	
CHECKED BY		APPROVED BY	
DATE			

REVISIONS	
NO.	DESCRIPTION


GANNETT FLEMING CORDDY & CARPENTER, INC.  
ENGINEERS  
600 N. SECOND ST.  
HARRISBURG, PENNSA.

FIGURE 3


*J*




THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDG



PLAN  
CUT-OFF TRENCH DRAINAGE BLANKET-ROCK TOE  
SCALE 1" = 3'




PROFILE ALONG C/L OF CUT-OFF TRENCH  
SCALE 1" = 30'



CAMBER AT TOP OF DAM


HORIZ. SCALE 1" = 100'  
VERT. SCALE 1" = 4'



SECTION  
SCALE 1" = 3'


THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

ACTICABLE







**THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC**




**WEST ELEVATION**  
SCALE 1/4" = 1'-0"







**SOUTH ELEVATION (SHOWN NORTH ELEVATION (O.H.))**  
SCALE 1/4" = 1'-0"



**PLAN AT BASE OF STEEL TOWER**  
EXISTING CONTROL HOUSE & FLOOR NOT SHOWN  
SCALE 1/4" = 1'-0"



**PLAN CONTROL HOUSE FLOOR**  
SCALE 1/4" = 1'-0"




**SECTION**  
SCALE 1/4" = 1'-0"

NOTE: WHERE CHAMBERS ARE SHOWN ON NEW WORK THEY ARE 1".

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

ACTICABLE



**NOTES**

DIMENSIONS THE CONTRACTOR SHALL MAKE FIELD MEASUREMENTS OF THE EXISTING CONTROL TOWER AND REPORT TO THE ENGINEER ALL DIFFERENCES BETWEEN ACTUAL DIMENSIONS AND THOSE OF THE EXISTING PLANS INCLUDING WITH ANY CORRECTION AT THE SITE OR WITH FABRICATION IF ANY ITEM IS TO BE INSTALLED AS PART OF THE WORK.

**STRUCTURAL STEEL:**  
 SHEAR CONNECTIONS SHALL BE WELDED.  
 FIELD CONNECTIONS:  
 TOWER, 10" GALVANIZED HIGH STRENGTH BOLTS CONTROL, MIDDLE, AND MACHINE BOLTS DOUBLE BOLTS.  
 TOWER, 10" EXCEPT ON MIDDLE BRACING WHICH MAY BE 8".  
 CONTROL HOUSE, 1/2" MIN. CHANNEL BRACES, SEE SPECIFICATIONS PAINT, SEE SPECIFICATION.  
 EXISTING GATE STEMS FOR GATES NO. 2, 3 AND 4 SHALL BE REPLACED GATE NO. 5 AS NOT SHOWN ON THESE DRAWINGS, REFER TO SPECIFICATIONS FOR WORK PERTAINING TO THIS GATE.  
 ALL WORK ON THIS SHEET PAYABLE UNDER ITEM 24.  
 FOR GENERAL NOTES PERTAINING TO THIS SHEET SEE SHEET NO. 8.





DESIGNED F.J.S.	MUNICIPAL AUTHORITY OF THE BOROUGH OF LATROBE TROUT RUN DAM  EXTENSION OF EXISTING TOWER - I	SHEET NO. 9
CHECKED S.W.A.T.		JOB NO. 2788
APPROVED V.P.R.		DATE JUNE 8, 1958
GANNETT FLEMING CORDROY & CARPENTER, INC. ENGINEERS 400 N. SECOND ST., HARRISBURG, PENNA.		
REVISIONS		




FIGURE 5 2



THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC




THIS PAGE IS BEST QU  
FROM COPY FURNISHED



THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDC

NEOPRENE WATERSTOP SCALE 8" = 1'-0"

NOTES  
FOR GENERAL NOTES PERTAINING TO THIS SHEET SEE SHEET NO. 8  
ALL REINFORCING STEEL ON THIS SHEET PERMISSIBLE UNDER ITEM 8



NO.	DESCRIPTION	DATE	BY
1	REVISIONS		
2	ADDED CONCRETE THROTTLE BLOCK.	10-1-55	SMW
3		10-1-55	SMW

DESIGNED BY S.W.M.P.	MUNICIPAL AUTHORITY OF THE BOROUGH OF LATROBE TROUT RUN DAM	SHEET NO. 11
CHECKED BY V.B.B.		JOB NO. 2788
APPROVED BY V.B.B.	TOWER & CONDUIT DETAILS SUPPLY LINE BLOW-OFF	DATE JUNE 8, 1955
CANNETT FLEMING CORDROY & CARPENTER, INC. ENGINEERS 600 N. SECOND ST. HARRISBURG, PENNSA.		


FIGURE 6

APPENDIX G  
REGIONAL VICINITY MAP



DERRY, PA. WILPEN, PA.

N4015—W7915/7.5 N4015—W7907.5/7.5



Latrobe Reservoir

GONIER

Tipple Mine

Coalpit



