

# 9710 W Outer Dr

## Existing Condition Photos



East Elevation



West & South Elevation



North Elevation



South Elevation

## Current Design Description

A 3-story apartment structure with 10 residential units, constructed in 1940, brick on wood stud wall construction, shingle roof, stone corner details, stone details at palladian window, stone sills, wood detailing at front entry, steel and wood canopy at back entry, wood windows throughout with the exception of steel windows at bathrooms and the lowest level. The addition of a brick shed to house the gas meter was made at a later date.



# 9730 W Outer Dr

## Existing Condition Photos



East & Courtyard South Elevation

## Current Design Description

A 3-story apartment structure with 23 residential units, constructed in 1939, with front courtyard, brick wall construction, shingle roof, stone sills, stone band detail, stone keystone details, brick detailing at corners, wood detailing at front entry, and steel windows throughout, and bay windows at the back facade.



Courtyard East



Courtyard East & North Elevation



East Elevation - Southern Facade



East Elevation - Northern Facade



# 9730 W Outer Dr

## Existing Condition Photos



West & North Elevation



North Elevation



South Elevation



West Elevation

## Current Design Description

A 3-story apartment structure with 23 residential units, with front courtyard, brick wall construction, shingle roof, stone sills, stone band detail, brick detailing at corners, wood detailing at front entry, and steel windows throughout, and bay windows at the back facade.



## Existing Conditions Detail Photos



### Existing Fence

- Short runs of chain link fence go beyond the property line



### Existing Downspouts

- Downspouts are in good condition and are tied into the City sewer; Paint is flaking off.
- Gutters need painting



### Existing Canopy

- Existing tie back canopy is corroded and in need of repair/reconstruction
- Brick is discolored/damaged around door and canopy due to improper drainage



## Existing Conditions Detail Photos



### Existing 9730 Front Landing

- Existing landing is damaged and hazardous



### Existing Vents in Masonry

- Existing vents in masonry are located in the kitchens in 9710
- Existing vents in masonry are also located at the mechanical room in 9710



### Existing Conduit

- Conduit is building-mounted at the back of both buildings



## Existing Conditions Detail Photos



## Historic Woodwork & Fixture

- Existing historic woodwork at front entries of both buildings shows deterioration and is in need of repair/reconstruction and new paint to match existing
- Existing historic light is in fair condition, flaking paint and rust should be removed and fixture restored

## Existing Utility Cap

- An existing utility cap is protruding up above the pavement where the front entry path meets the sidewalk and is a potential tripping hazard



## Existing Conditions Detail Photos



### Sill & Brick Discoloration

- Existing stone sills and masonry below are discolored and possibly water damaged
- Existing small windows in utility rooms appear to be added after original construction. The color of these bricks suggests that they were used in conjunction with the addition of the gas shed, and attempt to match the 'cleaned' color of the original bricks.



### Existing Landscaping

- Existing shrubs line the front facades of both buildings as well as a section of the back facade of 9730, some being dead/dying
- Two coniferous trees and several deciduous trees dot the site at the perimeter of the parking lot and parking lot islands and line the street frontage
- An ornamental tree is adjacent to the 9730 front entry






# Existing Conditions Detail Photos

- Existing parking layout has two-directional one-way parking, and only accommodates 33 parking spaces. New residential unit count is 35.
- Existing path between buildings is only 2'-0" wide.
- Existing path and sidewalk near the front of 9730 W Outer Dr front entry is missing a section and heaving.



# Existing Site Survey






## Description of Project\_Permit Work List

This project a rehabilitation being undertaken by Grandmont Rosedale Park Collective. The goal of the project is to celebrate the historic presence, features, and use of the buildings, while updating systems, increasing functionality, and introducing accessibility.

The scope of work includes the following; notes pertain to both buildings U.N.O:

1. Restore the existing masonry (brick), utilizing repointing, tuckpointing, and cleaning as necessary
2. Replace the existing leaky (non-historic) asphalt shingle roof in kind
3. Replace the existing deteriorated wood and steel windows with double hung thermally-broken aluminum windows and install thermally-broken windows at new openings for new Level 00 units
4. Install new accessible ramp and railing at 9730 new accessible entry
5. Replace existing 9710 steel & wood canopy in kind, and install similar new canopy at new 9730 accessible entry; install downspout at both canopies for water mitigation
6. At 9730 front entry, remove & replace existing concrete landing in kind & restore historic light fixture
7. Replace all other light fixtures at entrances with new; install new exterior sconce at new accessible entry; remove building-mounted security lights; install new security lighting at parking lot & ramp
8. Repair existing historic woodwork at front entries of 9710 & 9730
9. Scrape and paint all exterior doors, wood features, and gutters; paint and install new 8"x8" brick vents per res. unit in brick facades (avoid front facade) where brick vent is not already existing

## Scope of Work Drawing






## Description of Project Cont\_Permit Work List

10. Install new security fence at perimeter of parking lot and ramp with pedestrian swing gate and remote operated vehicular gates; existing sections of fence on-site to remain
11. Remove & replace narrow gray concrete pathway between buildings with accessible path (5'-0"W)
12. Re-stripe (to 90 degree spaces & (2) accessible spaces) and reconfigure curbs at existing parking lot to match unit count; remove and replace concrete as needed at parking lot to properly grade
13. Repair pathway and sidewalk near 9730 front entry; remedy utility cap trip hazard at 9710 front entry
14. Regrade site to slope away from buildings where necessary; remove existing landscaping in order to regrade and replace with similar
15. Construct new masonry dumpster enclosure to house (3) 2 yd dumpsters to serve both buildings
16. Install (35) condensing units at grade (1 per unit); install metal panel enclosure to secure and screen (10) condensing units to service 9710; install ACBandit (or similar) security cages at remaining condensing units and plant living screens around each condensing unit cluster
17. Restore any disturbed areas with lawn; remove (2) trees to accommodate ramp, install parking lot & site deciduous trees (Red Sunset Maple, Autumn Brilliance Serviceberry, American Hophornbeam); other new plantings (crosshatch) include shrubs (Annabelle Hydrangea, Kelseyi Dwarf Dogwood, Dense Yew, Hicks Yew) and perennials (Happy Returns Daylily, Pardon Me Daylily, Russian Sage)

## Scope of Work Drawing



# Detailed Scope of Work

## Wood Window Replacement

See Appendix for Window Assessment from Blackberry



9710 W Outer Dr existing conditions, wood windows

9710 W Outer Dr Wood Windows

Wood construction with steel lintels and stone sills, *highlighted in red*, save for bathroom and Level 00 windows of steel construction.

### Cause for Replacement

- Some exterior sills are split, allowing water to enter the building envelope
- The majority of sills are fissured, causing dry rot and material breakdown
- The operability of the windows ranges from inconsistent to very difficult
- They use a tape balance system that is not readily replaced without potential damage to the master frame
- The jamb liner/weatherstrip is in poor conditions and is not a product that is available for replacement
- All windows require re-glazing with new glazing compound, and existing material is unable to be removed without damage to the sashes and breaking the glass
- The glazing compound is falling out and breaking down on all sashes
- The paint is peeling
- The caulking is failing and falling out
- The storm windows are in poor condition with many broken track guides and failing corner joinery, allowing water to get trapped on the exterior sills, and dry rot and decay in 30-40% of the openings
- A true restoration process is not able to be implemented for these windows. Painting and Glazing Repair can be done; however, this approach does not address the described window issues.

### Replacement Method

- All existing window components to be removed and disposed of; abatement may be required. Wood blocking to be set in the jamb cavity to fill the weight box void.
- New windows to be set with exterior aluminum brickmould and sill components replicating historic exterior casework. New Double Hung or Single Hung windows would be set and fastened in place. Prior to this install all cavities would be insulated.
- Windows would be cleaned, adjusted, and the perimeter caulked at the masonry intersection. New casework would be installed and finished.

### Cost Estimate Comparison (all windows)

#### ▪ Replacement:

\$94k [wood] + \$45k [9710 steel] + \$261k [9730 steel]  
+ \$19k [new openings] + \$10k [repair fixed decorative windows]  
= **\$429,000** [total]

#### ▪ Paint & Glazing Repair:

\$49.5k [wood] + \$37k [9710 steel] + \$165k [9730 steel]  
+ \$19k [new openings] + \$10k [repair fixed decorative windows]  
= **\$280,500** [total]

*\* Note: Cost estimate includes material, tax on material, labor (non-union, non-prevailing wage), employment cost, insurance, staging, shop drawings & supervision. Cost estimate does NOT include new casework or associated painting in replacement est; neither interior painting, balance repair, or new storms in painting & glazing repair*



## Detailed Scope of Work

### Steel Window Replacement

See Appendix for Window Assessment from Blackberry



9710 W Outer Dr existing conditions, steel windows

9710 & 9730 W Outer Dr Steel Windows  
Steel construction set in wood framed, masonry opening with stone sills, *highlighted in red*; include all bathroom, Level 00, & 9730 windows.

### Cause for Replacement

- The exterior perimeter caulking is failing and coming loose from the masonry
- The locks are bent/broken in over 80% of all windows
- The weather stripping is rusted and the tape balancers are typically bent, crimped, or torn, making the operation and sash movement stiff and resistant
- There isn't a tight seal at the points of weatherstripping between the sash and master frame causing air infiltration and condensation, which has caused corrosion on the interior painted surfaces
- The exterior paint is worn, peeling, and/or allowing rust and corrosion to bleed thru to the surface
- The butt joint tubular steel framing has mild-to-heavy corrosion at the exterior sill, the sash, and frame joinery
- The storm windows have many broken track guides and failing corner joinery, trapping water on the exterior sill creating rust and corrosion
- The glazing compound is falling out and failing on all sashes
- These windows do not lend themselves to restoration, as the components are in poor condition and no replacement parts are available, and leaving the sashes in place will not resolved the poor operation issue

### Replacement Method

- All existing window components to be removed and disposed of; abatement may be required. Wood blocking to be set in the in the jamb cavity.
- Repair fixed decorative windows in the common area stairs wells only.
- New windows to be set directly in the masonry openings and anchored to the wood blocking. Prior to this installation all voids would be insulated.
- Interior plaster returns to be repaired.
- Perimeter caulking to be applied on the interior and exterior, and windows to be cleaned and adjusted.

### Cost Estimate Comparison (all windows)



- Replacement:  
\$94k [wood] + \$45k [9710 steel] + \$261k [9730 steel]  
+ \$19k [new openings] + \$10k [repair fixed decorative windows]  
= **\$429,000** [total]
- Paint & Glazing Repair:  
\$49.5k [wood] + \$37k [9710 steel] + \$165k [9730 steel]  
+ \$19k [new openings] + \$10k [repair fixed decorative windows]  
= **\$280,500** [total]

\* Note: Cost estimate includes material, tax on material, labor (non-union, non-prevailing wage), employment cost, insurance, staging, shop drawings & supervision. Cost estimate does NOT include new casework or associated painting in replacement est; neither interior painting, balance repair, or new storms for painting & glazing repair est.

# Wood Window Replacement


## Existing & Proposed Details

Proposed wood window replacement:  
 Quaker H650 DS, thermally-broken aluminum window with custom panning. This approach will provide a well-functioning, energy efficient replication of the original windows.



**EXTERIOR**

**EXISTING HEAD/MEETING RAIL/SILL**





**PROPOSED HEAD/MEETING RAIL/SILL**




# Wood Window Replacement

## Existing & Proposed Details Cont.




### EXISTING JAMB



### PROPOSED JAMB

# Wood Window Replacement Existing & Proposed Details

Proposed steel window replacement:  
Thermal Windows, Inc.  
Series 700 double hung  
thermally broken aluminum  
window. This approach will  
provide a well-functioning,  
energy efficient replacement  
of the original windows with  
the closest available profile  
to existing. See appendix.




**PROPOSED WINDOW DETAILS & MEASUREMENTS**




# Window Replacement

## 9710 W Outer Dr Elevations - Existing + New




### North Elevation

- All existing wood and steel windows to be replaced
- All window locations to remain as existing
- No new window openings
- New louvered dryer vents at A5 for new W/D at Laundry
- Existing brick vents to remain & new vent added for mech.




### West Elevation

- All existing wood and steel windows to be replaced; exception: existing fixed steel window at stairwell to be repaired
- All window locations to remain as existing
- No new window openings



### South Elevation

- All existing wood and steel windows to be replaced
- All window locations to remain as existing
- No new window openings
- Existing brick vents to remain




### East Elevation

- All existing wood and steel windows to be replaced; exception: existing fixed steel window at stairwell to be repaired
- All window locations to remain as existing
- No new window openings


# Window Replacement

## 9730 W Outer Dr Elevations - Existing + New




### South Elevation

- All existing steel windows to be replaced & existing window locations to remain
- New window openings at M1 & M2 at existing masonry wall (see photos, pg 3) Remove existing masonry for openings
- New brick vents installed




### North Elevation

- All existing steel windows to be replaced & existing window locations to remain
- New window openings at P6 & P7 at exist. masonry wall (see photos, pg 3)
- Remove existing masonry to create openings
- New brick vents installed



### South Courtyard Elevation

- All existing steel windows to be replaced & existing window locations to remain
- No new window openings




### North Courtyard Elevation

- All existing steel windows to be replaced & existing window locations to remain
- No new window openings




# Window Replacement

## 9730 W Outer Dr Elevations - Existing + New



### East Elevation

- All existing steel windows to be replaced; exception: existing fixed steel window at stairwell to be repaired
- No new window openings & existing window locations to remain



### West Elevation

- All existing steel windows to be replaced; exception: existing fixed steel window at stairwell to be repaired
- Existing window locations to remain as existing, excluding (2) existing windows to be demolished for new accessible entry & ramp (see Demo Elevation & pg 1)
- New window openings at V2, V3, V4, V5, V8, V10, V11 & new door at existing masonry wall (see photos, pg 1)
- Remove existing masonry for openings
- New brick vents installed




**Demolition Elevation**  
@ New Accessible Entry

See Appendix for Structural Assessment

# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - North Elevation

### Window A1, Type D1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - North Elevation


### Window A2, Type F1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - North Elevation

### Window A3, Type G1


- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - North Elevation




### Window A4, Type L1

- Broken Glass
- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - North Elevation



### Window A5, Type H1

- Broken Glass
- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos




9710 W Outer Dr - North Elevation

### Window A6, Type G1

- Broken Glass
- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - North Elevation


### Window A7, Type D2

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos




9710 W Outer Dr - North Elevation

### Window B1, Type A1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - North Elevation

### Window B2, Type E1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement


## Existing Conditions Detail Photos



9710 W Outer Dr - North Elevation


### Window B3, Type G1

- Broken Balance
- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - North Elevation

### Window B4, Type K1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - North Elevation

### Window B5, Type K1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - North Elevation


### Window B6, Type G1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos




9710 W Outer Dr - North Elevation

### Window B7, Type A1

- Badly Rotted
- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - North Elevation


### Window C1, Type A1

- Broken Glass
- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - North Elevation

### Window C2, Type E1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - North Elevation

### Window C3, Type G1

- Broken Glass
- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos




9710 W Outer Dr - North Elevation

### Window C4, Type K1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - North Elevation

### Window C5, Type K1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos




9710 W Outer Dr - North Elevation

### Window C6, Type G1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - North Elevation

### Window C7, Type A1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - West Elevation

### Window D1, Type D1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - West Elevation

### Window E1, Type A1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos




9710 W Outer Dr - West Elevation

### Window E2, Type B1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - West Elevation

### Window E3, Type B1

- Exterior Split Sill
- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - West Elevation

### Window E4, Type A1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - West Elevation

### Window F1, Type A1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos




9710 W Outer Dr - West Elevation

### Window F2, Type B1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

## Window Repair

### Existing Conditions Detail Photos



9710 W Outer Dr - West Elevation

### Window F3, Type S1


- Existing Fixed Window at Common Area Stairwell to be repaired
- See Appendix for Window Schedule & Measurements
- See Window Assessment & Survey by Blackberry in appendices for further details and information





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - West Elevation

### Window F4, Type B1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - West Elevation

### Window F5, Type A1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - South Elevation

### Window G1, Type H1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - South Elevation

### Window G2, Type G1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - South Elevation


### Window G3, Type F2

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - South Elevation

### Window G4, Type D1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - South Elevation

### Window H1, Type A1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - South Elevation

### Window H2, Type G1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - South Elevation

### Window H3, Type J1

- Exterior Rotted Sill
- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - South Elevation

### Window H4, Type I1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - South Elevation

### Window I1, Type A1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - South Elevation

### Window I2, Type G1


- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - South Elevation

### Window I3, Type I1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - South Elevation

### Window I4, Type I1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - South Elevation

### Window I5, Type G1

- Broken Glass
- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - South Elevation


### Window I6, Type E2

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - South Elevation

### Window 17, Type A1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation

### Window J1, Type D1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation

### Window J2, Type C1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation

### Window J3, Type C1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation

### Window J4, Type C1

- Badly Rotted
- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation

### Window J5, Type C1

- Badly Rotted
- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation

### Window J6, Type D1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation

### Window K4, Type B1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation

### Window K5, Type A1

- Broken Glass
- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation

### Window L1, Type A1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos




9710 W Outer Dr - East Elevation

### Window L2, Type B1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Repair

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation

Window L3, Type S3

Window L4, Type S2

Window L5, Type S3

- Existing Fixed Window at Common Area Stairwell to be repaired
- See Appendix for Window Schedule & Measurements
- See Window Assessment & Survey by Blackberry in appendices for further details and information





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation

### Window L6, Type B1

- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation

### Window L7, Type A1


- Note: Extent of exterior deterioration, dry rot, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos




9730 W Outer Dr - South Elevation

### Window M3, Type Y1

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - South Elevation


### Window M4, Type U2

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos




9730 W Outer Dr - South Elevation

### Window M5, Type Y1

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - South Elevation


### Window M6, Type T2

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - South Elevation


### Window M7, Type M2

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - South Elevation


### Window N1, Type N2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - South Elevation


### Window N2, Type U2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - South Elevation


### Window N3, Type Z1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos




9730 W Outer Dr - South Elevation

### Window N4, Type U2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - South Elevation


### Window N5, Type Z1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos




9730 W Outer Dr - South Elevation

### Window N6, Type T2

- Broken Glass
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - South Elevation

### Window N7, Type N2


- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - South Elevation


### Window O1, Type N2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - South Elevation


### Window O2, Type U2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos




9730 W Outer Dr - South Elevation

### Window O3, Type Z1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - South Elevation


### Window O4, Type U2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos





9730 W Outer Dr - South Elevation

### Window O5, Type Z1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - South Elevation


### Window O6, Type T2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement


## Existing Conditions Detail Photos



9730 W Outer Dr - South Elevation


### Window O7, Type N2

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - North Elevation

### Window P1, Type M2


- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos




9730 W Outer Dr - North Elevation

### Window P2, Type T2

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - North Elevation

### Window P4, Type U2


- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement


## Existing Conditions Detail Photos



9730 W Outer Dr - North Elevation


### Window P5, Type Y1

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - North Elevation


### Window Q1, Type N2

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos




9730 W Outer Dr - North Elevation

### Window Q2, Type T2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - North Elevation


### Window Q3, Type Z1

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos




9730 W Outer Dr - North Elevation

### Window Q4, Type U2

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - North Elevation


### Window Q5, Type Z1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - North Elevation


### Window Q7, Type N2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - North Elevation

### Window R1, Type N2


- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - North Elevation


### Window R2, Type T2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - North Elevation

### Window R4, Type U2


- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - North Elevation


### Window R5, Type Z1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - North Elevation

### Window R6, Type U2


- Broken Glass
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - North Elevation


### Window R7, Type N2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window S1, Type M1


- Badly Corroded
- Broken Glass
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation




### Window S2, Type O1

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window S3, Type O1

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation




### Window S4, Type M1

- Badly Corroded
- Water Infiltration
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window S8, Type Q1

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation




### Window S9, Type U1

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation




### Window S10, Type O1

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation




### Window S11, Type O1

- Badly Corroded
- Broken Glass
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window S15, Type M1


- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window S16, TypeO1

- Badly Corroded
- Replacement window, not historic
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window S17, Type O1

- Badly Corroded
- Broken Glass
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window S18, Type M1

- Badly Corroded
- Broken Glass
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window T1, Type N1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window T2, Type P1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window T3, Type P1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window T4, Type N1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window T8, Type R1


- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation




### Window T9, Type U1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window T10, Type P1


- Broken Glass
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window T11, Type R1

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window T15, Type N1

- Missing Hardware
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation




### Window T16, Type P1

- Broken Glass
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window T17, Type P1

- Broken Glass
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window T18, Type N1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window U1, Type N1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos




9730 W Outer Dr - East Elevation



### Window U2, Type P1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window U3, Type P1

- Broken Glass
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos




9730 W Outer Dr - East Elevation




### Window U4, Type N1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window U8, Type R1


- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Repair

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation




### Window U9, Type S5

- Existing Fixed Window at Common Area Stairwell to be repaired
- See Appendix for Window Schedule & Measurements
- See Window Assessment & Survey by Blackberry in appendices for further details and information



# Window Replacement

## Existing Conditions Detail Photos




9730 W Outer Dr - East Elevation



### Window U10, Type S6


- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window U11, Type P1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window U12, Type R1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos




9730 W Outer Dr - East Elevation




### Window U16, Type N1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation



### Window U17, Type P1


- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - East Elevation




### Window U18, Type P1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos





9730 W Outer Dr - East Elevation



### Window U19, Type N1

- Interior Rusted Balance Tape
- See Jamb Track
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - South Courtyard Elevation


### Window S5, Type U1

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - South Courtyard Elevation


### Window S6, Type T1

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - South Courtyard Elevation

### Window S7, Type M1

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement


## Existing Conditions Detail Photos



9730 W Outer Dr - South Courtyard Elevation

### Window T5, Type U1

- Broken Glass
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - South Courtyard Elevation

### Window T6, Type T1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - South Courtyard  
Elevation

### Window T7, Type N1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - South Courtyard  
Elevation

### Window U5, Type U1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - South Courtyard Elevation


### Window U6, Type T1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos




9730 W Outer Dr - South Courtyard Elevation

### Window U7, Type N1

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - North Courtyard Elevation


### Window S12, Type M1

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - North Courtyard Elevation

### Window S13, Type T1

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - North Courtyard Elevation


### Window S14, Type U1

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - North Courtyard Elevation


### Window T12, Type N1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - North Courtyard Elevation

### Window T13, Type T1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - North Courtyard Elevation


### Window T14, Type U1

- Broken Glass
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - North Courtyard Elevation


### Window U13, Type N1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos




9730 W Outer Dr - North Courtyard Elevation

### Window U14, Type T1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements

# Window Replacement

## Existing Conditions Detail Photos



9730 W Outer Dr - North Courtyard Elevation

### Window U15, Type U1


- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation




### Window V1, Type M2

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation



### Window V6, Type M2

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation


### Window V7, Type Q2

- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation

### Window DEMO 01, Type Q2


- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos




9710 W Outer Dr - East Elevation




### Window V9, Type M2

- Broken Glass
- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos




9710 W Outer Dr - East Elevation



### Window W1, Type N2


- Broken Glass
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation




### Window W2, Type V1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation



### Window W3 & W4, Type X1


- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation




### Window W5, Type V1

- Missing Balance
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos




9710 W Outer Dr - East Elevation



### Window W6, Type R2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation




### Window W7, Type R2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation



### Window W8, Type P2


- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation




### Window W9, Type U2

- Broken Glass
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements




# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation



### Window W10, Type V1


- Missing part of Sash Frame
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation


### Window W11 & W12, Type X1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation



### Window W13, Type V1


- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation



### Window W14, Type U2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation



### Window W15, Type R2


- Badly Corroded
- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation




### Window DEMO 02, Type R2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation



### Window W16, Type V1


- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation




### Window W17 & W18, Type X1

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation



### Window W19, Type V1


- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation




### Window W20, Type N2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement


## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation

### Window X1, Type N2


- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation




### Window X2, Type P2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement


## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation

### Window X3, Type R2


- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Repair


## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation


### Window X4, Type S7

- Existing Fixed Window at Common Area Stairwell to be repaired
- See Appendix for Window Schedule & Measurements
- See Window Assessment & Survey by Blackberry in appendices for further details and information



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation

### Window X5, Type R2


- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation




### Window X6, Type P2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation

### Window X7, Type U2


- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation


### Window X8, Type P2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation



### Window X9, Type U2


- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation




### Window X10, Type R2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation



### Window X11, Type R2


- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation




### Window X12, Type P2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements



# Window Replacement

## Existing Conditions Detail Photos



9710 W Outer Dr - East Elevation



### Window X13, Type N2

- Note: Extent of exterior deterioration, corrosion, and loss of operability is not fully apparent in interior photos. Replacement parts for existing windows are unavailable, making restoration of thermal and operable functionality impossible, and long-term maintenance infeasible. Recommendation is for replacement, for quality of life of future tenants and for feasibility of long-term maintenance.
- See Window Assessment (Blackberry) in appendix for further detail and information, including further notes on deterioration beyond repair
- See Appendix for Window Schedule & Measurements





## Detailed Scope of Work

### Roof Replacement



Level 02 ceiling, water damage    proposed asphalt shingle type

### Shingle Roof Replacement

- Due to existing roof leaks in multiple locations and the age of the existing roof, the gray asphalt shingle roof will be replaced in kind
- See photo of one of several instances of water damage caused by roof leaks (left)
- See photo of existing roof color & materials (top)



### Gutters


- Repair existing gutters where separating and replace fascia where deteriorated (see photo of existing condition, left)
- Clean and paint




### Dormers

- Repair existing dormers (see photo of existing condition, left)
- Scrape and paint

## Detailed Scope of Work



*proposed elevation*



*proposed plan*

## New Accessible Ramp

- New barrier free, wood construction ramp (highlighted in gray in plan) with wood railing and stair
- Railing verticals play contrastingly off of masonry horizontals of the historic buildings



*proposed new canopy at 9730 W Outer Dr*

## Canopies

- Reconstruct existing tie back canopy at 9710 of like materials: flat metal canopy
- Construct new canopy of similar materials: flat metal canopy
- Install canopy into mortar joints
- Install & paint new aluminum downspouts at both canopies for proper drainage



## Detailed Scope of Work

### Exterior Light Fixtures



*existing conditions*



#### 9730 Front Entry

- Fixture Restoration
- Rewire and replace bulb with 3000K LED



*existing conditions*



*proposed*

#### 9710 Front Entry

- New fixture; original is missing
- Replace bulb with 3000K LED
- Proposed Product: Generation Lighting, 8753EN3-15 One Light Outdoor Wall Lantern, 9.3 Watt LED bulb, 800 Lumens, White Glass, Black Polycarbonate finish, Dimensions: 6"W X 7.25"H
- See appendix for cut sheet



*existing conditions*



*proposed*

#### 9730 Back Entry

- New fixture at back entry door; original is missing
- Replace bulb with 3000K LED
- Proposed Product: Niveous LED Outdoor Flush-mount by dweLED, Small Option: 9.5 Watt (800 Lumens) 120 Volt Integrated LED: CRI: 90 Color Temp: 3000K Lifespan: 45000 hours, White Aluminum, Mouth Blown Etched Glass, Dimensions: 6"H, 6" Diameter, Weight 2.38Lbs
- See appendix for cut sheet

# Detailed Scope of Work

## Exterior Light Fixtures



existing conditions



proposed

### 9710 Back Entry

- New fixture; original is missing
- Replace bulb with 3000K LED
- Proposed Product: Generation Lighting, 8753EN3-15 One Light Outdoor Wall Lantern, 9.3 Watt LED bulb, 800 Lumens, White Glass, Black Polycarbonate finish, Dimensions: 6" W X 7.25" H
- See appendix for cut sheet




proposed sketch



proposed

### New Accessible Entry



- New wall sconce at new entry
- Proposed Product: Generation Lighting, 8753EN3-15 One Light Outdoor Wall Lantern, 9.3 Watt, 3000K LED bulb, 800 Lumens, White Glass, Black Polycarbonate finish, Dimensions: 6" W X 7.25" H
- See appendix for cut sheet



existing conditions

### Parking Lot Islands

- New LED Shoebox fixtures at perimeter of parking lot and positioned to light the ramp
- Proposed Product: D-Series Size 0 LED Area Luminaire, EPA: 0.95 sf, 16 lbs, Dimensions: 26" L x 13" W x 3" H - 7" H
- See appendix for cut sheet



proposed






# Detailed Scope of Work

## Proposed Condensing Units, Screens, & Fences




*proposed security cage*



*proposed condensing unit*



*living screen, Hicks Yew*



*proposed cond. unit plan*

### Cond. Units & Security Cages

- Proposed one new air-to-air condensing unit per residential unit; air conditioning is not existing
- ACBandit security cages (pictured, left) or similar, bolt condensing units to concrete using steel straps to discourage theft
- See pgs 9&10 for location on-site

### Living Screens

- Hicks Yew functions as living screens at perimeter of clusters of condensing units
- See pgs 9&10 for location on-site




*proposed security fence*

### New Security Fence & Screened Enclosure

Install new security fence at perimeter of parking lot and ramp, abutting existing chain link fence (neighbor). Product: Riverdale Mills, WireWall, cut to 6'H, 10.5G Steel, Black PVC Coating, Welded Wire Mesh system

Install new 6'H metal panel enclosure to screen & secure & allow ventilation to (10) condensing units at 9710: McNICHOLS Wire Mesh, Carbon Steel, Cold Rolled, Mill Finish, Woven-Lockcrimp Weave, 1/2" x 1/2" Opening (Square), 0.120" (11 Gauge) Thick Wire Diameter, 65% Open Area, Hot Dip Galvanized, welded 2x2 HSS frame




*proposed screen panel effect*

See scope of work drawing on pg 10 and Appendix for cut sheets.

## Detailed Scope of Work



proposed CMU color



proposed enclosure plan




proposed gate

## New Dumpster Enclosure

- New 6'H masonry dumpster enclosure with opaque doors on 6" concrete pad to house (3) 2-yard dumpsters
- Dumpster Enclosure Gates: Ametco, Shadow 100, double swing gates, electro-forged welded steel fencing, fixed louver design, 1 31/32" X 1/16" formed main bar & 5/32" round cross bar to provide 100% direct visual screening, includes posts, frame, hinges, panels, pad-lockable slide and cane bolts, Galvanized and Powder Coated Light Gray, Overall Dimensions: 11' X 6', 3.5 lbs
- Masonry to be Fendt 8x4x16 CMU, smooth finish, color 4076 (inspired by existing stone detail of buildings) mortar to be of like color

## Exterior Paint

- Paint exterior woodwork, exterior doors, dormers, gutters, fascia, downspouts
- The selected dark blue hue enhances the buildings' presence, grounding and highlighting trim and detailing
- Color: Inkwell SW 6992



- Paint brick vents (see photo of brick color and existing recessed brick vents)
- Color: SW to match "cleaned" brick color



## General Paint Specs

Primers: SW exterior grade All Surface Enamel Latex Primer - A41W01210  
 Sherwin Williams (SW) Exterior Latex Wood Primer - B42W08141

Paint: SW Duration Exterior Acrylic Latex - K32W00251; Sheen: Satin

Surface preparation: Protect surfaces not to be painted; clean surfaces by removing dirt, existing paint, rust, and other foreign matter with rag or brush; clean steel and aluminum surfaces in accordance with SSPC SP1 (solvent cleaning). Completely dry surfaces before painting.

Application: Apply primer and paint per manufacturer's recommendations; apply one coat of primer on all unpainted surfaces and two paint finish coats on all surfaces; allow recommended dry time between coats; ensure coating is uniform and free from drips, runs, waves, brush marks or variation in color, texture, or finish.



## Detailed Scope of Work

### Brick Restoration & Cleaning

Exterior brick walls are generally in good condition: masonry is generally uncracked; mortar joints appear sound; no evidence of excessive repointing; bricks don't appear to be distressed. General cleaning of the brick is needed as well, evidenced by discoloration. The gentlest, least invasive means possible to be used to clean the existing brick. A 9' x 9' area to be tested with water and natural bristle brush cleaning first. Water or steam may be used. Extra low pressure (i.e. no more than 100 psi) to be used first. If this doesn't work, the pressure may be increased up to 400 psi. If these methods don't work, Prosoco EK Restoration Cleaner (Enviro Klean), a mild pH neutral detergent cleaner may be used. If this method doesn't work either, Prosoco Sure Klean, a mild acidic cleaner may be used, but only after successfully testing an area of brick and stone with this cleaner.



### Tuckpointing

- Tuckpointing is needed in small areas throughout the brick facades of both buildings
- Examples of areas in need of tuckpointing\_9710 W Outer Dr
- (see photos of existing conditions, left)



### Repointing

- Repointing is required at 9730 at the chimney (see photo of existing condition, left)
- Repointing is required at water damaged section of masonry at 9710 back entry (see photo of existing condition, left)
- Mortar will match existing in strength, color, and profile

### Appendix to Follow

- CUT SHEETS
- STRUCTURAL ASSESSMENT
- WINDOW ASSESSMENT, SCHEDULES & DETAILS





Intoto Studio

9710-9730 West Outer Drive  
Condition Assessment Report

July 7, 2021



Resurget Engineering PC  
4219 Woodward Ave., Suite 306  
Detroit, MI 48201  
[www.resurget.engineering](http://www.resurget.engineering)



**RESURGET**  
ENGINEERING

# Contents

|  | Page |
|--|------|
| 1 Executive Summary .....                                      | 1    |
| 2 Project Description .....                                    | 2    |
| 3 Project Team.....  | 2    |
| 4 Scope of Services.....                                       | 2    |
| 5 Condition Assessment.....                                    | 2    |
| 5.1 Building Description, Document Review and Interviews       | 2    |
| 5.2 Walk-Through Survey  | 3    |
| 5.3 9710 West Outer Drive                                      | 4    |
| 5.3.1 Exterior Facade.....                                     | 5    |
| 5.3.2 Storage locker water damage.....                         | 5    |
| 5.3.3 Demolished Ceiling.....                                  | 5    |
| 5.3.4 Semibasement Sill Damage .....                           | 6    |
| 5.3.5 Pit below stairs .....                                   | 7    |
| 5.3.6 Roof Truss Access and Water Damage.....                  | 7    |
| 5.3.7 Rear Canopy .....  | 8    |
| 5.3.8 Utility Cap in Sidewalk .....                            | 8    |
| 5.4 9730 West Outer Drive                                      | 9    |
| 5.4.1 Semibasement Sill Damage.....                            | 10   |
| 5.4.2 Water damage due to leaks .....                          | 11   |
| 5.4.3 Damage at bay window .....                               | 12   |
| 5.4.4 Roof Truss Access and Water Damage...                    | 12   |
| 5.4.5 Water Damage at sills due to air conditioning units..... | 13   |
| 5.4.6 Joist damaged by pipe penetrations. ....                 | 13   |
| 5.4.7 Typical Building condition .....                         | 14   |
| 5.4.8 Downspout tie in .....                                   | 14   |
| 5.4.9 Front entry.....   | 15   |



# 1 Executive Summary

Resurget Engineering was authorized by Intoto to carry out a Condition Assessment of the existing buildings located at 9710 and 9730 Outer Drive in Detroit, Michigan.

The scope of work includes the Baseline Property Condition Assessment of the existing building structure. Does not include any work related to ADA compliance or environmental hazardous materials. It does not address Mechanical, Electrical or Plumbing systems.

The structures in question are two adjacent two-story multifamily housing buildings. Both buildings are two stories tall with an additional semibasement level. The original and continued use will be multifamily residential. The attic space, which was not accessed as part of this walk through, is a gable truss structure with several louver dormers.

All the facades are constructed of gravity-bearing brick veneer with cmu or concrete backup at the semibasement level and wood stud backup assumed on the upper levels. Punched window openings are supported by steel lintels. The exterior of the building has been maintained, including brick repointing. Louvers are clad in wood siding.

The buildings appear to be in good condition overall. Localized deterioration due to water infiltration or plumbing or roof leaks has occurred.

The major issues identified during the walk-through observations are:

- The exterior grade slopes toward the building in some locations. These semibasement areas have interior water damage below windowsills. Plaster should be removed, the condition of the masonry or concrete wall assessed, and site should be sloped away from the building. An electrical engineer or electrician should be consulted to address the outlets below the windowsills which have possibly been exposed to moisture.
- Plumbing leaks have damaged some ceilings and walls. Plaster should be removed in these locations and the structural framing assessed for water damage. Where plaster was already removed from the ceiling, there was no indication of joist damage due to plumbing leaks.
- Ceilings immediately adjacent to plumbing pipe runs in semibasement spaces have signs of water damage. Plaster should be removed to expose structural framing to be assessed for water damage.
- Safe attic access was unavailable during the walkthrough. Attic access should be provided for an assessment of the roof trusses.
- There were several areas of damaged second level ceiling in 9730 and one instance of damaged ceiling in 9710. These are likely indicative of roof leaks. It is likely that some sheathing replacement will be required at roof leaks. If structural trusses are damaged, new members may need to be sistered to existing members. Any damaged connections will need to be strengthened.
- An exterior canopy and an exterior historic light are in poor condition. If possible, the canopy should be replaced one-for-one in weight and shape. The historic light's mount is severely deteriorated. The area should be secured until it can be repaired or rebuilt.
- The buildings' downspouts are currently tied into the city drainage system. If drains are capped as part of the work, it is possible that new water entry paths may occur. Any change to the drainage system should be done in consultation with a civil engineer.

## 2 Project Description

Resurget Engineering PC was authorized by Intoto Studio to carry out a Condition Assessment of the existing buildings located at 9710 and 9730 West Outer Drive, Detroit, MI.

## 3 Project Team

Ben Ellefson, Architect/Principal and Nicole Fricke of Intoto Studio met Stacey Brown, PE (field observer) of Resurget Engineering, on site along with other team members and the building owner to conduct the walk-through survey.

## 4 Scope of Services

Resurget Engineering's scope of work for this project includes the Baseline Property Condition Assessment of the existing building structure. Using ASTM E2018-15 "Standard Guide for Property Condition Assessments: Baseline Property Condition Assessment Process" as a guideline for the walk-through survey and Report.

The purpose of the walk-through survey is to identify easily visible physical deficiencies to the building structural members and components. Physical deficiencies include conspicuous defects and moderate to severe damage or deterioration of structural members and their material. It specifically excludes deficiencies that may be remedied by routine maintenance, miscellaneous minor repairs, normal operating maintenance and members and conditions that are not visible or accessible during the walk-through survey.

The scope does not include any work related to ADA compliance or environmental hazardous materials. It does not include functionality, performance or condition of windows and doors. It does not address Mechanical, Electrical or Plumbing systems.

## 5 Condition Assessment

Per ASTM E2018-15 the Property Condition Assessment should include the following four components:

- Document review and interviews.
- Walk-through survey.
- Property condition report.

### 5.1 Building Description, Document Review and Interviews

In discussions with Intoto Studio, it was determined that no existing drawings or documentation on the building was available. Intoto Studio provided Resurget with concept level plans.

9710 and 9730 West Outer Drive are multifamily residential buildings including:

- Semibasement housing mechanical, electrical, and plumbing equipment, storage, laundry, and apartments.
- First and second level with apartments and a main hall.
- Vented attic space (inaccessible).
- Sloped, hipped roofs.

The exterior walls are constructed of structural brick above grade and concrete masonry units below grade. The roof dormers and gable ends of 9730 are wood-framed with wood siding.

9710 window and door openings are supported by steel lintels. 9730 window and door openings are supported by steel lintels and have flat brick arches above.

9710 has a small semi-circular canopy at its rear (parking) entrance and a shed-style brick attachment to the south end of the building.

9730 has bay windows on the first level down to the foundation. Its front entrance is inset.



The buildings were recently purchased from the owner of the past 40 years. Resurget learned that several tenant-caused leaks had occurred.

## 5.2 Walk-Through Survey

The objective of the walk-through survey is to visually observe the property to obtain information on structural material systems and components. During the walk-through survey, a reasonable effort was made to compile a photographic record of typical conditions present including easily visible material physical deficiencies.

An opinion on the physical condition of observed systems and components is provided. To clarify the meaning of an opinion, the terminology used is expanded to:

- Good Condition: In working condition and does not require immediate or short-term repairs.
- Fair Condition: In working condition but may require immediate or short-term repairs.
- Poor Condition: Not in working condition or requires immediate or short-term repairs.
- Very Poor Condition: severely deteriorated beyond repair requiring immediate replacement to restore to original condition.

A summary of the material systems, components, and items observed during the walk-through survey are listed below for each building.

### 5.3 9710 West Outer Drive



Fig-1 9710 Front (east) façade



Fig-3 9710 Rear (west) façade



Fig-2 9710 South façade



Fig-4 North facade





Fig-5 Typical lintel condition

### 5.3.1 Exterior Facade

In general, the exterior walls of common clay brick or stone are in good condition. The steel lintels above openings are in good condition.

See Fig-5.

#### Comments:

*In general, masonry is uncracked. Mortar joints appear to be sound. There is no evidence of excessive repointing. Bricks do not appear to be distressed. Refer to Fig-1 through Fig-4 on previous page.*

*Steel lintels at observable windows were painted. There was no evidence of cracking or repair at window corners. The steel lintels do not appear to be flaking, warped, or delaminated.*



Fig-6 Water-damaged plaster ceiling in locker room

### 5.3.2 Storage locker water damage

The ceiling in the storage locker areas shows signs of water damage. The ceiling should be removed to expose the existing joists. The joists should be assessed for localized water damage. If joists are in fair condition or worse a new member should be sistered to the existing damaged member.

See Fig-6.

#### Comments:

*Visible water damage is most likely caused by the visible plumbing stacks. It is anticipated that any structural damage to joists would be localized to the plumbing run.*




Fig-7 Exposed joists at previous area of water damage

### 5.3.3 Demolished Ceiling

It was reported that the building experience some plumbing leaks under the previous owner. The previous owner cut out the damaged plaster ceiling to expose the joists in some areas of damage.

Where exposed, the joists visually appear to be in good condition.

See Fig-7.

#### Comments:

*Joists bear directly on or are pocketed into the masonry wall. Pocketed joists would deteriorate when exposed to a wet masonry wall. Where visible, there was some slight water staining to the joists, but the joists did not appear to be water damaged.*



Fig-8 Damaged sill wall



Fig-9 Damaged sill wall with electrical outlet

### 5.3.4 Semibasement Sill Damage

The windows of the semibasement are typically about 4 inches above grade. Plaster below the sills is water-damaged and in poor condition. It should be removed to expose masonry. Once exposed, the masonry wall should be assessed for water damage.

Site regrading may be required to resolve water infiltration. The condition occurs where site slopes toward the building. A civil site engineer should be consulted for the regrading of the site.

Currently, both buildings' drainage systems are tied into the storm system. Water infiltration patterns may worsen if these ties are removed.

See Fig-8 and Fig-9.

#### **Comments:**

*Given the extent of damage, it is unlikely open windows caused the observed damage. Since the damage is concentrated under the sills, it is likely a combination of improperly sloped site and sill detailing.*

*Some windows have existing electrical outlets below them, and some of these outlets were visibly corroded.. While electrical systems are outside the scope of this report, we strongly recommend that an electrical engineer or electrician provide guidance on removal or repair of these outlets.*





Fig-10 Sump pit

### 5.3.5 Pit below stairs

There is what appears to be a sump pit below the front entry stairs. The pit appeared dry and in good condition during the walkthrough. The framing supporting the entry was in good condition. There was no sign of water infiltration in this space.

See Fig-10.



Fig-11 Attic access hatch is directly adjacent to stair landing.

### 5.3.6 Roof Truss Access and Water Damage

Truss space access was provided via an attic hatch directly adjacent to the stair rail. Given the difficult corner location and proximity to a large fall potential, no one on the walkthrough team thought it was safe to access the attic.

Water-damaged plaster was observed adjacent to the south stair. Other than this one location, the ceiling was in good condition.

Without access to the attic space, it is difficult to tell the extent of roof structure damage at the water-damaged plaster. Safe access to the attic should be secured so that a walkthrough of the trusses and roof sheathing can be performed from the attic space.

See Fig-11 and Fig-12.

#### **Comments:**

*The observed area of damage was small (2-4 sf). It is possible that roof, roof sheathing, or roof trusses could be damaged due to long-term water infiltration.*

*Safe access to the attic should be provided. The area of damaged plaster should be removed, and any adjacent structural material should be checked for water damage.*




Fig-12 Damaged plaster indicates roof water infiltration.



Fig-13 Rear canopy

### 5.3.7 Rear Canopy

The canopy is in poor condition and should be replaced. The turnbuckle bar is in fair condition.

The adjacent brick masonry appears water damaged. The brick should be cleaned and repointed. Any deteriorating brick should be repaired or replaced.

See Fig-13.

#### **Comments:**

*The rear entry canopy is severely corroded. The deck edge has rusted away in some places. The ribs supporting the canopy have also deteriorated.*

*The adequacy of the canopy connection to the structure was not analyzed as part of this assessment. We recommend a one-for-one size and weight replacement of the existing canopy to avoid structural work.*



Fig-14 Utility cap in sidewalk

### 5.3.8 Utility Cap in Sidewalk

While not structural, it was noted that a gas utility cap was partially embedded in the front entry sidewalk, creating a trip hazard.

See Fig-14.



## 5.4 9730 West Outer Drive



Fig-15 9730 front (east) façade



Fig-17 9710 rear (west) façade



Fig-16 9710 south façade



Fig-18 north facade



Fig-19 Damage plaster at semibasement




Fig-20 damage at semibasement

## 5.4.1 Semibasement Sill Damage

The windows of the semibasement are typically about 4 inches above grade. Plaster below the sills is water-damaged and in poor condition. It should be removed to expose masonry. Once exposed, the masonry wall should be assessed for water damage.

Site regrading may be required to resolve water infiltration. The condition occurs where site slopes toward the building. A civil site engineer should be consulted for the regrading of the site.

Currently, both buildings' drainage systems are tied into the storm system. Water infiltration patterns may worsen if these ties are removed.

See Fig-19 and Fig-20.

### **Comments:**

*Given the extent of damage, it is unlikely open windows caused the observed damage. Since the damage is concentrated under the sills, it is likely a combination of improperly sloped site and sill detailing.*

*Some windows have existing electrical outlets below them, and some of these outlets were visibly corroded. While electrical systems are outside the scope of this report, we strongly recommend that an electrical engineer or electrician provide guidance on removal or repair of these outlets.*





Fig-21 Exterior guardrail at loading docks damaged



Fig-22 Apartment 209 kitchen ceiling water damage



Fig-23 Apartment 209 living room damage

## 5.4.2 Water damage due to leaks

In several areas, the ceiling has been damaged and subsequently removed due to plumbing leaks. Where structure was visible in these areas, it did not appear that there was any damage to the wood joists, which would be consistent with a short-term leak. The ceiling in these areas should be repaired. Notify Intoto of any soft spots in the wood during repair.

On the highest level, water-damaged plaster ceilings are most likely caused by roof leaks. Structural damage to roof sheathing and/or roof trusses is likely at the large leaks in the living room and kitchen of unit 209.

Without access to the attic space, the extent of roof structure damage at the water-damaged plaster is unknown. A walkthrough of the attic space should be performed after safe access is provided.

See Fig-21 through Fig-25.

### Comments:

*Generally, short duration high volume events (such as a ruptured pipe) will damage plaster but not impact the integrity of solid wood framing. Wood joists tend to be damaged from prolonged exposure to moisture, as is usually found in roof leaks.*

*Water-damaged sheathing should be removed and replaced. Cut sheathing to span to next adjacent truss.*

*Water-damaged trusses require condition assessments. Solutions include sistering of damaged members and strengthening of damaged connections.*



Fig-24 Mechanical room water damage. Sister water damaged joist.



Fig-25 Ceiling water damage. Remove to expose existing structure.



Fig-26 Water damage at corner of bay window matches exterior repointing.

### 5.4.3 Damage at bay window

In general, the bay windows are in good condition. One bay window shows signs of water damage. The exterior at this location has been repointed. Remove plaster to expose wood framing. Replace or sister damaged wood framing. Repair process should also locate and address location of water infiltration to prevent recurring damage.

See Fig-26.



Fig-27 Attic access

### 5.4.4 Roof Truss Access and Water Damage

Truss space access was provided via an attic hatch directly adjacent to the stair rail. Given the difficult corner location and proximity to a large fall potential, no one on the walkthrough team thought it was safe to access the attic.

Without access to the attic space, it is difficult to tell the extent of roof structure. Safe access to the attic should be secured so that a walkthrough of the trusses and roof sheathing can be performed from the attic space.

See Fig-27.

#### **Comments:**

*There are several areas of damaged ceiling on the second level of the building. These are likely related to roof leaks above. The extent of damage cannot be determined without either exposing the structure from below or providing safe roof access. Additionally, there was no access to any of the roof dormers during the walkthrough.*





Fig-28 Water damage at window ac units

#### 5.4.5 Water Damage at sills due to air conditioning units

Several apartments had window mounted air conditioning units. Many of the units had signs of water damage below the sills. The damaged plaster should be removed to expose the condition of the wood stud wall.

See Fig-28.

**Comments:**

*In most cases, removing the window air conditioner and shutting the window will remove the water entry path. Depending on how long the unit has been installed, there may be water damage to wall studs below the window.*



Fig-29 Damaged joist at mechanical room piping

#### 5.4.6 Joist damaged by pipe penetrations.

A notched joist in the mechanical room does not have any remaining structural capacity. A new piece of 2x lumber should be sistered to the far side of the joist. Extend the new piece either to the end of the existing joist or 2 feet past areas of water staining. Glue and nail the new joist to the existing joist.

See Fig-29.

**Comments:**

*The intent with this repair is to restore some capacity to the joist. It is understood that the depth of the new joist will be limited by plumbing conflicts. It is our experience that a single failed joist will not cause a local collapse. Above, this is likely a "soft spot" in the floor that a user would notice.*



Fig-30 Water damage at window ac units



Fig-31 Typical joist condition at exposed ceilings



Fig-32 Downspout

#### 5.4.7 Typical Building condition

Overall, the building is in good condition. Even in presumed areas of previous plumbing flooding, the joists do not show signs of deterioration.

See Fig-30 and Fig-31.

#### 5.4.8 Downspout tie in

The downspouts on 9710 and 9730 are currently tied into the city sewer system. If these downspouts need to be capped, a civil engineer should be engaged to ensure proper site drainage.

See Fig-32.

##### **Comments:**

*Additional water on the site may lead to increased water infiltration into the building, especially at semibasement windowsills. In all cases, grade should be sloped away from the building. However, if downspouts need to be capped, the amount of water infiltrating the building may be increased and more invasive waterproofing measures may need to be considered.*





Fig-33 Entry

## 5.4.9 Front entry

The front entry landing is damaged and needs repair. In general, these repairs are architectural in nature.

The historic light hanging above the front entry is in fair condition. Flaking paint and rust should be removed to expose remaining metal. If there is significant section loss, light should be removed until a restoration strategy can be implemented.

See Fig-33 and Fig-34.



Fig-34 Historic light fixture with flaking paint and possible corrosion.

# Structural Assessment Report Visual Inspection Checklist

## Part 1: Property Description

### Type of Construction:

|                   |              |
|-------------------|--------------|
| <u>Wood Frame</u> | Brick        |
| Steel Frame       | Stone        |
| Concrete          | Other (List) |

### Building Classification:

|                    |            |
|--------------------|------------|
| <u>Residential</u> | Government |
| Commercial         | Religious  |
| Institutional      | Industrial |

### Characteristics:

|                            |                |                        |                   |                    |             |              |
|----------------------------|----------------|------------------------|-------------------|--------------------|-------------|--------------|
| <u>Building Age:</u>       | 0-25yrs        | 25-120 yrs             | <u>50-100yrs</u>  | 100 + yrs          |             |              |
| <u>Foundation:</u>         | Pier           | Slab                   | Chain Wall        | <u>Basement</u>    | Other       |              |
| <u>Roof Type:</u>          | <u>Hipped</u>  | <u>Gable</u>           | Mansard           | Pyramid            | <u>Flat</u> | Other        |
| <u>Roof Cover:</u>         | Slate          | Metal                  | Tile              | <u>Asphalt</u>     | Asbestos    | <u>Other</u> |
| <u>Wall Finish:</u>        | Stucco         | Wood                   | Vinyl             | <u>Masonry</u>     | Asbestos    | Other        |
| <u>Landscape:</u>          | <u>Walkway</u> | <u>Driveway</u>        | Fences            | Sculpture/Fountain | Structures  |              |
| <u>Interior Condition:</u> | Mold/Mildew    | <u>Falling Plaster</u> | Structural Damage | Other              |             |              |

### Flood Data:

|  |          |         |             |             |       |
|--|----------|---------|-------------|-------------|-------|
| <u>Nature of Water</u>                               | Standing | Flowing | Seepage     | Water Marks | Other |
| <u>Space where water entered</u>                     | Basement | Crawl   | First Floor | Roof        | Other |
| <u>Depth of water measured from main floor (+/-)</u> | _____    |         |             |             |       |

### Evaluation:

|   |              |                 |        |
|---|--------------|-----------------|--------|
| <u>Collapsed or off Foundation</u>                | Minor        | Moderate        | Severe |
| <u>Leaning/Other Structural Damage</u>            | Minor        | Moderate        | Severe |
| <u>Damage to Window/Doors</u>                     | Minor        | <u>Moderate</u> | Severe |
| <u>Chimney, parapet, or other falling hazards</u> | <u>Minor</u> | Moderate        | Severe |
| <u>Roof Damage</u>                                | Minor        | <u>Moderate</u> | Severe |
| <u>Foundation Damage</u>                          | Minor        | Moderate        | Severe |
| <u>Damaged Cladding: Material _____</u>           | <u>Minor</u> | Moderate        | Severe |
| <u>Damaged Electrical/Mechanical/AC Systems</u>   | Minor        | Moderate        | Severe |
| <u>Landscape damage</u>                           | Minor        | Moderate        | Severe |

### Estimate Building Damage:

|            |         |
|------------|---------|
| None       | 30-60%  |
| <u>10%</u> | 60-90%  |
| 1-30%      | 90-100% |



## Part 2: Structural Assessment

### 1. Structural plans and details:

- a) Description of the site and its structures Combined lot with (2) multifamily residential buildings, surface parking lot, and garage (not in scope)
- b) Description of the foundation system Concrete semi-basement level
- c) Description of the structural system (including story height) (2) stories of wood stud construction

### 2. Presence of critical structures and structures without redundancies:

(i.e. transfer girders, small/ narrow/ slender columns, cantilever structures, long span structures, cable structures, timber structures, etc.) NA

### 3. Loading:

- a) Compatibility of existing usage with the design loading Currently unoccupied; proposed use is compatible
- b) Deviation from intended use or supporting higher design imposed loads NA
- c) Signs of overloading (to show affected locations on plan) None

### 4. Addition and Alteration works:

- a) Presence of Additions and Alterations Shed-style brick attachment on south end (9710)
- b) Impact of Additions and Alterations on the building structure None

### 5. Signs of structural defects and deterioration:

- a) Building tilt/ settlement NA
- b) Structural deformation NA
- c) Major structural defects (e.g. structural cracks, decayed timber member) NA
- d) Minor structural defects Rear Canopy (9710)
- e) Non-structural defects Water damage at basement sills and second level ceilings

### 6. Termite Attack:

- a) Need for inspection by anti-termite specialist NA
- b) Need for termite treatment by anti-termite specialist NA

### 7. Exposure to aggressive environment:

- a) Immersed in water – Columns and Basement, or Leaks in Roof NA
- b) Aggressive chemical which may accelerate the deterioration of structural elements, particularly in industrial buildings NA

### 8. Retaining walls and slope protection structures:

- a) Defects of retaining wall and other slope protection structures (e.g. cracks, tilt, displacement) NA
- b) Signs of undesirable condition surrounding retaining wall (e.g. tension cracks in soil, presence of big trees nearby, inadequate surface, drainage) NA

### 9. Safety Barriers (i.e. parapets & railings):


- a) Any defects NA

10) Record of previous strengthening works done NA

**Production Specifications:**


Panel dimensions and spaces expressed as center-to-center of wires.

- Core Wire: Nominal 10.5g (0.128" +/- 0.002" before welding)
- Dimensional Tolerance: +/- 1/4"
- Spacing Tolerance: +/- 1/16"
- Permissible Vertical Bow: 2" →
- Permissible Wire Straightness Deviation: 1/16"
- Selvage Trim: 0 min / 1/32" max
- Shear Tabs: 0 min / 1/8" max
- Est. weight per panel: 134.35 lbs



Customer Drawing Approval:

Name: \_\_\_\_\_ Date: \_\_\_\_\_




**Galvanized - Compliant to ASTM A-641**

**PVC Coating - Compliant to ASTM**

**A-974**

→ 0.5" SPCS



**IF IN DOUBT-ASK**

|  |          | LTR  | REVISION         |          | ECN  | APP             | DATE |
|--|----------|--|------------------|----------|--|-----------------|------|
| THIS DRAWING IS THE PROPERTY OF RIVERDALE MILLS CORPORATION AND CONTAINS PROPRIETARY INFORMATION PROTECTED BY COPYRIGHT AND/OR TRADE SECRET LAWS. NEITHER THIS DRAWING NOR ITS CONTENTS MAY BE DISCLOSED OR REPRODUCED BY ANY MEANS WHATSOEVER, IN WHOLE OR IN PART, WITHOUT THE PRIOR, WRITTEN CONSENT OF RIVERDALE MILLS CORP. | MATERIAL | 10.5G PLAIN STEEL, GAW, BLACK PVC WELDED WIRE MESH | DRAWN            | DATE     | <b>RIVERDALE</b><br>RIVERDALE MILLS CORPORATION<br>NORTHBRIDGE, MA 01534 |                 |      |
|  |          |  | JMH              | 6/6/18   |  |                 |      |
|  | CUSTOMER |  | CHECKED          | APPROVED | TITLE  |                 |      |
| FILE: P053010587012F1  |          | DIMENSIONS SHOWN ARE AFTER PLATING OR FINISHING.   | SCALE            | NTS      | DWG NO.  | P053010587012F1 | REV. |
|  |          |  | DO NOT SCALE DWG |          |  |                 |      |





SKU  
BVE808


Job Name:  
Mark:  
Submitted By:  
Date: 10/18/2021

## Extruded Aluminum Brick Vent, 8 In Sq



Brick vents provide a permanent means of ventilation for crawl spaces, hung ceilings, incinerator rooms, chimney flues, foundations, pipe spaces and corridors. Extruded construction provides a quality finished appearance. A high water stop at the rear and deep overlapping blades with storm stops provide maximum resistance to rain and weather.

- Anodized aluminum construction
- Built in aluminum mesh insect screen



| A        | B       | C    |
|----------|---------|------|
| 8.125 in | 7.75 in | 4 in |

### Performance Characteristics

No Fan Curve Available.

### Construction Features

|                |                                      |
|----------------|--------------------------------------|
| Frame Material | Heavy gauge extruded 6063T5 aluminum |
| Frame Gauge    | 0.125                                |
| Frame Type     | No Flange                            |
| Blade Material | Heavy gauge extruded 6063T5 aluminum |
| Blade Gauge    | 0.125                                |

### California Residents

**⚠ WARNING**

This product can expose you to chemicals including cadmium used in the processing of corrosion resistant metal and fasteners, which is known to the State of California to cause cancer and birth defects or other reproductive harm. For more information visit [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)



MICHIGAN OWNED



MICHIGAN MADE



# SMART BRICK



## FARMINGTON HILLS LOCATION

22005 GILL RD  
FARMINGTON HILLS, MI 48335  
OFFICE (248) 474-3211  
FAX (248) 474-8110



## ANN ARBOR LOCATION

3285 W LIBERTY RD  
ANN ARBOR, MI 48103  
OFFICE (734) 663-4277  
FAX (734) 663-6515





**DESIGN SPECIFICATIONS**

Smart Brick CMU's are manufactured to exceed existing ASTM specifications for compressive strength, absorption, dimensions, and aggregates. Consult your Fendt sales representative for specific information.

**SHAPES & SIZES**

Smart Brick CMU's are manufactured in a variety of thicknesses and shapes to facilitate proper masonry construction. See diagrams and listings for dimensions and available fittings.



**COLORS**

Smart Brick CMU's are manufactured in a variety of colors, including standard grey, solid colors, and blended colors. Custom colors are available where project size warrants. Color selection should be made from actual block chip/sample, and should take into account permissible shade variations that are inherent with concrete masonry products.

**WATER REPELLENCY**


Various water repellent systems are available for concrete masonry units, including integral repellents and exterior surface-applied sealants. Contact your Fendt sales representative for more information.

**CLEANING**

All specialty concrete masonry units shall be cleaned with a mild solution of a masonry cleaner to remove normal stains and any efflorescence which may occur with any new masonry construction.

**INSULATION**

Smart Brick CMU's are available with factory-installed polystyrene inserts, or may be insulated on-site with granular-fill insulation. Contact your Fendt sales representative for more information.



**AVAILABLE SIZES**

- 4" x 4" x 8"
- 4" x 4" x 12"
- 4" x 4" x 16"
- 8" x 4" x 16"
- 12" x 4" x 16"

**FIRE RATINGS**

Fendt Builder's Supply, Inc. will provide written certification verifying the fire-rating on any unit, in compliance with the design criteria accepted by the Michigan State Fire Marshall, outlined in the Michigan Masonry Council's Tech Bulletin 1.1, Oct. 1977, "Recommended Practices for the Specification of Fire Resistance Ratings".



**FARMINGTON HILLS LOCATION**

22005 GILL RD  
 FARMINGTON HILLS, MI 48335  
 OFFICE (248) 474-3211  
 FAX (248) 474-8110



**ANN ARBOR LOCATION**

3285 W LIBERTY RD  
 ANN ARBOR, MI 48103  
 OFFICE (734) 663-4277  
 FAX (734) 663-6515







## Ordering Information

### Accessories

Ordered and shipped separately.




|                    |   |
|--------------------|---|
| DLL127F 1.5 JU     | Photocell - SSL twist-lock (120-277V) <sup>24</sup>                                     |
| DLL347F 1.5 CUL JU | Photocell - SSL twist-lock (347V) <sup>24</sup>   |
| DLL480F 1.5 CUL JU | Photocell - SSL twist-lock (480V) <sup>24</sup>   |
| DSHORT SBK U       | Shorting cap <sup>24</sup>  |
| DSX0HS 20C U       | House-side shield for P1,P2,P3 and P4 <sup>22</sup>                                     |
| DSX0HS 30C U       | House-side shield for P10,P11,P12 and P13 <sup>22</sup>                                 |
| DSX0HS 40C U       | House-side shield for P5,P6 and P7 <sup>22</sup>  |
| DSX0DDL U          | Diffused drop lens (polycarbonate) <sup>22</sup>  |
| PUMBA DDBXD U*     | Square and round pole universal mounting bracket adaptor (specify finish) <sup>23</sup> |
| KMA8 DDBXD U       | Mast arm mounting bracket adaptor (specify finish) <sup>23</sup>                        |
| DSX0EGS (FINISH) U | External glare shield   |

For more control options, visit [DTL](#) and [ROAM](#) online. Link to [nLight Air 2](#)

### NOTES



- 1 HA not available with P4, P7, and P13.
- 2 P10, P11, P12 and P13 and rotated options (L90 or R90) only available together.
- 3 Any Type 5 distribution with photocell, is not available with WBA.
- 4 Not available with HS or DDL.
- 5 MVOLT driver operates on any line voltage from 120-277V (50/60 Hz).
- 6 Single fuse (SF) requires 120V, 277V or 347V. Double fuse (DF) requires 208V, 240V or 480V. XVOLT not available with fusing (SF or DF).
- 7 XVOLT only suitable for use with P4, P7 and P13.
- 8 XVOLT operates with any voltage between 277V and 480V.
- 9 XVOLT not available with fusing (SF or DF) and not available with PIR, PIRH, PIR1FC3V, PIRH1FC3V.
- 10 Suitable for mounting to round poles between 3.5" and 12" diameter.
- 11 Universal mounting brackets intended for retrofit on existing pre-drilled poles only. 1.5 G vibration load rating per ANCI C136.31. Only usable when pole's drill pattern is NOT Lithonia template #8.
- 12 Must order fixture with SPA mounting. Must be ordered as a separate accessory; see Accessories information. For use with 2-3/8" diameter mast arm (not included).
- 13 Must be ordered with PIRHN.
- 14 Sensor cover available only in dark bronze, black, white and natural aluminum colors.
- 15 Must be ordered with NLTAIR2. For more information on nLight Air 2 visit [this link](#).
- 16 Photocell ordered and shipped as a separate line item from Acuity Brands Controls. See accessories. Shorting Cap included.
- 17 If ROAM<sup>®</sup> node required, it must be ordered and shipped as a separate line item from Acuity Brands Controls. Shorting Cap included.
- 18 DMG not available with PIRHN, PER5, PER7, PIR, PIRH, PIR1FC3V or PIRH1FC3V, FAO.
- 19 Reference Controls Options table on page 4.
- 20 Reference Motion Sensor Default Table on page 4 to see functionality.
- 21 Not available with other dimming controls options.
- 22 Not available with BLC, LCCO and RCCO distribution.
- 23 Must be ordered with fixture for factory pre-drilling.
- 24 Requires luminaire to be specified with PER, PER5 or PER7 option. See Controls Table on page 4.
- 25 For retrofit use only. Only usable when pole's drill pattern is NOT Lithonia template #8

## EGS – External Glare Shield



## Drilling

### HANDHOLE ORIENTATION (from top of pole)



### Tenon Mounting Slipfitter

| Tenon O.D. | Mounting | Single Unit | 2 @ 180   | 2 @ 90    | 3 @ 90    | 3 @ 120   | 4 @ 90    |
|------------|----------|-------------|-----------|-----------|-----------|-----------|-----------|
| 2-3/8"     | RPA      | AS3-5 190   | AS3-5 280 | AS3-5 290 | AS3-5 390 | AS3-5 320 | AS3-5 490 |
| 2-7/8"     | RPA      | AST25-190   | AST25-280 | AST25-290 | AST25-390 | AST25-320 | AST25-490 |
| 4"         | RPA      | AST35-190   | AST35-280 | AST35-290 | AST35-390 | AST35-320 | AST35-490 |

| Mounting Option                                  | Drilling Template | Single | 2 @ 180    | 2 @ 90     | 3 @ 90        | 3 @ 120         | 4 @ 90           |
|--|-------------------|--------|------------|------------|---------------|-----------------|------------------|
| Head Location                                    |                   | Side B | Side B & D | Side B & C | Side B, C & D | Round Pole Only | Side A, B, C & D |
| Drill Nomenclature                               | #8                | DM19AS | DM28AS     | DM29AS     | DM39AS        | DM32AS          | DM49AS           |
| <b>Minimum Acceptable Outside Pole Dimension</b> |                   |        |            |            |               |                 |                  |
| SPA  | #8                | 2-7/8" | 2-7/8"     | 3.5"       | 3.5"          |                 | 3.5"             |
| RPA  | #8                | 2-7/8" | 2-7/8"     | 3.5"       | 3.5"          | 3"              | 3.5"             |
| SPUMBA   | #5                | 2-7/8" | 3"         | 4"         | 4"            |                 | 4"               |
| RPUMBA   | #5                | 2-7/8" | 3.5"       | 5"         | 5"            | 3.5"            | 5"               |

### DSX0 Area Luminaire - EPA



\*Includes luminaire and integral mounting arm. Other tenons, arms, brackets or other accessories are not included in this EPA data.

| Fixture Quantity & Mounting Configuration | Single DM19 | 2 @ 180 DM28 | 2 @ 90 DM29 | 3 @ 90 DM39 | 3 @ 120 DM32 | 4 @ 90 DM49 |
|---|-------------|--------------|-------------|-------------|--------------|-------------|
| Mounting Type                             |             |              |             |             |              |             |
| DSX0 LED                                  | 0.950       | 1.900        | 1.830       | 2.850       | 2.850        | 3.544       |




Isofootcandle plots for the DSX0 LED 40C 1000 40K. Distances are in units of mounting height (20').


**LEGEND**




Test No.




Test No.




Test No. LTL23457P25 tested in accordance with IESNA LM-79-08.




Test No. LTL23457P25 tested in accordance with IESNA LM-79-08.




Test No. LTL23457P25 tested in accordance with IESNA LM-79-08.




Test No.




Test No.




Test No.




Test No.




Test No.




Test No. LTL23451P25 tested in accordance with IESNA LM-79-08.



Test No.



Test No.



Test No.

## Performance Data

### Lumen Ambient Temperature (LAT) Multipliers

Use these factors to determine relative lumen output for average ambient temperatures from 0-40°C (32-104°F).

| Ambient     |             | Lumen Multiplier |
|-------------|-------------|------------------|
| 0°C         | 32°F        | 1.04             |
| 5°C         | 41°F        | 1.04             |
| 10°C        | 50°F        | 1.03             |
| 15°C        | 59°F        | 1.02             |
| 20°C        | 68°F        | 1.01             |
| <b>25°C</b> | <b>77°C</b> | <b>1.00</b>      |
| 30°C        | 86°F        | 0.99             |
| 35°C        | 95°F        | 0.98             |
| 40°C        | 104°F       | 0.97             |

### Projected LED Lumen Maintenance

Data references the extrapolated performance projections for the platforms noted in a **25°C ambient**, based on 10,000 hours of LED testing (tested per IESNA LM-80-08 and projected per IESNA TM-21-11).

To calculate LLF, use the lumen maintenance factor that corresponds to the desired number of operating hours below. For other lumen maintenance values, contact factory.

| Operating Hours | Lumen Maintenance Factor |
|-----------------|--------------------------|
| 25,000          | 0.96                     |
| 50,000          | 0.92                     |
| 100,000         | 0.85                     |

#### Motion Sensor Default Settings

| Option                 | Dimmed State    | High Level (when triggered) | Photocell Operation | Dwell Time | Ramp-up Time | Ramp-down Time |
|------------------------|-----------------|-----------------------------|---------------------|------------|--------------|----------------|
| PIR or PIRH            | 3V (37%) Output | 10V (100%) Output           | Enabled @ 5FC       | 5 min      | 3 sec        | 5 min          |
| *PIR1FC3V or PIRH1FC3V | 3V (37%) Output | 10V (100%) Output           | Enabled @ 1FC       | 5 min      | 3 sec        | 5 min          |

\*for use when motion sensor is used as dusk to dawn control.

### Electrical Load

|                                      |                     |           |               |         | Current (A) |      |      |      |      |      |
|--------------------------------------|---------------------|-----------|---------------|---------|-------------|------|------|------|------|------|
|                                      | Performance Package | LED Count | Drive Current | Wattage | 120         | 208  | 240  | 277  | 347  | 480  |
| Forward Optics (Non-Rotated)         | P1                  | 20        | 530           | 38      | 0.32        | 0.18 | 0.15 | 0.15 | 0.10 | 0.08 |
|                                      | P2                  | 20        | 700           | 49      | 0.41        | 0.23 | 0.20 | 0.19 | 0.14 | 0.11 |
|                                      | P3                  | 20        | 1050          | 71      | 0.60        | 0.37 | 0.32 | 0.27 | 0.21 | 0.15 |
|                                      | P4                  | 20        | 1400          | 92      | 0.77        | 0.45 | 0.39 | 0.35 | 0.28 | 0.20 |
|                                      | P5                  | 40        | 700           | 89      | 0.74        | 0.43 | 0.38 | 0.34 | 0.26 | 0.20 |
|                                      | P6                  | 40        | 1050          | 134     | 1.13        | 0.65 | 0.55 | 0.48 | 0.39 | 0.29 |
|                                      | P7                  | 40        | 1300          | 166     | 1.38        | 0.80 | 0.69 | 0.60 | 0.50 | 0.37 |
| Rotated Optics (Requires L90 or R90) | P10                 | 30        | 530           | 53      | 0.45        | 0.26 | 0.23 | 0.21 | 0.16 | 0.12 |
|                                      | P11                 | 30        | 700           | 72      | 0.60        | 0.35 | 0.30 | 0.27 | 0.20 | 0.16 |
|                                      | P12                 | 30        | 1050          | 104     | 0.88        | 0.50 | 0.44 | 0.39 | 0.31 | 0.23 |
|                                      | P13                 | 30        | 1300          | 128     | 1.08        | 0.62 | 0.54 | 0.48 | 0.37 | 0.27 |

### Controls Options

| Nomenclature  | Description   | Functionality   | Primary control device  | Notes  |
|---------------|---|---|---|--|
| FAO           | Field adjustable output device installed inside the luminaire; wired to the driver dimming leads. | Allows the luminaire to be manually dimmed, effectively trimming the light output.  | FAO device  | Cannot be used with other controls options that need the 0-10V leads                                 |
| DS            | Drivers wired independently for 50/50 luminaire operation   | The luminaire is wired to two separate circuits, allowing for 50/50 operation.  | Independently wired drivers   | Requires two separately switched circuits. Consider nLight AIR as a more cost effective alternative. |
| PERS or PER7  | Twist-lock photocell receptacle   | Compatible with standard twist-lock photocells for dusk to dawn operation, or advanced control nodes that provide 0-10V dimming signals.              | Twist-lock photocells such as DLL Elite or advanced control nodes such as ROAM. | Pins 4 & 5 to dimming leads on driver, Pins 6 & 7 are capped inside luminaire                        |
| PIR or PIRH   | Motion sensors with integral photocell. PIR for 8-15' mounting; PIRH for 15-30' mounting          | Luminaires dim when no occupancy is detected.   | Acuity Controls SBGR  | Also available with PIRH1FC3V when the sensor photocell is used for dusk-to-dawn operation.          |
| NLTAIR2 PIRHN | nLight AIR enabled luminaire for motion sensing, photocell and wireless communication.            | Motion and ambient light sensing with group response. Scheduled dimming with motion sensor over-ride when wirelessly connected to the nLight Eclipse. | nLight Air rSDGR  | nLight AIR sensors can be programmed and commissioned from the ground using the CIAIRity Pro app.    |



# Performance Data

## Lumen Output

Lumen values are from photometric tests performed in accordance with IESNA LM-79-08. Data is considered to be representative of the configurations shown, within the tolerances allowed by Lighting Facts. Contact factory for performance data on any configurations not shown here.

| Forward Optics |           |               |              |            |                      |   |   |   |     |                      |   |   |   |     |                      |   |   |   |     |
|----------------|-----------|---------------|--------------|------------|----------------------|---|---|---|-----|----------------------|---|---|---|-----|----------------------|---|---|---|-----|
| Power Package  | LED Count | Drive Current | System Watts | Dist. Type | 30K (3000 K, 70 CRI) |   |   |   |     | 40K (4000 K, 70 CRI) |   |   |   |     | 50K (5000 K, 70 CRI) |   |   |   |     |
|                |           |               |              |            | Lumens               | B | U | G | LPW | Lumens               | B | U | G | LPW | Lumens               | B | U | G | LPW |
| P1             | 20        | 530           | 38W          | T1S        | 4,369                | 1 | 0 | 1 | 115 | 4,706                | 1 | 0 | 1 | 124 | 4,766                | 1 | 0 | 1 | 125 |
|                |           |               |              | T2S        | 4,364                | 1 | 0 | 1 | 115 | 4,701                | 1 | 0 | 1 | 124 | 4,761                | 1 | 0 | 1 | 125 |
|                |           |               |              | T2M        | 4,387                | 1 | 0 | 1 | 115 | 4,726                | 1 | 0 | 1 | 124 | 4,785                | 1 | 0 | 1 | 126 |
|                |           |               |              | T3S        | 4,248                | 1 | 0 | 1 | 112 | 4,577                | 1 | 0 | 1 | 120 | 4,634                | 1 | 0 | 1 | 122 |
|                |           |               |              | T3M        | 4,376                | 1 | 0 | 1 | 115 | 4,714                | 1 | 0 | 1 | 124 | 4,774                | 1 | 0 | 1 | 126 |
|                |           |               |              | T4M        | 4,281                | 1 | 0 | 1 | 113 | 4,612                | 1 | 0 | 2 | 121 | 4,670                | 1 | 0 | 2 | 123 |
|                |           |               |              | TFTM       | 4,373                | 1 | 0 | 1 | 115 | 4,711                | 1 | 0 | 2 | 124 | 4,771                | 1 | 0 | 2 | 126 |
|                |           |               |              | TSVS       | 4,548                | 2 | 0 | 0 | 120 | 4,900                | 2 | 0 | 0 | 129 | 4,962                | 2 | 0 | 0 | 131 |
|                |           |               |              | T5S        | 4,552                | 2 | 0 | 0 | 120 | 4,904                | 2 | 0 | 0 | 129 | 4,966                | 2 | 0 | 0 | 131 |
|                |           |               |              | T5M        | 4,541                | 3 | 0 | 1 | 120 | 4,891                | 3 | 0 | 1 | 129 | 4,953                | 3 | 0 | 1 | 130 |
|                |           |               |              | TSW        | 4,576                | 3 | 0 | 2 | 120 | 4,929                | 3 | 0 | 2 | 130 | 4,992                | 3 | 0 | 2 | 131 |
|                |           |               |              | BLC        | 3,586                | 1 | 0 | 1 | 94  | 3,863                | 1 | 0 | 1 | 102 | 3,912                | 1 | 0 | 1 | 103 |
|                |           |               |              | LCCO       | 2,668                | 1 | 0 | 1 | 70  | 2,874                | 1 | 0 | 2 | 76  | 2,911                | 1 | 0 | 2 | 77  |
|                |           |               |              | RCCO       | 2,668                | 1 | 0 | 1 | 70  | 2,874                | 1 | 0 | 2 | 76  | 2,911                | 1 | 0 | 2 | 77  |
| P2             | 20        | 700           | 49W          | T1S        | 5,570                | 1 | 0 | 1 | 114 | 6,001                | 1 | 0 | 1 | 122 | 6,077                | 2 | 0 | 2 | 124 |
|                |           |               |              | T2S        | 5,564                | 1 | 0 | 2 | 114 | 5,994                | 1 | 0 | 2 | 122 | 6,070                | 2 | 0 | 2 | 124 |
|                |           |               |              | T2M        | 5,593                | 1 | 0 | 1 | 114 | 6,025                | 1 | 0 | 1 | 123 | 6,102                | 1 | 0 | 1 | 125 |
|                |           |               |              | T3S        | 5,417                | 1 | 0 | 2 | 111 | 5,835                | 1 | 0 | 2 | 119 | 5,909                | 2 | 0 | 2 | 121 |
|                |           |               |              | T3M        | 5,580                | 1 | 0 | 2 | 114 | 6,011                | 1 | 0 | 2 | 123 | 6,087                | 1 | 0 | 2 | 124 |
|                |           |               |              | T4M        | 5,458                | 1 | 0 | 2 | 111 | 5,880                | 1 | 0 | 2 | 120 | 5,955                | 1 | 0 | 2 | 122 |
|                |           |               |              | TFTM       | 5,576                | 1 | 0 | 2 | 114 | 6,007                | 1 | 0 | 2 | 123 | 6,083                | 1 | 0 | 2 | 124 |
|                |           |               |              | TSVS       | 5,799                | 2 | 0 | 0 | 118 | 6,247                | 2 | 0 | 0 | 127 | 6,327                | 2 | 0 | 0 | 129 |
|                |           |               |              | T5S        | 5,804                | 2 | 0 | 0 | 118 | 6,252                | 2 | 0 | 0 | 128 | 6,332                | 2 | 0 | 1 | 129 |
|                |           |               |              | T5M        | 5,789                | 3 | 0 | 1 | 118 | 6,237                | 3 | 0 | 1 | 127 | 6,316                | 3 | 0 | 1 | 129 |
|                |           |               |              | TSW        | 5,834                | 3 | 0 | 2 | 119 | 6,285                | 3 | 0 | 2 | 128 | 6,364                | 3 | 0 | 2 | 130 |
|                |           |               |              | BLC        | 4,572                | 1 | 0 | 1 | 93  | 4,925                | 1 | 0 | 1 | 101 | 4,987                | 1 | 0 | 1 | 102 |
|                |           |               |              | LCCO       | 3,402                | 1 | 0 | 2 | 69  | 3,665                | 1 | 0 | 2 | 75  | 3,711                | 1 | 0 | 2 | 76  |
|                |           |               |              | RCCO       | 3,402                | 1 | 0 | 2 | 69  | 3,665                | 1 | 0 | 2 | 75  | 3,711                | 1 | 0 | 2 | 76  |
| P3             | 20        | 1050          | 71W          | T1S        | 7,833                | 2 | 0 | 2 | 110 | 8,438                | 2 | 0 | 2 | 119 | 8,545                | 2 | 0 | 2 | 120 |
|                |           |               |              | T2S        | 7,825                | 2 | 0 | 2 | 110 | 8,429                | 2 | 0 | 2 | 119 | 8,536                | 2 | 0 | 2 | 120 |
|                |           |               |              | T2M        | 7,865                | 2 | 0 | 2 | 111 | 8,473                | 2 | 0 | 2 | 119 | 8,580                | 2 | 0 | 2 | 121 |
|                |           |               |              | T3S        | 7,617                | 2 | 0 | 2 | 107 | 8,205                | 2 | 0 | 2 | 116 | 8,309                | 2 | 0 | 2 | 117 |
|                |           |               |              | T3M        | 7,846                | 2 | 0 | 2 | 111 | 8,452                | 2 | 0 | 2 | 119 | 8,559                | 2 | 0 | 2 | 121 |
|                |           |               |              | T4M        | 7,675                | 2 | 0 | 2 | 108 | 8,269                | 2 | 0 | 2 | 116 | 8,373                | 2 | 0 | 2 | 118 |
|                |           |               |              | TFTM       | 7,841                | 2 | 0 | 2 | 110 | 8,447                | 2 | 0 | 2 | 119 | 8,554                | 2 | 0 | 2 | 120 |
|                |           |               |              | TSVS       | 8,155                | 3 | 0 | 0 | 115 | 8,785                | 3 | 0 | 0 | 124 | 8,896                | 3 | 0 | 0 | 125 |
|                |           |               |              | T5S        | 8,162                | 3 | 0 | 1 | 115 | 8,792                | 3 | 0 | 1 | 124 | 8,904                | 3 | 0 | 1 | 125 |
|                |           |               |              | T5M        | 8,141                | 3 | 0 | 2 | 115 | 8,770                | 3 | 0 | 2 | 124 | 8,881                | 3 | 0 | 2 | 125 |
|                |           |               |              | TSW        | 8,204                | 3 | 0 | 2 | 116 | 8,838                | 4 | 0 | 2 | 124 | 8,950                | 4 | 0 | 2 | 126 |
|                |           |               |              | BLC        | 6,429                | 1 | 0 | 2 | 91  | 6,926                | 1 | 0 | 2 | 98  | 7,013                | 1 | 0 | 2 | 99  |
|                |           |               |              | LCCO       | 4,784                | 1 | 0 | 2 | 67  | 5,153                | 1 | 0 | 2 | 73  | 5,218                | 1 | 0 | 2 | 73  |
|                |           |               |              | RCCO       | 4,784                | 1 | 0 | 2 | 67  | 5,153                | 1 | 0 | 2 | 73  | 5,218                | 1 | 0 | 2 | 73  |
| P4             | 20        | 1400          | 92W          | T1S        | 9,791                | 2 | 0 | 2 | 106 | 10,547               | 2 | 0 | 2 | 115 | 10,681               | 2 | 0 | 2 | 116 |
|                |           |               |              | T2S        | 9,780                | 2 | 0 | 2 | 106 | 10,536               | 2 | 0 | 2 | 115 | 10,669               | 2 | 0 | 2 | 116 |
|                |           |               |              | T2M        | 9,831                | 2 | 0 | 2 | 107 | 10,590               | 2 | 0 | 2 | 115 | 10,724               | 2 | 0 | 2 | 117 |
|                |           |               |              | T3S        | 9,521                | 2 | 0 | 2 | 103 | 10,256               | 2 | 0 | 2 | 111 | 10,386               | 2 | 0 | 2 | 113 |
|                |           |               |              | T3M        | 9,807                | 2 | 0 | 2 | 107 | 10,565               | 2 | 0 | 2 | 115 | 10,698               | 2 | 0 | 2 | 116 |
|                |           |               |              | T4M        | 9,594                | 2 | 0 | 2 | 104 | 10,335               | 2 | 0 | 3 | 112 | 10,466               | 2 | 0 | 3 | 114 |
|                |           |               |              | TFTM       | 9,801                | 2 | 0 | 2 | 107 | 10,558               | 2 | 0 | 2 | 115 | 10,692               | 2 | 0 | 2 | 116 |
|                |           |               |              | TSVS       | 10,193               | 3 | 0 | 1 | 111 | 10,981               | 3 | 0 | 1 | 119 | 11,120               | 3 | 0 | 1 | 121 |
|                |           |               |              | T5S        | 10,201               | 3 | 0 | 1 | 111 | 10,990               | 3 | 0 | 1 | 119 | 11,129               | 3 | 0 | 1 | 121 |
|                |           |               |              | T5M        | 10,176               | 4 | 0 | 2 | 111 | 10,962               | 4 | 0 | 2 | 119 | 11,101               | 4 | 0 | 2 | 121 |
|                |           |               |              | TSW        | 10,254               | 4 | 0 | 3 | 111 | 11,047               | 4 | 0 | 3 | 120 | 11,186               | 4 | 0 | 3 | 122 |
|                |           |               |              | BLC        | 8,036                | 1 | 0 | 2 | 87  | 8,656                | 1 | 0 | 2 | 94  | 8,766                | 1 | 0 | 2 | 95  |
|                |           |               |              | LCCO       | 5,979                | 1 | 0 | 2 | 65  | 6,441                | 1 | 0 | 2 | 70  | 6,523                | 1 | 0 | 3 | 71  |
|                |           |               |              | RCCO       | 5,979                | 1 | 0 | 2 | 65  | 6,441                | 1 | 0 | 2 | 70  | 6,523                | 1 | 0 | 3 | 71  |

# Performance Data

## Lumen Output

Lumen values are from photometric tests performed in accordance with IESNA LM-79-08. Data is considered to be representative of the configurations shown, within the tolerances allowed by Lighting Facts. Contact factory for performance data on any configurations not shown here.

| Forward Optics |           |               |              |            |                      |      |      |     |        |                      |   |   |     |        |                      |   |   |     |        |
|----------------|-----------|---------------|--------------|------------|----------------------|------|------|-----|--------|----------------------|---|---|-----|--------|----------------------|---|---|-----|--------|
| Power Package  | LED Count | Drive Current | System Watts | Dist. Type | 30K (3000 K, 70 CRI) |      |      |     |        | 40K (4000 K, 70 CRI) |   |   |     |        | 50K (5000 K, 70 CRI) |   |   |     |        |
|                |           |               |              |            | Lumens               | B    | U    | G   | LPW    | Lumens               | B | U | G   | LPW    | Lumens               | B | U | G   | LPW    |
| P5             | 40        | 700           | 89W          | T1S        | 10,831               | 2    | 0    | 2   | 122    | 11,668               | 2 | 0 | 2   | 131    | 11,816               | 2 | 0 | 2   | 133    |
|                |           |               |              | T2S        | 10,820               | 2    | 0    | 2   | 122    | 11,656               | 2 | 0 | 2   | 131    | 11,803               | 2 | 0 | 2   | 133    |
|                |           |               |              | T2M        | 10,876               | 2    | 0    | 2   | 122    | 11,716               | 2 | 0 | 2   | 132    | 11,864               | 2 | 0 | 2   | 133    |
|                |           |               |              | T3S        | 10,532               | 2    | 0    | 2   | 118    | 11,346               | 2 | 0 | 2   | 127    | 11,490               | 2 | 0 | 2   | 129    |
|                |           |               |              | T3M        | 10,849               | 2    | 0    | 2   | 122    | 11,687               | 2 | 0 | 2   | 131    | 11,835               | 2 | 0 | 2   | 133    |
|                |           |               |              | T4M        | 10,613               | 2    | 0    | 3   | 119    | 11,434               | 2 | 0 | 3   | 128    | 11,578               | 2 | 0 | 3   | 130    |
|                |           |               |              | TFTM       | 10,842               | 2    | 0    | 2   | 122    | 11,680               | 2 | 0 | 2   | 131    | 11,828               | 2 | 0 | 2   | 133    |
|                |           |               |              | TSVS       | 11,276               | 3    | 0    | 1   | 127    | 12,148               | 3 | 0 | 1   | 136    | 12,302               | 3 | 0 | 1   | 138    |
|                |           |               |              | T5S        | 11,286               | 3    | 0    | 1   | 127    | 12,158               | 3 | 0 | 1   | 137    | 12,312               | 3 | 0 | 1   | 138    |
|                |           |               |              | T5M        | 11,257               | 4    | 0    | 2   | 126    | 12,127               | 4 | 0 | 2   | 136    | 12,280               | 4 | 0 | 2   | 138    |
|                |           |               |              | T5W        | 11,344               | 4    | 0    | 3   | 127    | 12,221               | 4 | 0 | 3   | 137    | 12,375               | 4 | 0 | 3   | 139    |
|                |           |               |              | BLC        | 8,890                | 1    | 0    | 2   | 100    | 9,576                | 1 | 0 | 2   | 108    | 9,698                | 1 | 0 | 2   | 109    |
|                |           |               |              | LCCO       | 6,615                | 1    | 0    | 3   | 74     | 7,126                | 1 | 0 | 3   | 80     | 7,216                | 1 | 0 | 3   | 81     |
|                |           |               |              | RCCO       | 6,615                | 1    | 0    | 3   | 74     | 7,126                | 1 | 0 | 3   | 80     | 7,216                | 1 | 0 | 3   | 81     |
|                |           |               |              | P6         | 40                   | 1050 | 134W | T1S | 14,805 | 3                    | 0 | 3 | 110 | 15,949 | 3                    | 0 | 3 | 119 | 16,151 |
| T2S            | 14,789    | 3             | 0            |            |                      |      |      | 3   | 110    | 15,932               | 3 | 0 | 3   | 119    | 16,134               | 3 | 0 | 3   | 120    |
| T2M            | 14,865    | 3             | 0            |            |                      |      |      | 3   | 111    | 16,014               | 3 | 0 | 3   | 120    | 16,217               | 3 | 0 | 3   | 121    |
| T3S            | 14,396    | 3             | 0            |            |                      |      |      | 3   | 107    | 15,509               | 3 | 0 | 3   | 116    | 15,705               | 3 | 0 | 3   | 117    |
| T3M            | 14,829    | 2             | 0            |            |                      |      |      | 3   | 111    | 15,975               | 3 | 0 | 3   | 119    | 16,177               | 3 | 0 | 3   | 121    |
| T4M            | 14,507    | 2             | 0            |            |                      |      |      | 3   | 108    | 15,628               | 3 | 0 | 3   | 117    | 15,826               | 3 | 0 | 3   | 118    |
| TFTM           | 14,820    | 2             | 0            |            |                      |      |      | 3   | 111    | 15,965               | 3 | 0 | 3   | 119    | 16,167               | 3 | 0 | 3   | 121    |
| TSVS           | 15,413    | 4             | 0            |            |                      |      |      | 1   | 115    | 16,604               | 4 | 0 | 1   | 124    | 16,815               | 4 | 0 | 1   | 125    |
| T5S            | 15,426    | 3             | 0            |            |                      |      |      | 1   | 115    | 16,618               | 4 | 0 | 1   | 124    | 16,828               | 4 | 0 | 1   | 126    |
| T5M            | 15,387    | 4             | 0            |            |                      |      |      | 2   | 115    | 16,576               | 4 | 0 | 2   | 124    | 16,786               | 4 | 0 | 2   | 125    |
| T5W            | 15,506    | 4             | 0            |            |                      |      |      | 3   | 116    | 16,704               | 4 | 0 | 3   | 125    | 16,915               | 4 | 0 | 3   | 126    |
| BLC            | 12,151    | 1             | 0            |            |                      |      |      | 2   | 91     | 13,090               | 1 | 0 | 2   | 98     | 13,255               | 1 | 0 | 2   | 99     |
| LCCO           | 9,041     | 1             | 0            |            |                      |      |      | 3   | 67     | 9,740                | 1 | 0 | 3   | 73     | 9,863                | 1 | 0 | 3   | 74     |
| RCCO           | 9,041     | 1             | 0            |            |                      |      |      | 3   | 67     | 9,740                | 1 | 0 | 3   | 73     | 9,863                | 1 | 0 | 3   | 74     |
| P7             | 40        | 1300          | 166W         |            |                      |      |      | T1S | 17,023 | 3                    | 0 | 3 | 103 | 18,338 | 3                    | 0 | 3 | 110 | 18,570 |
|                |           |               |              | T2S        | 17,005               | 3    | 0    | 3   | 102    | 18,319               | 3 | 0 | 3   | 110    | 18,551               | 3 | 0 | 3   | 112    |
|                |           |               |              | T2M        | 17,092               | 3    | 0    | 3   | 103    | 18,413               | 3 | 0 | 3   | 111    | 18,646               | 3 | 0 | 3   | 112    |
|                |           |               |              | T3S        | 16,553               | 3    | 0    | 3   | 100    | 17,832               | 3 | 0 | 3   | 107    | 18,058               | 3 | 0 | 3   | 109    |
|                |           |               |              | T3M        | 17,051               | 3    | 0    | 3   | 103    | 18,369               | 3 | 0 | 3   | 111    | 18,601               | 3 | 0 | 3   | 112    |
|                |           |               |              | T4M        | 16,681               | 3    | 0    | 3   | 100    | 17,969               | 3 | 0 | 3   | 108    | 18,197               | 3 | 0 | 3   | 110    |
|                |           |               |              | TFTM       | 17,040               | 3    | 0    | 3   | 103    | 18,357               | 3 | 0 | 4   | 111    | 18,590               | 3 | 0 | 4   | 112    |
|                |           |               |              | TSVS       | 17,723               | 4    | 0    | 1   | 107    | 19,092               | 4 | 0 | 1   | 115    | 19,334               | 4 | 0 | 1   | 116    |
|                |           |               |              | T5S        | 17,737               | 4    | 0    | 2   | 107    | 19,108               | 4 | 0 | 2   | 115    | 19,349               | 4 | 0 | 2   | 117    |
|                |           |               |              | T5M        | 17,692               | 4    | 0    | 2   | 107    | 19,059               | 4 | 0 | 2   | 115    | 19,301               | 4 | 0 | 2   | 116    |
|                |           |               |              | T5W        | 17,829               | 5    | 0    | 3   | 107    | 19,207               | 5 | 0 | 3   | 116    | 19,450               | 5 | 0 | 3   | 117    |
|                |           |               |              | BLC        | 13,971               | 2    | 0    | 2   | 84     | 15,051               | 2 | 0 | 2   | 91     | 15,241               | 2 | 0 | 2   | 92     |
|                |           |               |              | LCCO       | 10,396               | 1    | 0    | 3   | 63     | 11,199               | 1 | 0 | 3   | 67     | 11,341               | 1 | 0 | 3   | 68     |
|                |           |               |              | RCCO       | 10,396               | 1    | 0    | 3   | 63     | 11,199               | 1 | 0 | 3   | 67     | 11,341               | 1 | 0 | 3   | 68     |



# Performance Data

## Lumen Output

Lumen values are from photometric tests performed in accordance with IESNA LM-79-08. Data is considered to be representative of the configurations shown, within the tolerances allowed by Lighting Facts. Contact factory for performance data on any configurations not shown here.

| Rotated Optics |           |               |              |            |                      |      |      |     |        |                      |   |   |     |        |                      |   |   |     |        |
|----------------|-----------|---------------|--------------|------------|----------------------|------|------|-----|--------|----------------------|---|---|-----|--------|----------------------|---|---|-----|--------|
| Power Package  | LED Count | Drive Current | System Watts | Dist. Type | 30K (3000 K, 70 CRI) |      |      |     |        | 40K (4000 K, 70 CRI) |   |   |     |        | 50K (5000 K, 70 CRI) |   |   |     |        |
|                |           |               |              |            | Lumens               | B    | U    | G   | LPW    | Lumens               | B | U | G   | LPW    | Lumens               | B | U | G   | LPW    |
| P10            | 30        | 530           | 53W          | T1S        | 6,727                | 2    | 0    | 2   | 127    | 7,247                | 3 | 0 | 3   | 137    | 7,339                | 3 | 0 | 3   | 138    |
|                |           |               |              | T2S        | 6,689                | 3    | 0    | 3   | 126    | 7,205                | 3 | 0 | 3   | 136    | 7,297                | 3 | 0 | 3   | 138    |
|                |           |               |              | T2M        | 6,809                | 3    | 0    | 3   | 128    | 7,336                | 3 | 0 | 3   | 138    | 7,428                | 3 | 0 | 3   | 140    |
|                |           |               |              | T3S        | 6,585                | 3    | 0    | 3   | 124    | 7,094                | 3 | 0 | 3   | 134    | 7,183                | 3 | 0 | 3   | 136    |
|                |           |               |              | T3M        | 6,805                | 3    | 0    | 3   | 128    | 7,331                | 3 | 0 | 3   | 138    | 7,424                | 3 | 0 | 3   | 140    |
|                |           |               |              | T4M        | 6,677                | 3    | 0    | 3   | 126    | 7,193                | 3 | 0 | 3   | 136    | 7,284                | 3 | 0 | 3   | 137    |
|                |           |               |              | TFTM       | 6,850                | 3    | 0    | 3   | 129    | 7,379                | 3 | 0 | 3   | 139    | 7,472                | 3 | 0 | 3   | 141    |
|                |           |               |              | TSVS       | 6,898                | 3    | 0    | 0   | 130    | 7,431                | 3 | 0 | 0   | 140    | 7,525                | 3 | 0 | 0   | 142    |
|                |           |               |              | T5S        | 6,840                | 2    | 0    | 1   | 129    | 7,368                | 2 | 0 | 1   | 139    | 7,461                | 2 | 0 | 1   | 141    |
|                |           |               |              | T5M        | 6,838                | 3    | 0    | 1   | 129    | 7,366                | 3 | 0 | 2   | 139    | 7,460                | 3 | 0 | 2   | 141    |
|                |           |               |              | TSW        | 6,777                | 3    | 0    | 2   | 128    | 7,300                | 3 | 0 | 2   | 138    | 7,393                | 3 | 0 | 2   | 139    |
|                |           |               |              | BLC        | 5,626                | 2    | 0    | 2   | 106    | 6,060                | 2 | 0 | 2   | 114    | 6,137                | 2 | 0 | 2   | 116    |
|                |           |               |              | LCCO       | 4,018                | 1    | 0    | 2   | 76     | 4,328                | 1 | 0 | 2   | 82     | 4,383                | 1 | 0 | 2   | 83     |
|                |           |               |              | RCCO       | 4,013                | 3    | 0    | 3   | 76     | 4,323                | 3 | 0 | 3   | 82     | 4,377                | 3 | 0 | 3   | 83     |
|                |           |               |              | P11        | 30                   | 700  | 72W  | T1S | 8,594  | 3                    | 0 | 3 | 119 | 9,258  | 3                    | 0 | 3 | 129 | 9,376  |
| T2S            | 8,545     | 3             | 0            |            |                      |      |      | 3   | 119    | 9,205                | 3 | 0 | 3   | 128    | 9,322                | 3 | 0 | 3   | 129    |
| T2M            | 8,699     | 3             | 0            |            |                      |      |      | 3   | 121    | 9,371                | 3 | 0 | 3   | 130    | 9,490                | 3 | 0 | 3   | 132    |
| T3S            | 8,412     | 3             | 0            |            |                      |      |      | 3   | 117    | 9,062                | 3 | 0 | 3   | 126    | 9,177                | 3 | 0 | 3   | 127    |
| T3M            | 8,694     | 3             | 0            |            |                      |      |      | 3   | 121    | 9,366                | 3 | 0 | 3   | 130    | 9,484                | 3 | 0 | 3   | 132    |
| T4M            | 8,530     | 3             | 0            |            |                      |      |      | 3   | 118    | 9,189                | 3 | 0 | 3   | 128    | 9,305                | 3 | 0 | 3   | 129    |
| TFTM           | 8,750     | 3             | 0            |            |                      |      |      | 3   | 122    | 9,427                | 3 | 0 | 3   | 131    | 9,546                | 3 | 0 | 3   | 133    |
| TSVS           | 8,812     | 3             | 0            |            |                      |      |      | 0   | 122    | 9,493                | 3 | 0 | 0   | 132    | 9,613                | 3 | 0 | 0   | 134    |
| T5S            | 8,738     | 3             | 0            |            |                      |      |      | 1   | 121    | 9,413                | 3 | 0 | 1   | 131    | 9,532                | 3 | 0 | 1   | 132    |
| T5M            | 8,736     | 3             | 0            |            |                      |      |      | 2   | 121    | 9,411                | 3 | 0 | 2   | 131    | 9,530                | 3 | 0 | 2   | 132    |
| TSW            | 8,657     | 4             | 0            |            |                      |      |      | 2   | 120    | 9,326                | 4 | 0 | 2   | 130    | 9,444                | 4 | 0 | 2   | 131    |
| BLC            | 7,187     | 3             | 0            |            |                      |      |      | 3   | 100    | 7,742                | 3 | 0 | 3   | 108    | 7,840                | 3 | 0 | 3   | 109    |
| LCCO           | 5,133     | 1             | 0            |            |                      |      |      | 2   | 71     | 5,529                | 1 | 0 | 2   | 77     | 5,599                | 1 | 0 | 2   | 78     |
| RCCO           | 5,126     | 3             | 0            |            |                      |      |      | 3   | 71     | 5,522                | 3 | 0 | 3   | 77     | 5,592                | 3 | 0 | 3   | 78     |
| P12            | 30        | 1050          | 104W         |            |                      |      |      | T1S | 12,149 | 3                    | 0 | 3 | 117 | 13,088 | 3                    | 0 | 3 | 126 | 13,253 |
|                |           |               |              | T2S        | 12,079               | 4    | 0    | 4   | 116    | 13,012               | 4 | 0 | 4   | 125    | 13,177               | 4 | 0 | 4   | 127    |
|                |           |               |              | T2M        | 12,297               | 3    | 0    | 3   | 118    | 13,247               | 3 | 0 | 3   | 127    | 13,415               | 3 | 0 | 3   | 129    |
|                |           |               |              | T3S        | 11,891               | 4    | 0    | 4   | 114    | 12,810               | 4 | 0 | 4   | 123    | 12,972               | 4 | 0 | 4   | 125    |
|                |           |               |              | T3M        | 12,290               | 3    | 0    | 3   | 118    | 13,239               | 4 | 0 | 4   | 127    | 13,407               | 4 | 0 | 4   | 129    |
|                |           |               |              | T4M        | 12,058               | 4    | 0    | 4   | 116    | 12,990               | 4 | 0 | 4   | 125    | 13,154               | 4 | 0 | 4   | 126    |
|                |           |               |              | TFTM       | 12,369               | 4    | 0    | 4   | 119    | 13,325               | 4 | 0 | 4   | 128    | 13,494               | 4 | 0 | 4   | 130    |
|                |           |               |              | TSVS       | 12,456               | 3    | 0    | 1   | 120    | 13,419               | 3 | 0 | 1   | 129    | 13,589               | 4 | 0 | 1   | 131    |
|                |           |               |              | T5S        | 12,351               | 3    | 0    | 1   | 119    | 13,306               | 3 | 0 | 1   | 128    | 13,474               | 3 | 0 | 1   | 130    |
|                |           |               |              | T5M        | 12,349               | 4    | 0    | 2   | 119    | 13,303               | 4 | 0 | 2   | 128    | 13,471               | 4 | 0 | 2   | 130    |
|                |           |               |              | TSW        | 12,238               | 4    | 0    | 3   | 118    | 13,183               | 4 | 0 | 3   | 127    | 13,350               | 4 | 0 | 3   | 128    |
|                |           |               |              | BLC        | 10,159               | 3    | 0    | 3   | 98     | 10,944               | 3 | 0 | 3   | 105    | 11,083               | 3 | 0 | 3   | 107    |
|                |           |               |              | LCCO       | 7,256                | 1    | 0    | 3   | 70     | 7,816                | 1 | 0 | 3   | 75     | 7,915                | 1 | 0 | 3   | 76     |
|                |           |               |              | RCCO       | 7,246                | 3    | 0    | 3   | 70     | 7,806                | 4 | 0 | 4   | 75     | 7,905                | 4 | 0 | 4   | 76     |
|                |           |               |              | P13        | 30                   | 1300 | 128W | T1S | 14,438 | 3                    | 0 | 3 | 113 | 15,554 | 3                    | 0 | 3 | 122 | 15,751 |
| T2S            | 14,355    | 4             | 0            |            |                      |      |      | 4   | 112    | 15,465               | 4 | 0 | 4   | 121    | 15,660               | 4 | 0 | 4   | 122    |
| T2M            | 14,614    | 3             | 0            |            |                      |      |      | 3   | 114    | 15,744               | 4 | 0 | 4   | 123    | 15,943               | 4 | 0 | 4   | 125    |
| T3S            | 14,132    | 4             | 0            |            |                      |      |      | 4   | 110    | 15,224               | 4 | 0 | 4   | 119    | 15,417               | 4 | 0 | 4   | 120    |
| T3M            | 14,606    | 4             | 0            |            |                      |      |      | 4   | 114    | 15,735               | 4 | 0 | 4   | 123    | 15,934               | 4 | 0 | 4   | 124    |
| T4M            | 14,330    | 4             | 0            |            |                      |      |      | 4   | 112    | 15,438               | 4 | 0 | 4   | 121    | 15,633               | 4 | 0 | 4   | 122    |
| TFTM           | 14,701    | 4             | 0            |            |                      |      |      | 4   | 115    | 15,836               | 4 | 0 | 4   | 124    | 16,037               | 4 | 0 | 4   | 125    |
| TSVS           | 14,804    | 4             | 0            |            |                      |      |      | 1   | 116    | 15,948               | 4 | 0 | 1   | 125    | 16,150               | 4 | 0 | 1   | 126    |
| T5S            | 14,679    | 3             | 0            |            |                      |      |      | 1   | 115    | 15,814               | 3 | 0 | 1   | 124    | 16,014               | 3 | 0 | 1   | 125    |
| T5M            | 14,676    | 4             | 0            |            |                      |      |      | 2   | 115    | 15,810               | 4 | 0 | 2   | 124    | 16,010               | 4 | 0 | 2   | 125    |
| TSW            | 14,544    | 4             | 0            |            |                      |      |      | 3   | 114    | 15,668               | 4 | 0 | 3   | 122    | 15,866               | 4 | 0 | 3   | 124    |
| BLC            | 7,919     | 3             | 0            |            |                      |      |      | 3   | 62     | 8,531                | 3 | 0 | 3   | 67     | 8,639                | 3 | 0 | 3   | 67     |
| LCCO           | 5,145     | 1             | 0            |            |                      |      |      | 2   | 40     | 5,543                | 1 | 0 | 2   | 43     | 5,613                | 1 | 0 | 2   | 44     |
| RCCO           | 5,139     | 3             | 0            |            |                      |      |      | 3   | 40     | 5,536                | 3 | 0 | 3   | 43     | 5,606                | 3 | 0 | 3   | 44     |

## FEATURES & SPECIFICATIONS

### INTENDED USE

The sleek design of the D-Series Size 0 reflects the embedded high performance LED technology. It is ideal for many commercial and municipal applications, such as parking lots, plazas, campuses, and pedestrian areas.

### CONSTRUCTION

Single-piece die-cast aluminum housing has integral heat sink fins to optimize thermal management through conductive and convective cooling. Modular design allows for ease of maintenance and future light engine upgrades. The LED driver is mounted in direct contact with the casting to promote low operating temperature and long life. Housing is completely sealed against moisture and environmental contaminants (IP65). Low EPA (0.95 ft<sup>2</sup>) for optimized pole wind loading.

### FINISH

Exterior parts are protected by a zinc-infused Super Durable TGIC thermoset powder coat finish that provides superior resistance to corrosion and weathering. A tightly controlled multi-stage process ensures a minimum 3 mils thickness for a finish that can withstand extreme climate changes without cracking or peeling. Available in both textured and non-textured finishes.

### OPTICS

Precision-molded proprietary acrylic lenses are engineered for superior area lighting distribution, uniformity, and pole spacing. Light engines are available in 3000 K, 4000 K or 5000 K (70 CRI) configurations. The D-Series Size 0 has zero uplight and qualifies as a Nighttime Friendly™ product, meaning it is consistent with the LEED® and Green Globes™ criteria for eliminating wasteful uplight.

### ELECTRICAL

Light engine(s) configurations consist of high-efficacy LEDs mounted to metal-core circuit boards to maximize heat dissipation and promote long life (up to L85/100,000 hours at 25°C). Class 1 electronic drivers are designed to have a power factor >90%, THD <20%, and an expected life of 100,000 hours with <1% failure rate. Easily serviceable 10kV surge protection device meets a minimum Category C Low operation (per ANSI/IEEE C62.41.2).

### STANDARD CONTROLS

The DSX0 LED area luminaire has a number of control options. DSX Size 0, comes standard with 0-10V dimming driver. Dusk to dawn controls can be utilized via optional NEMA twist-lock photocell receptacles. Integrated motion sensors with on-board photocells feature field-adjustable programming and are suitable for mounting heights up to 30 feet.

### nLIGHT AIR CONTROLS

The DSX0 LED area luminaire is also available with nLight® AIR for the ultimate in wireless control. This powerful controls platform provides out-of-the-box basic motion sensing and photocontrol functionality and is suitable for mounting heights up to 40 feet. Once commissioned using a smartphone and the easy-to-use CLAIRITY app, nLight AIR equipped luminaires can be grouped, resulting in motion sensor and photocell group response without the need for additional equipment. Scheduled dimming with motion sensor over-ride can be achieved when used with the nLight Eclipse. Additional information about nLight Air can be found [here](#).

### INSTALLATION

Included mounting block and integral arm facilitate quick and easy installation. Stainless steel bolts fasten the mounting block securely to poles and walls, enabling the D-Series Size 0 to withstand up to a 3.0 G vibration load rating per ANSI C136.31. The D-Series Size 0 utilizes the AERIS™ series pole drilling pattern (template #8). Optional terminal block and NEMA photocontrol receptacle are also available.

### LISTINGS

UL listed to meet U.S. and Canadian standards. UL Listed for wet locations. Light engines are IP66 rated; luminaire is IP65 rated. Rated for -40°C to 50°C ambient with HA option. U.S. Patent No. D672,492 S. International patent pending.

DesignLights Consortium® (DLC) Premium qualified product and DLC qualified product. Not all versions of this product may be DLC Premium qualified or DLC qualified. Please check the DLC Qualified Products List at [www.designlights.org/QPL](http://www.designlights.org/QPL) to confirm which versions are qualified.

International Dark-Sky Association (IDA) Fixture Seal of Approval (FSA) is available for all products on this page utilizing 3000K color temperature only.

### BUY AMERICAN

Product with the BAA option is assembled in the USA and meets the Buy America(n) government procurement requirements under FAR, DFARS and DOT. Please refer to [www.acuitybrands.com/buy-american](http://www.acuitybrands.com/buy-american) for additional information.

### WARRANTY

5-year limited warranty. Complete warranty terms located at: [www.acuitybrands.com/support/customer-support/terms-and-conditions](http://www.acuitybrands.com/support/customer-support/terms-and-conditions)

**Note:** Actual performance may differ as a result of end-user environment and application. All values are design or typical values, measured under laboratory conditions at 25 °C. Specifications subject to change without notice.





# Niveous LED Outdoor Flushmount/Wall Sconce

By dweLED

Niveous LED Outdoor Flushmount/Wall Sconce

By dweLED

## Product Options

**Size:** Small , Medium , Large

**Color Temperature:** 2700 , 3000 , 3500

## Details

- Can be installed as a ceiling fixture or a wall sconce
- Aluminum canopy construction
- Rated for use in closets
- No transformer required
- Designed in 2016
- Finish: White
- Material: Aluminum
- Shade Material: Mouth Blown Etched Glass
- Dimmable When Used With a Electronic low voltage (ELV) Dimmer (Not Included)
- Dimmer Range: 100 - 10%
- Title 24 compliant
- ETL Listed Wet
- Warranty: 5 Years Functional, 2 Years Finish
- Made In China

## Dimensions

Small Option Fixture: Height 6", Diameter 6", Weight 2.38Lbs

Medium Option Fixture: Height 9", Diameter 9", Weight 4.89Lbs, 5.07Lbs

Large Option Fixture: Height 12.75", Diameter 12", Weight 8.22Lbs

## Lighting

- Small Option: 9.5 Watt (800 Lumens) 120 Volt Integrated LED: CRI: 90  
Color Temp: 2700K Lifespan: 45000 hours
- Small Option: 9.5 Watt (800 Lumens) 120 Volt Integrated LED: CRI: 90  
Color Temp: 3000K Lifespan: 45000 hours
- Small Option: 9.5 Watt (800 Lumens) 120 Volt Integrated LED: CRI: 90  
Color Temp: 3500K Lifespan: 45000 hours
- Medium Option: 18 Watt (1600 Lumens) 120 Volt Integrated LED: CRI: 90  
Color Temp: 2700K Lifespan: 45000 hours
- Medium Option: 18 Watt (1600 Lumens) 120 Volt Integrated LED: CRI: 90  
Color Temp: 3000K Lifespan: 45000 hours
- Medium Option: 18 Watt (1600 Lumens) 120 Volt Integrated LED: CRI: 90  
Color Temp: 3500K Lifespan: 45000 hours
- Large Option: 24 Watt (2229 Lumens) 120 Volt Integrated LED: CRI: 90  
Color Temp: 3000K Lifespan: 45000 hours

## Additional Details

**Product URL:**

<https://www.lumens.com/niveous-led-outdoor-flushmount-wall-sconce-by-dweled-WACP122458.html>

**Rating:** ETL Listed Wet

**Product ID:** WACP122458



## Notes:

**Prepared by:**

**Prepared for:**

**Project:**

**Room:**

**Placement:**

**Approval:**



9/27/21

Intoto Studio  
Attn: Nicole Fricke  
6505 Woodward Ave  
Suite 200  
Detroit, MI 48223  
PH: 313-387-5158

Job Name: 9710 & 9730 Outer Drive  
Job Location: Detroit, MI

## **Historic Window Site Review and Survey:**

**BlackBerry is providing information for the 9710 & 9730 Outer Drive Project, Detroit, MI. The information provided was a Schematic Design Package 07/07/21. BlackBerry made a site visit and met with the design team in mid-July. BlackBerry returned to the site to perform a Historic Window Site Review and Window Survey on 9/13/21. Information provided to consider in making this review included photographs, floor plans, and a general project scope description. The windows being considered are wood double hung units with two-track aluminum storm windows, as well as steel double hung units with two-track aluminum storm windows. There are common areas in the stairwells that have fixed radius head steel windows. BlackBerry went to each window, opening to inspect each window from the interior. Each window was opened to inspect the exterior sill as well as note the operation and overall condition of the wood and steel windows. All wood double hung windows had the exterior storms removed and were inspected from the exterior side since replication is a consideration.**

### **9710 Outer Drive, Detroit MI. Wood Double Hung Windows:**

**The existing wood windows are double hung with wood master frame, wood sashes, steel weather stripping, wood exterior brickmould and sills. The interior includes sash trim, interior casing, stool, and apron. The majority of the windows do not have true divided light muntins; however, the windows on the front elevation include muntins in the upper sash. All windows are single pane annealed glass. The windows have a two-track aluminum storm and screen exterior window. We have attached a full window by window site Survey Sheet. All windows are marked by window location, elevation, and type of material. The sheet includes both wood and steel windows in the 9710 building.**



In reviewing the Survey Sheet (attached), the overall condition of the wood double hung windows is twofold. The exterior elevation is “poor” to “fair” condition. The exterior side of the windows have not been painted on a regular basis, and despite having an exterior storm window are in poor condition. The glazing compound is falling out and breaking down on all sashes. The paint finish is peeling and pulling loose on all window sashes, frames, sills, and brickmould. The exterior perimeter caulking is failing and falling out on all windows. Some of the exterior sills are split, allowing water to enter the building envelope. The majority of sills are fissured and open to water penetrating the material. This has caused dry rot and material breakdown on many sills at the intersection of the sill and master frame. ACM is likely in the glazing compound and perimeter caulk.

The interior of the windows are in “good” condition. The painting has been maintained over the past years. All the interior trim including sash trim, casing, stool, and apron are in place. The window locks are working and are in “good” condition or are replaceable if missing. One serious issue is the operability for opening the windows. Because of the age and years of use the window track and weather stripping is worn, bent, or torn from use. This makes the operation inconsistent and, in many cases, very difficult. Likewise, the window uses a tape balance system that is concealed and not readily replaced without potential damage to the master frame. They are not surface mounted or mortised; so, you are unable to unscrew them for replacement. The other unusual condition is that each sash only has one tape balance on the left side, not the right. Over time these sashes have trouble traveling in the weatherstrip sash pocket making operation difficult, since they are unbalanced in the sash pocket. The jamb liner/weatherstrip is not a product that is available for replacement.

The storm windows are in poor condition with many broken track guides and failing corner joinery. They have allowed water to get trapped on the exterior sills and allow dry rot and decay to develop in 30 to 40 % of the openings. Field Sketch Details are attached to this review showing accurate existing profiles and dimensions.

#### **Recommendation for Wood Double Hung Windows:**

Our recommendation would be the replacement of all wood double hungs with a wood clad or thermally-broken aluminum, double hung or single hung product, eliminating the three-track storm as well. A detailed drawing is attached showing a proposed Quaker H650 Series Single Hung replica product. This drawing compares existing to proposed profiles and dimensions. This approach will provide a well-functioning, energy efficient replication of the original windows.

This recommendation is concluded for these specific reasons.

- Since all windows require re-glazing with new glazing compound one issue is the existing glazing compound. Most of this material is original and literally rock hard and impossible to remove without damage to the sashes and breaking the glass. As the glazing compound has broken down over the years, portions dried out and broke loose. At time went on this was patched and then

Painted over. For a period of time this looked good but once again started to fail and fallout. Approximately 30 to 50% of the original glazing compound is aged and turned dark gray in color and is very dense and adhered to the glass or wood sash glazing pocket.

- To truly restore the windows the sash would need to be removed and restored in a shop setting where the sashes can be deglazed with a steam cabinet and a variety of techniques. To do this the concern is the existing condition of the tape balance and the inability to disengage it without damage. Currently the steel tape is crimped and bent in the majority of openings, and we have no source to replace them with a new component.
- The jamb liner/weatherstripping is in poor condition and is not a component that we have identified as available for replacement. Once again there is a need to replace this component to improve the operation, but we don't have a supply source, and the replacement would create damage to other components including the tape balance.

#### **Replacement Method for Existing Wood Double Hung Window:**

- All existing window components would be removed and disposed. Abatement may be required depending on a hazmat environmental report.
- Wood blocking would be set in the jamb cavity to fill the void where the weight box occupied.
- New windows would be set with exterior aluminum brickmould and sill components, that would replicate historic exterior casework of the era. New Double Hung or Single Hung windows would be set and fastened in place. Prior to this install, all cavities would be insulated.
- Windows would be cleaned and adjusted, and the perimeter caulked at the masonry intersection.
- New casework would be installed and finished by others.
- Note: no exterior screens can be included on tax credit projects without approval, and they have not been included in this budget pricing.

#### **Wood Window Paint and Glazing Repair:**

As explained above a true restoration process is not able to be implemented for these windows. The following is an alternate repair and painting option. While we offer this; BlackBerry does not believe this is a reasonable or practical approach since the inherent issues with the window are not addressed, that being their poor operation and long-term durability and energy efficiency.

- Remove all storm/screens.
- Scrape, prime, and paint all exterior wood surface components.
- Repair or replace split exterior sill where possible.
- Replace glass as needed.
- Patch loose or missing glazing compound.



- Replace exterior perimeter caulking.
- Does not include weatherstripping replacement, balance tape replacement, interior painting of sashes or casework.
- Does include reinstalling existing storms.

**If the project pursues Federal or State Historic Tax credits and it is anticipated that for any existing window being replaced; all components would have to be removed back to the masonry opening including removal of interior casework and the master frame and weight box.**

The estimated budget pricing for window removal and replacement is dependent on a specific product type. For purposes here the pricing allows for the use of the Quaker H650 Single Hung shown in the attached drawings.

Estimated Replacement Budget Price \$94,000.00

Estimated Paint and Glazing Repair Budget Price \$49,500.00

**9710 and 9730 Outer Drive, Detroit MI. Steel Double Hung and Fixed Window:**

The existing steel windows are double hung and fixed windows set directly in the wood framed and masonry opening with plaster returning directly to the steel master frame on the interior. The windows are a hot rolled steel frame and sash assembly with single pane annealed glass. The glazing is set with an exterior putty glazing compound. There is evidence that all these steel windows were fitted with a steel framed half screen covering the lower sash area. The sashes operate using a tape balance that is mortised in the top of the master frame. There is one steel sweep lock and keeper per window unit. The weather stripping is a custom steel fin that is integral to the master frame and interior sash stop.

In reviewing the Survey Sheet (attached) the overall condition of the steel windows is “poor” to “fair”. The exterior side of the windows have not been painted on a regular basis, and despite having an exterior aluminum storm/screen window the paint is worn, in many locations peeling, or allowing rust and corrosion to bleed thru to the surface. The butt joint tubular steel framing has mild to heavy corrosion at the exterior sill and the sash and frame joinery. The exterior perimeter caulking is failing and coming loose from the masonry. The condition of the glazing compound is similar to that of the wood double hung, falling out and failing on all sashes. ACM is likely present in all glazing compound and perimeter caulking.

The interior of the windows are in “fair” to “poor” condition. The steel windows allow condensation to form on the interior surface and is evident by the surface corrosion on the interior painted surfaces. The bathroom and kitchen windows have more surface rust than the living area windows. The locks are bent or broken in over 80% of all windows. The weather stripping is rusted and makes the operation and sash movement stiff and resistant. Air infiltration is a primary concern as well as the

previously mention condensation issues. These are the result of the lack of a tight seal at the points of weatherstripping between the sash and master frame. Condensation is the direct result of the thermal conduction via the steel frame and sash, as well as the monolithic glazing. The tape balancers are typically bent, crimped, or torn and this likewise makes the sash movement stiff and resistant. The storm windows are in “poor” condition with many broken track guides and failing corner joinery. They have allowed water to get trapped on the exterior sill creating rust and corrosion. Field Sketches are attached that show the steel windows’ accurate existing profiles and dimensions.

#### **Recommendation for Steel Double Hung and Fixed Windows:**

BlackBerry acknowledges two possible recommendations to address the steel windows. Our primary recommendation is for full replacement of the existing windows. The key conclusion for this is the fact that the windows do not lend themselves to restoration. In defining restoration of steel windows, the process shown below is the industry standard approach.

#### **Restoration Method: For Steel Double Hung and Fixed Windows.**

- Remove storm windows
- Remove sashes to be stripped and cleaned in a shop setting. Glazing compound to be removed and abated if ACM is present.
- Strip and clean master-frame in the field, remove perimeter caulking and abated if ACM is present.
- Replace glass as needed (Determine if Annealed or Tempered Monolithic) reglazing with new glazing compound.
- Prime and paint all components.
- Caulk exterior perimeter at masonry.
- Set restored sashes in place.
- Clean and Adjust sashes including balance mechanism and lock and keeper.
- Set new interior storm window

The issue with this process is that removing the sashes involves the removal of the interior sash stop and weatherstripping, as well as the tape balances. These windows and components do not lend themselves to this process. These components are in such poor condition and no replacement parts are available. Leaving the sashes in place will not resolve the poor operation that is the current condition of the windows. These windows are simply obsolete based on the age and original design. Our recommendation is for the full replacement of the existing steel windows except the Fixed units in the Common Area Stair Wells. The difficulty with this approach is the existing windows have very narrow sitelines, and we have not found any available product (including Steel, Wood/Clad, or Aluminum) that will match the critical sitelines. We have included a detail of a thermally-broken aluminum window from Thermal Industries (700 Single Hung Series) that we suggest. We would direct



set the unit in the existing masonry opening, which would provide the narrowest overall assembly we have found. Below is a description of the replacement process per the industry standard approach.

**Replacement Method for Existing Steel Double Hung Window:**

- All existing window components would be removed and disposed. Abatement may be required depending on a Haz-Mat Environmental Report
- Wood blocking would be set in the jamb cavity.
- New window would be direct in the masonry opening and anchored to the wood blocking. Prior to this installation all voids would be insulated.
- Perimeter caulking would be applied on the interior and exterior.
- Windows would be cleaned and adjusted.
- Plaster repair is by others.
- Note: no exterior screens can be included on tax credit projects without approval, and they have not been included in the budget pricing.

**Steel Window Paint and Glazing Repair:**

As explained previously, a true restoration process is not able to be implemented for these windows. The following is an alternate repair and painting option. While we offer this; BlackBerry does not believe this is a reasonable or practical approach since the inherent issues with the window are not addressed, that being their poor operation and long-term durability and energy efficiency.

- Remove all storm/screens.
- Scrape, prime, and paint all exterior and interior steel surface components.
- Replace glass as needed.
- Patch loose or missing glazing compound.
- Replace exterior perimeter caulking.
- Does not include re-installing existing storm or providing new storm.

Estimated Replacement Budget Price for 9710 \$45,000.00

Estimated Replacement Budget Price for 9730 \$280,000.00

**( (11) New Windows Budget Price Included Above \$19,000.00)**

Estimated Paint and Glazing Repair Budget Price for 9710 \$37,000.00

Estimated Paint and Glazing Repair Budget Price for 9730 \$165,000.00

**( Add (11) New Windows Budget to Paint & Glazing Repair \$19,000.00)**

**(5) Fixed Windows Paint and Glazing Budget Price with interior storm for Common Areas for \$10,000.00 (For Replacement & Repair Budgets)**

Budget Price includes material, tax on material, labor (non-union, non-prevailing wage), employment cost, insurance, staging, shop drawings and supervision.

Note: Abatement and Haz-mat disposal cost has not been included since no environmental report has not been provided.

**Lead Times:**

**Shop Drawings: allow 3 to 4 weeks from date of Letter of Intent or Signed Contract  
Manufacturing; allow 10 to 12 weeks from approved Shop Drawings for new window  
product.**

**Repair and Painting can only be done in appropriate weather conditions, found  
typically from early April thru late October.**

**See attachments supporting this review.**

**Sincerely,**

\_\_\_\_\_MKS\_\_\_\_\_

Michael K. Shields

President

BlackBerry Systems, Inc.

\_\_\_9/27/21\_\_\_\_\_

Date

**Photos of Typical Wood Double Hung Windows 9710 Outer  
Drive**



**WINDOW #17 FULL VIEW/ EXTERIOR**





**WINDOW #17 SPLIT SILL / BOTTOM SASH RAIL**



**WINDOW #H3 FULL VIEW / EXTERIOR**



**WINDOW #H3 ROTTED SILL**





**WINDOW #E3 FULL VIEW / EXTERIOR**



**WINDOW #E3 SPLIT SILL**



**TYPICAL SILL**



**TYPICAL MEETING RAIL**





**WINDOW #H4 INTERIOR SILL AND MULLION**



**WINDOW #H4 INTERIOR VIEW INTERIOR MULLION**



**Photos of Typical Steel Double Hung Windows 9710 and 9730**  
**Outer Drive**



**WINDOW #P5 EXTERIOR VIEW**



**WINDOW #P5 EXTERIOR CORNER VIEW**



**WINDOW #W2 EXTERIOR VIEW**



**WINDOW # U19 INTERIOR VIEW**






**WINDOW #U19 INTERIOR JAMB TRACK TYPICAL**



**WINDOW #U19 INTERIOR RUSTED BALANCE TAPE TYPICAL**



**WINDOW SHCEDULE**

| WINDOW TYPE | DESCRIPTION | WINDOW SIZE | DETAILS | REMARKS |
|-------------|-------------|-------------|---------|---------|
| A1          | 6/1         | 37" X 63"   |         |         |
| B1          | (2) 6/1     | 73" X 63"   |         |         |
| C1          | 6/1         | 37" X 49"   |         |         |
| D1          | 6/1         | 33" X 49"   |         |         |
| D2          | 1/1         | 33" X 49"   |         |         |
| E1          | 6/1         | 38" X 55"   |         |         |
| E2          | 1/1         | 38" X 55"   |         |         |
| F1          | 6/1         | 38" X 49"   |         |         |
| F2          | 1/1         | 38" X 49"   |         |         |
| G1          | 1/1         | 29" X 41"   |         |         |
| H1          | (2)1/1      | 60" X 49"   |         |         |
| I1          | (2)1/1      | 61" X 63"   |         |         |
| J1          | 1/1         | 31" X 63"   |         |         |
| K1          | (2)6/1      | 52" X 63"   |         |         |
| L1          | (2)1/1      | 52" X 49"   |         |         |
| M1          | 6/1         | 33" X 57"   |         |         |
| M2          | 1/1         | 33" X 57"   |         |         |
| N1          | 6/1         | 33" X 65"   |         |         |
| N2          | 1/1         | 33" X 65"   |         |         |
| O1          | (2)6/1      | 76" X 57"   |         |         |
| P1          | (2)6/1      | 76" X 65"   |         |         |
| P2          | (2)1/1      | 76" X 65"   |         |         |
| Q1          | 8/1         | 41" X 57"   |         |         |
| Q2          | 1/1         | 41" X 57"   |         |         |
| R1          | 8/1         | 41" X 65"   |         |         |
| R2          | 1/1         | 41" X 65"   |         |         |
| T1          | 6/1         | 37" X 41"   |         |         |
| T2          | 1/1         | 37" X 41"   |         |         |
| U1          | 4/1         | 25" X 41"   |         |         |
| U2          | 1/1         | 25" X 41"   |         |         |
| V1          | 6/1         | 29" X 64"   |         |         |
| W1          | 6/1         | 29" X 57"   |         |         |
| X1          | 4/1         | 24" X 64"   |         |         |
| Y1          | (2)1/1      | 60" X 57"   |         |         |
| Z1          | (2)1/1      | 60" X 65"   |         |         |
| S1          | -           | VIF         |         |         |
| S2          | -           | VIF         |         |         |
| S3          | -           | VIF         |         |         |
| S4          | -           | VIF         |         |         |
| S5          | -           | VIF         |         |         |
| S6          | -           | VIF         |         |         |
| S6          | -           | VIF         |         |         |

**GENERAL NOTES**

- WINDOW SIZES SHOWN ON ELEVATIONS AND IN THE WINDOW SCHEDULE ARE APPROXIMATE. ROUGH WINDOW OPENINGS MAY VERIFY IN FIELD. VERIFY ALL WINDOW SIZES IN FIELD PRIOR TO WINDOW FABRICATION AND INSTALLATION.
- ALL TYPICAL WINDOWS ARE DOUBLE HUNG EXCEPT "S" SERIES OR IF OTHERWISE NOTED

**REMARKS**

**Grandmont Rosedale  
Park Collective II**

9710 - 9730 W Outer  
Dr. Detroit, MI 48223



**OWNER**  
GRPC 4 Limited Dividend Housing Association  
Limited Partnership, a Michigan limited partnership  
19800 Grand River  
Detroit, MI 48223  
313-387-4732 phone  
313-387-5158 fax  
www.grandmontrosedale.com

**ARCHITECT**  
INTOTO STUDIO LLC  
6505 Woodward Ave  
Suite 200  
Detroit, MI 48202  
313-395-5030 phone  
www.intotostudio.com

**CIVIL ENGINEERING**  
PEA GROUP  
45 W. Grand River Ave.  
Suite 501  
Detroit, MI 48226  
313-769-5770 phone  
www.peagroup.com

**MEP ENGINEERING**  
MA ENGINEERING  
400 S. Old Woodward Ave  
Suite 100  
Birmingham, MI 48009  
248-258-1610 phone  
www.ma-engineering.com

**STRUCTURAL ENGINEERING**  
RESURGET ENGINEERING  
4219 Woodward Ave.  
Suite 306  
Detroit, MI 48201  
313-315-3290 phone  
www.resurget-engineering.com

Key Plan

Registration Seal

**NOT FOR  
CONSTRUCTION**

| No. | Date       | Description        |
|-----|------------|--------------------|
| 1   | 07/07/2021 | Schematic Design   |
| 2   | 08/11/2021 | Design Development |

Project Number: 20.005.02  
Drawn By: Author      Approved By: Checker

Scale:      As indicated

Drawing Title  
**WINDOW TYPES &  
SCHEDULE**  
Drawing No:

**A4.0.1**



### Window Summary 9710 W. Outer Dr

| Eleavations     | Window | Material | Type | Glass      | Frame | Sash  | Sill  | Sash Trim | Exterior Finish | Interior Finish | Lock  | G. Compound | Storm        | Other          |
|-----------------|--------|----------|------|------------|-------|-------|-------|-----------|-----------------|-----------------|-------|-------------|--------------|----------------|
| North Elevation | C1     | Wood     | DH   | 1PC Broke  | Fair  | Fair  | Poor  | Good      | Poor            | Good            | Good  | Poor        | Yes          | Broken Glass   |
|                 | C2     | Wood     | DH   | OK         | Fair  | Fair  | Split | Good      | Poor            | Good            | Good  | Poor        | Yes          |                |
|                 | C3     | Steel    | DH   | OK         | Fair  | Fair  | Fair  | N/A       | Poor            | Fair            | Fair  | Poor        | Yes          | Broken Glass   |
|                 | C4     | Wood     | DH-2 | OK         | Fair  | Fair  | Fair  | Good      | Poor            | Good            | Good  | Poor        | Yes          |                |
|                 | C5     | Wood     | DH-2 | Ok         | Fair  | Fair  | Split | Good      | Poor            | Good            | Good  | Poor        | Yes          |                |
|                 | C6     | steel    | DH   | Ok         | Fair  | Fair  | Poor  | Good      | Poor            | Fair            | Fair  | Poor        | Yes          |                |
|                 | C7     | Wood     | DH   | Ok         | Fair  | Fair  | Fair  | Fair      | Good            | Poor            | Good  | Poor        | Yes          |                |
|                 | B1     | Wood     | DH   | Ok         | Fair  | Fair  | Fair  | Fair      | Good            | Poor            | Good  | Poor        | Yes          |                |
|                 | B2     | Wood     | DH   | Ok         | Fair  | Fair  | Fair  | Good      | Poor            | Good            | Good  | Poor        | Yes          |                |
|                 | B3     | steel    | DH   | Ok         | Fair  | Fair  | Fair  | N/A       | Fair            | Poor            | Poor  | Fair        | Yes          | Broken Balance |
|                 | B4     | Wood     | DH-2 | Ok         | Fair  | Fair  | Poor  | Good      | Poor            | Good            | Good  | Poor        | Yes          |                |
|                 | B5     | Wood     | DH-2 | Ok         | Fair  | Fair  | Poor  | Good      | Poor            | Good            | Good  | Poor        | Yes          |                |
|                 | B6     | steel    | DH   | Ok         | Fair  | Fair  | Fair  | N/A       | Fair            | Good            | Good  | Fair        | Yes          |                |
|                 | B7     | Wood     | DH   | Ok         | Fair  | Fair  | Poor  | Good      | Poor            | Good            | Good  | Poor        | Yes          | Badly Rotted   |
|                 | A1     | steel    | DH   | Ok         | Fair  | Poor  | Fair  | N/A       | Poor            | Poor            | Fair  | Poor        | Yes          |                |
|                 | A2     | steel    | DH   | Ok         | Fair  | Poor  | Fair  | N/A       | Poor            | Poor            | Fair  | Poor        | Yes          |                |
|                 | A3     | steel    | DH   | Ok         | Poor  | Poor  | Fair  | N/A       | Poor            | Poor            | Fair  | Poor        | Yes          |                |
| A4              | steel  | DH-2     | Ok   | Fair       | Poor  | Poor  | N/A   | Poor      | Poor            | Fair            | Poor  | Yes         | Broken Glass |                |
| A5              | steel  | DH-2     | Ok   | 1 PC Broke | Poor  | Poor  | Poor  | N/A       | Poor            | Poor            | Fair  | Poor        | Yes          | Broken Glass   |
| A6              | steel  | DH       | Ok   | Poor       | Poor  | Poor  | Poor  | N/A       | Poor            | Poor            | Poor  | Poor        | Yes          | Broken Glass   |
| A7              | steel  | DH       | Ok   | Poor       | Poor  | Poor  | Poor  | N/A       | Poor            | Poor            | Poor  | Poor        | Yes          |                |
| West Elevation  | F1     | Wood     | DH   | Ok         | Poor  | Poor  | Poor  | Good      | Poor            | Poor            | Poor  | Poor        | Yes          |                |
|                 | F2     | Wood     | DH-2 | Ok         | Poor  | Poor  | Split | Good      | Poor            | Good            | Broke | Poor        | Yes          |                |
|                 | F3     | steel    | FIX  | Ok         | Fair  | Fair  | Fair  | N/A       | Fair            | Fair            | N/A   | Poor        | Yes          | Broken Glass   |
|                 | F4     | Wood     | DH-2 | Ok         | Fair  | Fair  | Poor  | Good      | Poor            | Good            | Good  | Poor        | Yes          |                |
|                 | F5     | Wood     | DH   | Ok         | Fair  | Fair  | Poor  | Good      | Poor            | Good            | Good  | Poor        | Yes          |                |
|                 | E1     | Wood     | DH   | Ok         | Fair  | Fair  | Poor  | Good      | Poor            | Good            | Good  | Poor        | Yes          | Broke Balancer |
|                 | E2     | Wood     | DH-2 | Ok         | Fair  | Fair  | Fair  | Good      | Poor            | Good            | Good  | Poor        | Yes          |                |
|                 | E3     | Wood     | DH-2 | Ok         | Fair  | Fair  | Poor  | Good      | Poor            | Good            | Good  | Poor        | Yes          |                |
|                 | E4     | Wood     | DH   | Ok         | Fair  | Fair  | Poor  | Good      | Poor            | Good            | Good  | Poor        | Yes          |                |
|                 | D1     | steel    | DH   | Ok         | Poor  | Poor  | Poor  | N/A       | Poor            | Poor            | Poor  | Poor        | Yes          |                |
| South Elevation | I1     | Wood     | DH   | Ok         | Poor  | Poor  | Poor  | Good      | Poor            | Good            | Good  | Poor        | Yes          |                |
|                 | I2     | steel    | DH   | Ok         | Poor  | Fair  | Poor  | N/A       | Poor            | Fair            | Poor  | Poor        | Yes          |                |
|                 | I3     | Wood     | DH-2 | Ok         | Poor  | Poor  | Poor  | Good      | Poor            | Good            | Good  | Poor        | Yes          |                |
|                 | I4     | Wood     | DH-2 | Ok         | Poor  | Poor  | Poor  | Good      | Poor            | Good            | Good  | Poor        | Yes          |                |
|                 | I5     | steel    | DH   | Ok         | Poor  | Fair  | Fair  | N/A       | Poor            | Fair            | Good  | Poor        | Yes          | Broken Glass   |
|                 | I6     | Wood     | DH   | Ok         | Poor  | Fair  | Poor  | Good      | Poor            | Good            | Good  | Poor        | Yes          |                |
|                 | I7     | Wood     | DH   | Ok         | Fair  | Fair  | Poor  | Good      | Poor            | Good            | Good  | Poor        | Yes          |                |
|                 | H1     | Wood     | DH   | Ok         | Fair  | Fair  | Fair  | Good      | Poor            | Good            | Good  | Poor        | Yes          |                |
|                 | H2     | steel    | DH   | Ok         | Fair  | Fair  | Poor  | N/A       | Poor            | Fair            | Poor  | Poor        | Yes          |                |
|                 | H3     | Wood     | DH   | Ok         | Fair  | Fair  | Fair  | Good      | Poor            | Good            | Good  | Poor        | Yes          | Badly Rotted   |
| H4              | Wood   | DH-2     | Ok   | Poor       | Poor  | Split | Good  | Poor      | Good            | Good            | Poor  | Yes         |              |                |

\*WINDOW TYPES HIGHLIGHTED IN LIGHT BLUE TO BE REPAIRED AND REMAIN FIXED; THESE WINDOWS OCCUR ONLY IN COMMON AREA STAIRWELLS

\*\*WINDOWS HIGHLIGHTED IN YELLOW EXHIBIT EXHIBIT COMPONENTS IN POOR, BROKEN, AND/OR MISSING CONDITION

|                 |    |       |      |        |      |      |       |      |      |      |      |      |     |                |
|-----------------|----|-------|------|--------|------|------|-------|------|------|------|------|------|-----|----------------|
|                 | H5 | Steel | DH   | Ok     | Poor | Fair | Fair  | N/A  | Fair | Fair | Poor | Poor | Yes |                |
|                 | H6 | Wood  | DH   | Ok     | Poor | Poor | Split | Good | Poor | Good | Good | Poor | Yes |                |
| South Elevation | H7 | Wood  | DH   | Ok     | Poor | Poor | Split | Good | Poor | Good | Good | Poor | Yes |                |
|                 | G1 | Steel | DH-2 | Ok     | Fair | Fair | Fair  | N/A  | Fair | Poor | Poor | Poor | Yes |                |
|                 | G2 | Steel | DH   | Ok     | Fair | Fair | Fair  | N/A  | Poor | Poor | Poor | Poor | Yes |                |
|                 | G3 | Steel | DH   | Ok     | Poor | Poor | Poor  | N/A  | Poor | Poor | Poor | Poor | Yes |                |
|                 | G4 | Steel | DH   | Ok     | Poor | Poor | Poor  | N/A  | Poor | Poor | Poor | Poor | Yes |                |
| East Elevation  | L1 | Wood  | DH   | Ok     | Poor | Poor | Poor  | Good | Poor | Good | Good | Poor | Yes |                |
|                 | L2 | Wood  | DH-2 | Ok     | Poor | Poor | Poor  | Good | Poor | Good | Good | Poor | Yes |                |
|                 | L3 | Steel | FX   | Ok     | Fair | Fair | Poor  | N/A  | Poor | Poor | Poor | Poor | Yes | Broken Glass   |
|                 | L4 | Steel | FX   | Ok     | Fair | Fair | Poor  | N/A  | Poor | Poor | Poor | Poor | Yes |                |
|                 | L5 | Steel | FX   | Ok     | Fair | Fair | Fair  | N/A  | Poor | Poor | Poor | Poor | Yes |                |
|                 | L6 | Wood  | DH-2 | Ok     | Fair | Fair | Fair  | Good | Poor | Good | Good | Poor | Yes |                |
|                 | L7 | Wood  | DH   | Ok     | Poor | Poor | Fair  | Good | Poor | Good | Good | Poor | Yes |                |
|                 | K1 | Wood  | DH   | Ok     | Poor | Poor | Split | Good | Poor | Good | Good | Poor | Yes |                |
|                 | K2 | Wood  | DH-2 | Ok     | Poor | Poor | Fair  | Good | Poor | Good | Good | Poor | Yes |                |
|                 | K3 | Wood  | Door | Ok     | Fair | Fair | N/A   | N/A  | Poor | Fair | Good | Fair | Yes |                |
|                 | K4 | Wood  | DH-2 | Ok     | Fair | Fair | Fair  | Good | Poor | Good | Good | Poor | Yes |                |
|                 | K5 | Wood  | DH   | Broken | Fair | Fair | Fair  | Good | Poor | Good | Good | Poor | Yes | Broken Glass   |
|                 | J1 | Steel | DH   | Ok     | Fair | Fair | Fair  | N/A  | Poor | Poor | Poor | Poor | Yes |                |
|                 | J2 | Steel | DH   | Ok     | Fair | Fair | Fair  | N/A  | Poor | Poor | Poor | Poor | Yes |                |
|                 | J3 | Steel | DH   | Ok     | Poor | Poor | Poor  | N/A  | Poor | Poor | Poor | Poor | Yes |                |
|                 | J4 | Steel | DH   | Ok     | Poor | Poor | Poor  | N/A  | Poor | Poor | Poor | Poor | Yes | Badly Corroded |
|                 | J5 | Steel | DH   | Ok     | Fair | Fair | Fair  | N/A  | Poor | Poor | Poor | Poor | Yes | Badly Corroded |
|                 | J6 | Steel | DH   | Ok     | Fair | Fair | Fair  | N/A  | Poor | Poor | Poor | Poor | Yes |                |
|                 |    |       |      |        |      |      |       |      |      |      |      |      |     |                |
|                 |    |       |      |        |      |      |       |      |      |      |      |      |     |                |
|                 |    |       |      |        |      |      |       |      |      |      |      |      |     |                |
|                 |    |       |      |        |      |      |       |      |      |      |      |      |     |                |
|                 |    |       |      |        |      |      |       |      |      |      |      |      |     |                |
|                 |    |       |      |        |      |      |       |      |      |      |      |      |     |                |

\*WINDOW TYPES HIGHLIGHTED IN LIGHT BLUE TO BE REPAIRED AND REMAIN FIXED; THESE WINDOWS OCCUR ONLY IN COMMON AREA STAIRWELLS

\*\*WINDOWS HIGHLIGHTED IN YELLOW EXHIBIT EXHIBIT COMPONENTS IN POOR, BROKEN, AND/OR MISSING CONDITION



### Window Summary 9730 W. Outer Dr

| Eleavations     | Window | Material | Type | Glass  | Frame | Sash | Sill | Sash Trim | Exterior Finish | Interior Finish | Lock | G. Compound | Storm | Other          |
|-----------------|--------|----------|------|--------|-------|------|------|-----------|-----------------|-----------------|------|-------------|-------|----------------|
| South Elevation | O1     | Steel    | DH   | OK     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |
|                 | O2     | Steel    | DH   | OK     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |
|                 | O3     | Steel    | DH-2 | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |
|                 | O4     | Steel    | DH   | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |
|                 | O5     | Steel    | DH-2 | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |
|                 | O6     | Steel    | DH   | Ok     | Poor  | Poor | Poor | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |
|                 | O7     | Steel    | DH   | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   | Badly Corroded |
|                 | N1     | Steel    | DH   | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |
|                 | N2     | Steel    | DH   | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |
|                 | N3     | Steel    | DH-2 | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |
|                 | N4     | Steel    | DH   | Ok     | Poor  | Poor | Poor | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |
|                 | N5     | Steel    | DH-2 | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |
|                 | N6     | Steel    | DH   | Broken | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   | Badly Corroded |
|                 | N7     | Steel    | DH   | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |
|                 | M1     | Steel    | DH   | Ok     | Poor  | Poor | Poor | N/A       | Poor            | Fair            | Poor | Poor        | Yes   | Badly Corroded |
|                 | M2     | Steel    | DH   | Ok     | Poor  | Poor | Poor | N/A       | Poor            | Fair            | Poor | Poor        | Yes   | Badly Corroded |
|                 | M3     | Steel    | DH-2 | Ok     | Poor  | Poor | Poor | N/A       | Poor            | Fair            | Poor | Poor        | Yes   | Badly Corroded |
|                 | M4     | Steel    | DH   | Ok     | Poor  | Poor | Poor | N/A       | Poor            | Fair            | Poor | Poor        | Yes   | Badly Corroded |
|                 | M5     | Steel    | DH-2 | Ok     | Poor  | Poor | Poor | N/A       | Poor            | Fair            | Poor | Poor        | Yes   | Badly Corroded |
|                 | M6     | Steel    | DH   | Ok     | Poor  | Poor | Poor | N/A       | Poor            | Fair            | Poor | Poor        | Yes   | Badly Corroded |
|                 | M7     | Steel    | DH   | Ok     | Poor  | Poor | Poor | N/A       | Poor            | Fair            | Poor | Poor        | Yes   | Badly Corroded |
| North Elevation | R1     | Steel    | DH   | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |
|                 | R2     | Steel    | DH   | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |
|                 | R3     | Steel    | DH-2 | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |
|                 | R4     | Steel    | DH   | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |
|                 | R5     | Steel    | DH-2 | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |
|                 | R6     | Steel    | DH   | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   | Broken Glass   |
|                 | R7     | Steel    | DH   | Ok     | Poor  | Poor | Poor | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |
|                 | Q1     | Steel    | DH   | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   | Badly Corroded |
|                 | Q2     | Steel    | DH   | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |
|                 | Q3     | Steel    | DH-2 | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   | Badly Corroded |
| North Elevation | Q4     | Steel    | DH   | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   | Badly Corroded |
|                 | Q5     | Steel    | DH-2 | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |
|                 | Q6     | Steel    | DH   | Ok     | Poor  | Poor | Fair | N/A       | Poor            | Fair            | Poor | Poor        | Yes   |                |

\*WINDOW TYPES HIGHLIGHTED IN LIGHT BLUE TO BE REPAIRED AND REMAIN FIXED; THESE WINDOWS OCCUR ONLY IN COMMON AREA STAIRWELLS

\*\*WINDOWS HIGHLIGHTED IN YELLOW EXHIBIT EXHIBIT COMPONENTS IN POOR, BROKEN, AND/OR MISSING CONDITION

|                                   |     |       |      |        |      |      |      |      |      |      |         |      |     |                |
|-----------------------------------|-----|-------|------|--------|------|------|------|------|------|------|---------|------|-----|----------------|
|                                   | Q7  | Steel | DH   | Ok     | Poor | Poor | Fair | N/A  | Poor | Fair | Poor    | Poor | Yes |                |
|                                   | P1  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A  | Poor | Poor | Poor    | Poor | Yes | Badly Corroded |
|                                   | P2  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A  | Poor | Poor | Poor    | Poor | Yes | Badly Corroded |
|                                   | P3  | Steel | DH-2 | Ok     | Poor | Poor | Poor | N/A  | Poor | Poor | Poor    | Poor | Yes | Badly Corroded |
|                                   | P4  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A  | Poor | Poor | Poor    | Poor | Yes | Badly Corroded |
|                                   | P5  | Steel | DH-2 | Ok     | Poor | Poor | Poor | N/A  | Poor | Poor | Poor    | Poor | Yes | Badly Corroded |
|                                   | P6  | Steel | DH   | Ok     | Fair | Fair | Poor | N/A  | Poor | Poor | Poor    | Poor | Yes | Badly Corroded |
|                                   | P7  | Steel | DH   | Ok     | Fair | Fair | Poor | N/A  | Poor | Poor | Poor    | Poor | Yes | Badly Corroded |
| <b>South Courtyard Elevation</b>  | U5  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A  | Poor | Fair | Poor    | Poor | Yes |                |
|                                   | U6  | Steel | DH   | Ok     | Fair | Fair | Fair | N/A  | Poor | Fair | Poor    | Poor | Yes |                |
|                                   | U7  | Steel | DH   | Ok     | Fair | Fair | Fair | N/A  | Poor | Fair | Poor    | Poor | Yes | Badly Corroded |
|                                   | T5  | Steel | DH   | Ok     | Fair | Fair | Fair | N/A  | Poor | Fair | Poor    | Poor | Yes | Broken Glass   |
|                                   | T6  | Steel | DH   | Ok     | Fair | Fair | Fair | N/A  | Poor | Fair | Poor    | Poor | Yes |                |
|                                   | T7  | Steel | DH   | Broken | Fair | Fair | Fair | N/A  | Poor | Fair | Poor    | Poor | Yes |                |
|                                   | S5  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A  | Poor | Poor | Poor    | Poor | Yes | Badly Corroded |
|                                   | S6  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A  | Poor | Poor | Poor    | Poor | Yes | Badly Corroded |
|                                   | S7  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A  | Poor | Poor | Poor    | Poor | Yes | Badly Corroded |
| <b>North Courtyard Elevations</b> | U13 | Steel | DH   | Ok     | Fair | Fair | Fair | N/A  | Poor | Fair | Poor    | Poor | Yes |                |
|                                   | U14 | Steel | DH   | Ok     | Fair | Fair | Fair | N/A  | Poor | Fair | Poor    | Poor | Yes |                |
|                                   | U15 | Steel | DH   | Ok     | Fair | Fair | Fair | N/A  | Poor | Fair | Poor    | Poor | Yes |                |
|                                   | T12 | Steel | DH   | Broken | Fair | Fair | Fair | N/A  | Poor | Poor | Missing | Poor | Yes |                |
|                                   | T13 | Steel | DH   | Ok     | Fair | Fair | Fair | N/A  | Poor | Poor | Poor    | Poor | Yes |                |
|                                   | T14 | Steel | DH   | Ok     | Fair | Fair | Fair | N/A  | Poor | Fair | Poor    | Poor | Yes |                |
|                                   | S12 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A  | Poor | Poor | Poor    | Poor | Yes |                |
|                                   | S13 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A  | Poor | Poor | Poor    | Poor | Yes |                |
|                                   | S14 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A  | Poor | Poor | Poor    | Poor | Yes |                |
| <b>East Elevation</b>             | U1  | Steel | DH   | Ok     | Fair | Fair | Fair | N/A  | Poor | Fair | Poor    | Poor | Yes |                |
|                                   | U2  | Steel | DH-2 | Ok     | Fair | Fair | Fair | N/A  | Poor | Fair | Poor    | Poor | Yes |                |
| <b>East Elevation</b>             | U3  | Steel | DH-2 | Ok     | Poor | Poor | Poor | N/A  | Poor | Fair | Poor    | Poor | Yes | Broken Glass   |
|                                   | U4  | Steel | DH-2 | Ok     | Poor | Poor | Poor | N/A  | Poor | Fair | Poor    | Poor | Yes |                |
|                                   | U8  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A  | Poor | Fair | Poor    | Poor | Yes |                |
|                                   | U9  | Steel | FX   | Ok     | Poor | Poor | Fair | N/A  | Poor | Poor | Poor    | Poor | Yes |                |
|                                   | U10 | Wood  | DH   | Ok     | Good | Good | Good | Good | Fair | Fair | Good    | Fair | Yes |                |
|                                   | U11 | Steel | DH-2 | Ok     | Poor | Good | Fair | N/A  | Poor | Fair | Poor    | Poor | Yes |                |
|                                   | U12 | Steel | DH   | Ok     | Poor | Good | Fair |      | Poor | Fair | Poor    | Poor | Yes |                |
|                                   | U13 | Steel | DH   | Ok     | Poor | Good | Fair | N/A  | Poor | Fair | Missing | Poor | Yes |                |

\*WINDOW TYPES HIGHLIGHTED IN LIGHT BLUE TO BE REPAIRED AND REMAIN FIXED; THESE WINDOWS OCCUR ONLY IN COMMON AREA STAIRWELLS

\*\*WINDOWS HIGHLIGHTED IN YELLOW EXHIBIT EXHIBIT COMPONENTS IN POOR, BROKEN, AND/OR MISSING CONDITION



|                       |     |       |      |        |      |      |      |     |      |      |      |      |     |                    |
|-----------------------|-----|-------|------|--------|------|------|------|-----|------|------|------|------|-----|--------------------|
|                       | U14 | Steel | DH   | Ok     | Poor | Good | Fair | N/A | Poor | Fair | Poor | Poor | Yes |                    |
|                       | U15 | Steel | DH   | Ok     | Poor | Good | Fair | N/A | Poor | Fair | Poor | Poor | Yes |                    |
|                       | U16 | Steel | DH   | Ok     | Poor | Good | Fair | N/A | Poor | Fair | Poor | Poor | Yes |                    |
|                       | U17 | Steel | DH-2 | Ok     | Poor | Good | Fair | N/A | Poor | Fair | Poor | Poor | Yes |                    |
|                       | U18 | Steel | DH-2 | Ok     | Poor | Good | Fair | N/A | Poor | Fair | Poor | Poor | Yes |                    |
|                       | U19 | Steel | DH   | Ok     | Poor | Good | Poor | N/A | Poor | Fair | Poor | Poor | Yes |                    |
|                       | T1  | Steel | DH   | Ok     | Poor | Good | Poor | N/A | Poor | Fair | Poor | Poor | Yes |                    |
|                       | T2  | Steel | DH-2 | Ok     | Poor | Good | Fair | N/A | Poor | Fair | Poor | Poor | Yes |                    |
|                       | T3  | Steel | DH-2 | Ok     | Poor | Good | Poor | N/A | Poor | Fair | Poor | Poor | Yes |                    |
|                       | T4  | Steel | DH   | Ok     | Poor | Good | Poor | N/A | Poor | Fair | Poor | Poor | Yes |                    |
|                       | T8  | Steel | DH   | Ok     | Poor | Good | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                    |
|                       | T9  | Steel | DH   | Ok     | Poor | Good | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                    |
|                       | T10 | Steel | DH-2 | Broken | Poor | Good | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Broken Glass       |
|                       | T11 | Steel | DH   | Ok     | Poor | Good | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded     |
|                       | T12 | Steel |      | Broken | Poor | Good | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                    |
|                       | T13 | Steel |      | Broken | Poor | Good | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                    |
|                       | T14 | Steel |      | Broken | Poor | Good | Fair | N/A | Poor | Poor | Poor | Poor | Yes | Broken Glass       |
|                       | T15 | Steel |      | Broken | Poor | Good | Fair | N/A | Poor | Poor | Poor | Poor | Yes | Missing Hardware   |
|                       | T16 | Steel |      | Broken | Poor | Good | Poor | N/A | Poor | Fair | Poor | Poor | Yes | Broken Glass       |
|                       | T17 | Steel |      | Broken | Poor | Good | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Broken Glass       |
|                       | T18 | Steel |      | Broken | Poor | Good | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                    |
|                       | S1  | Steel |      | Broken | Poor | Good | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Broken Glass       |
|                       | S2  | Steel |      | Ok     | Poor | Good | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded     |
| <b>East Elevation</b> | S3  | Steel | DH-2 | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded     |
|                       | S4  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Water Infiltration |
|                       | S8  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded     |
|                       | S9  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded     |
|                       | S10 | Steel | DH-2 | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded     |
|                       | S11 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Broken Glass       |
|                       | S12 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded     |
|                       | S13 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded     |
|                       | S14 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded     |
|                       | S15 | Steel | DH   | Broken | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded     |
|                       | S16 | Steel | DH-2 | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded     |
|                       | S17 | Steel | DH-2 | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Broken Glass       |
|                       | S18 | Steel | DH   | Broken | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Broken Glass       |

\*WINDOW TYPES HIGHLIGHTED IN LIGHT BLUE TO BE REPAIRED AND REMAIN FIXED; THESE WINDOWS OCCUR ONLY IN COMMON AREA STAIRWELLS

\*\*WINDOWS HIGHLIGHTED IN YELLOW EXHIBIT EXHIBIT COMPONENTS IN POOR, BROKEN, AND/OR MISSING CONDITION

|                |     |       |      |        |      |      |      |     |      |      |      |      |     |                             |
|----------------|-----|-------|------|--------|------|------|------|-----|------|------|------|------|-----|-----------------------------|
| West Elevation | X1  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | X2  | Steel | DH-2 | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Tape Broken                 |
|                | X3  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | X4  | Steel | FX   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | X5  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | X6  | Steel | DH-2 | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | X7  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | X8  | Steel | DH-2 | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | X9  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | X10 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | X11 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | X12 | Steel | DH-2 | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Tape Broken                 |
|                | X13 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | W1  | Steel | DH   | Broken | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Broken Glass                |
|                | W2  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | No  |                             |
|                | W3  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | W4  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | W5  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Missing Balance Tape Broken |
| West Elevation | W6  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | W7  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | W8  | Steel | DH-2 | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | W9  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Broken Glass                |
|                | W10 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Missing part sash           |
|                | W11 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | W12 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | W13 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | W14 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | W15 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | No  | Badly Corroded              |
|                | W16 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | W17 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | W18 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | W19 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | W20 | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes |                             |
|                | V1  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded              |
|                | V2  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded              |
|                | V3  | Steel | DH   | Ok     | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded              |

\*WINDOW TYPES HIGHLIGHTED IN LIGHT BLUE TO BE REPAIRED AND REMAIN FIXED; THESE WINDOWS OCCUR ONLY IN COMMON AREA STAIRWELLS

\*\*WINDOWS HIGHLIGHTED IN YELLOW EXHIBIT EXHIBIT COMPONENTS IN POOR, BROKEN, AND/OR MISSING CONDITION



|  |     |       |    |    |      |      |      |     |      |      |      |      |     |                |
|--|-----|-------|----|----|------|------|------|-----|------|------|------|------|-----|----------------|
|  | V4  | Steel | DH | Ok | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded |
|  | V5  | Steel | DH | Ok | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded |
|  | V6  | Steel | DH | Ok | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded |
|  | V7  | Steel | DH | Ok | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded |
|  | V8  | Steel | DH | Ok | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded |
|  | V9  | Steel | DH | Ok | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Broken Glass   |
|  | V10 | Steel | DH | Ok | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded |
|  | V11 | Steel | DH | Ok | Poor | Poor | Poor | N/A | Poor | Poor | Poor | Poor | Yes | Badly Corroded |
|  |     |       |    |    |      |      |      |     |      |      |      |      |     |                |
|  |     |       |    |    |      |      |      |     |      |      |      |      |     |                |
|  |     |       |    |    |      |      |      |     |      |      |      |      |     |                |

\*WINDOW TYPES HIGHLIGHTED IN LIGHT BLUE TO BE REPAIRED AND REMAIN FIXED; THESE WINDOWS OCCUR ONLY IN COMMON AREA STAIRWELLS


\*\*WINDOWS HIGHLIGHTED IN YELLOW EXHIBIT EXHIBIT COMPONENTS IN POOR, BROKEN, AND/OR MISSING CONDITION

OUTER DRIVE

FIELD SKETCH

Subject: 9710 Wood DH

Date: 7/24/21







OUTER DRIVE

Field SKETCH

Subject: 9710 Wood DH

Date: 7/24/21

HEAD DETAIL




Outer Drive

Field Sketch

Subject: 9710 Wood DH

Date: 7/24/21

Sill Detail





Outer Drive


Field Sketch

Subject: 9710-9730 STEEL DH

Date: 7/24/21

JAMB Detail

SIMILAR  
HEAD Detail






**Information Sheet**

OUTER DRIVE

FIELD SKETCH




Subject: 9710-9730 STEEL DH Date: 7/24/21

Sill Detail









**NOTICE:**  
 QUAKER DOES NOT SHIP ANY PARTS, SHIMS, JACKS, ETC., OR SEALANTS, UNLESS OTHERWISE NOTED.  
**VERIFY INSTALLATION**  
 VERIFY WALL DETAILS  
**SEALANT INSTALLMENT ON EXCEED**  
 AVOID EXCESSIVE APPLICATION  
 PROVIDE ADEQUATE BLOCKING TO SUPPORT THE SILL OR THE WINDOW  
 MAINTAIN FLANGES AND DRIP CAPS INTEGRAL OR APPLIED TO NOT TAKE THE PLACE OF WINDOW FLASHING OR FINISHES. FLASHING COORDINATION MUST BE PROPERLY MADE WITH THE SEALANT.  
 FLASHING AND SEALANT WITH AN ADHERENT FLASHING AGAINST WATER AND AIR INTRUSION AROUND THE WINDOW FRAME TO PREVENT SOILING OR PROPERTY DAMAGE.  
**VERIFY INSTALLATION**  
 VERIFY WALL DETAILS

|  |   |   |  |
|--|---|---|--|
| <p>PHONE (573)-744-5211<br/>                 FAX (573)-744-5566<br/>                 COMMERCIAL<br/>                 FAX (573)-744-5822<br/>                 alexc@quakerwindows.com</p> | Description: <b>CUT DETAILS</b>               |   | Project Name: <b>OUTER DRIVE<br/>                 COMPARISONS<br/>                 9710 - 9730</b> |
|  | Drawn By: <b>DG</b><br>Checked By: <b>AGN</b> | Scale: <b>3/8"=1"</b><br>Sheet #: <b>C2</b> |  |

# Series 700 Double Hung

CSI Division 08 51 13 - Aluminum Windows

12805 E. 31st St.  
Tulsa, OK 74146  
Phone: (800) 259-7580  
Fax: (918) 665-2197

## Style • Quality • Performance

### Standard Features

- 3 1/4" frame depths available
- 14 standard powder coat colors
- Full range of Anodized and AAMA 2605 finishes available
- Lock-out tilt latches
- Operable sashes tilts in for easy cleaning
- Sealed 7/8" insulated glass for optimum thermal efficiency
- Extruded screen frame
- Carbon Steel spiral sash balances
- High-density pile weatherstripping with mylar fin
- Center camp locks plus hidden security locks

### Performance

- AAMA Rating: CW-PG-30 Size: 56x91
- Air Infiltration (CFM): 0.16
- Water Resistance (PSF): 6.06
- Structural (PSF): 60.15
- STC range: 30-34
- \*U-Factor: .49 / .41
- \*SHGC: .28 / .26
- \*VT: .51 / .47
- CRF: 59 / 56

\*NFRC simulation results from certified testing labs.  
Variety of glazing combinations available.



**The Palace Apartments**  
Tulsa, OK  
Bone White Powder Coat



**Albertville High School**  
Albertville, AL  
Bone White Powder Coat



**Bennett Hall**  
Stillwater, OK  
Creme Powder Coat